

ASS. REC. BY:

REF:

TMI/

CC3/TMI20002846/Ksd3

12

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured: SLQ 3148 G

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMM 3855H

Yr Regn:

06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prous

c.c

1798

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

72393

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FUH0383546

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun

195/65R15

R:

GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

4

mm

L/Bal.

9

mm

L/Bal.

4

mm

D.O.A.

15/2/20

D.O.A.

18/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

&amp; 1st

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 MAR 2020

Date / Time

Action / Instruction

1 Cut injury

SMM 3855H - X

SLQ 3148G - X

4335.58 to Summit

( \$ 4,492.55 Red - 91% )

Finalize with wa. Yin.

Data/Time, File Pass to?

27/03/20

☐

: Prel. Report

1) DATE

☒

: Final Report

Data/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

250

F. &amp; S.

Others

TOTAL

261

Report Format:

Lump Sum / I.B. (\$ 4,335.58 p/p)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 20 February 2020

Our Ref: CC3/TMI20002846/Ksd3

The Motor Claims Department  
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


**PRELIMINARY ADVISE REPORT OF VEHICLE NO. SMM 3855H .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/02/2020 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>45,828.13</u>
Revised Estimate Amount	: S\$ <u>4,335.92</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear & front portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 5 days

Yours faithfully

Kenneth Kong  
Automotive Assessor

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto)  
**Sent:** Thursday, 20 February 2020 2:06 pm  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD,  
DOA: 15/02/2020, SMM 3855H (TP VEHICLE), SLQ 3148G(OI VEHICLE)  
**Attachments:** TP GIA REPORT.pdf, POLICE REPORT.pdf, ESTIMATE.pdf, PRELI ADVISE - SMM  
3855H.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SMM 3855H at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2  
ANG MO KIO ST 63 SINGAPORE 569111 on 18/02/2020 .

Enclosed herewith a copy of TP's GIA, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 27 March 2020 11:17 am  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR; 'claims'  
**Subject:** FW: TCS REF: SMM3855H -- Accident involving SMM 3855H & SLQ 3148G on 15/02/2020  
**Attachments:** ESTIMATE MARKED.pdf

Without prejudice

Dear Shirley

Amount confirmed \$ 4,335.58 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 26 March, 2020 4:00 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** TCS REF: AAD2001-184 -- Accident involving SMM 3855H & SLQ 3148G on 15/02/2020

Dear Wai Yin,

Please confirm final fig \$ 4,335.58 @ 5 days of repairs before GST.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
LKK Auto Consultants Pte Ltd

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	575K
<b>Vehicle Details</b>	
Vehicle No.:	SMM3855H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C54599
Chassis No.:	JTDKB3FUX03083546
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	27 Jun 2019
First Registration Date:	27 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$19,247.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2029
PARF Rebate Amount:	\$14,435.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,102.00
COE Rebate Amount:	\$34,481.00
<b>Total Rebate Amount:</b>	<b>\$48,916.00</b>

The information contained herein is correct as at 17 Feb 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/02/2020 13:13
Date Of Accident	15/02/2020 14:15
Exact Location Of Accident	ALONG ROCHOR RD IN FRONT OF FU LU SHOU COMPLEX
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM3855H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS LEASING PTE LTD
Co Reg No	0
Email Address	CANDY.KONG@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62310998

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994034
Cover Note Number	

### Driver

Name of Driver	THIAN BOON HOONG BENNY
NRIC No	SXXXX353I
Date Of Birth	16/07/1956
Occupation	OUTDOOR
Date Of Driving Pass	31/10/1980
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83338875
Fax Number	
Contact Number	
EMail Address	THIANBENNY@YAHOO.COM

Address	BLK 128B PUNGGOL FIELD WALK #05-355
Postcode	822128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - PRIVATE HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CENTRAL POLICE DIVISIONAL HQ (A DIVISION)
Police Station Address	<b>ROAD:</b> 391 NEW BRIDGE ROAD #03-112 POLICE CANTONMENT COMPLEX BLOCK A , <b>POSTCODE:</b> 088762 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2240000 - <b>FAX NO:</b> 62200877
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please refer to Police Report No. A/20200215/7013.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ3148G
Vehicle Make/Model/Colour	TOYOTA PRIUS
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	



Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLB890U  
Vehicle Make/Model/Colour BMW  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name THIAN BOON HOONG BENNY  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SMM3855H  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 17 FEB 2020

*[Signature]*

Driver's Signature

(If driver is not the policyholder)

Date & Time: 17 FEB 2020

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Deborah Lai

SKETCH PLAN

Handwritten text in the sketch plan area: *pls see attach attachment*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



Handwritten text in the first line of the description area: *pls see attach police report*

**DECLARATION**  
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 17 FEB 2020

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 17 FEB 2020

Reporting Centre Personnel's Signature  
Name: Deborah Lai  
NRIC/FIN No.:



A: SMM3855H  
B: SLQ3L48G  
C: SLB890U

\* Get A copy of GIA report



**SINGAPORE  
POLICE FORCE**



A/20200315/7913

1 of 2

## POLICE REPORT (NP299)

Report No. A/20200215/7013

Police Station Of Origin  
Central Division HQ  
A 391 New Bridge Road #03-112 Police  
Cantonment Complex SINGAPORE 088762  
Tel No:1800-2240000

Date/Time Report Made 15/02/2020 21:42	Vide Report No.		Station Diary No.
Name Of Informant THIAN BOON HOONG BENNY	Address APT BLK 128B PUNGGOL FIELD WALK #05-355 SINGAPORE 822128		
ID Type / ID No. NRIC NO / S1191353I	Contact No. Home/Office:                      Mobile: 83338875		
Nationality SINGAPORE CITIZEN	Email Address thianbenny@yahoo.com		
Occupation Taxi driver	Sex Male	Age 63	Date of Birth 16/07/1956
Institution/School Name	Race Chinese		
Date/Time Of Incident 15/02/2020 14:15	Language English		
	Location Of Incident Along Rochor Rd in front of Fu Lu Shou Complex		

### Brief details.

My vehicle (SMM3855H) was stationary as there's heavy traffic. Suddenly vehicle B (SLQ3148G) hit the rear of my vehicle and the impact push my vehicle forward causing it to hit vehicle C (SLB890U). I have visited the doctor as i am not feeling well after the incident and was given 3 days MC (MC No. EMD202031953)

Subjects Involved	
Victim	
Signature Of Officer Recording The Report:  Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/02/2020 21:42
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



A/20200215/7013

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. A/20200215/7013

Person Name	THIAN BOON HOONG BENNY		
ID Type	NRIC NO	ID No	S1191353I
Gender	Male	Age	63
Race	Chinese	Language	English
Occupation	Taxi driver	Address Type	
Address	APT BLK 128B PUNGGOL FIELD WALK #05-355 SINGAPORE 822128	Mobile No	83338875
Is Informant A Victim?	Yes		
Person Name	THIAN BOON HOONG BENNY (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/02/2020 21:42
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM 3855H**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

18 FEB 2020

**PART**

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 COVER, DECK TRIM, REAR
- 1 COVER, FLOOR UNDER, NO 1
- 1 COVER, FLOOR UNDER, NO 2
- 1 COVER, REAR FLOOR
- 1 PIPE ASSY, EXHAUST, TAIL
- 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH
- 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH

*Not Authonik**Recovery B4 paint**84335-58***SMM 3855H**

JTDKB3FUX03083546

TOYOTA

PRIUS

15.2.2020

**TOKIO MARINE**

27/6/2019

**LIST**

\$	Bu	442.60	✓
\$	Bt	332.70	✓
\$	mt	15.40	✓
\$	Tn	576.30	✓
\$	Sn	116.50	X
\$	Sn	117.70	X
\$	rn	1,147.80	X
\$	cmr	925.60	✓
\$	Sn	372.30	X
\$	rn	650.30	X
\$	Sn	502.00	X
\$	Sn	451.80	X
\$	myorn	123.70	✓
\$	Sn	123.70	X
\$	Sn	502.00	} X
\$	Sn	443.30	
\$	Sn	126.70	
\$	Sn	175.10	
\$	Sn	241.90	
\$	Sn	229.90	} X
\$	rn	1,655.40	
\$	Sn	56.50	
\$	Sn	56.50	} X
\$	Sn	259.20	
\$	Sn	88.50	} X
\$	rn	467.00	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM 3855H**

1	PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	R	139.80	X
1	DUCT ASSY, QUARTER VENT, RH	\$	Sn	67.00	X
1	FRONT BUMPER	\$	mgdii	516.00	2005n
1	REINFORCEMENT, FRONT BUMPER	\$	R	716.60	X
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	Sn	246.10	X
1	ABSORBER, FRONT BUMPER, LOWER	\$	Sn	132.70	X
1	ABSORBER, FRONT BUMPER ENERGY	\$	cm	79.60	
1	FRONT BUMPER SIDE RETAINER RH	\$	Sn	80.10	X
1	FRONT BUMPER SIDE RETAINER LH	\$	Sn	82.30	
1	COVER SUB-ASSY, ENGINE, NO.1	\$	Sn	472.40	
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sn	241.90	
1	FRONT LED LAMP (LOWER) LH	\$	Sn	951.40	
1	FRONT HEADLAMP LH	\$	Sn	2,637.60	
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sn	960.50	
1	FRONT LED LAMP (LOWER) RH	\$	Sn	951.40	X
1	FRONT HEADLAMP RH	\$	Sn	2,637.60	
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	Sn	960.50	
1	GRILLE SUB-ASSY, RADIATOR	\$	cm	346.00	
1	GRILLE, RADIATOR, LOWER NO.1	\$	Sn	170.10	X
1	EMBLEM ASSY, RADIATOR GRILLE	\$	me	90.80	
1	FRONT FENDER RH	\$	R	977.80	X
1	LINER, FRONT FENDER, RH	\$	Sn	206.70	
1	EMBLEM, SIDE PANEL RH	\$	nn	54.60	
1	FRONT FENDER LH	\$	R	977.80	
1	LINER, FRONT FENDER, LH	\$	Sn	202.50	
1	EMBLEM, SIDE PANEL LH	\$	nn	54.60	
1	FRONT BONNET	\$	R	983.10	
1	JAR ASSY, WINDSHIELD WASHER	\$	Sn	219.10	
1	INLET SUB ASSY, WASHER	\$	Sn	67.00	
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	Sn	292.40	
<b>TOTAL</b>		<b>\$</b>		<b>27,587.90</b>	
<b>25%</b>		<b>\$</b>		<b>6,896.98</b>	
		<b>\$</b>		<b>20,690.93</b>	



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM 3855H****Special Nett**

1SET	PARKING AID	\$	<i>Net</i>	700.00	<i>2005m</i>
1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	<i>—</i>
1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	<i>—</i>
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	<i>—</i>
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	<i>—</i>
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	<i>301m</i>
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	<i>301m</i>
1	REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	<i>X</i>
1	REAR WHEEL RIM	\$	<i>na</i>	1,879.40	
1	REAR TYRE 195/65/15	\$	<i>na</i>	350.00	
1	REAR WHEEL RIM COVER	\$	<i>na</i>	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1	REAR LH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1SET	FRNT RH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1SET	FRNT LH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	
1	FRONT FENDER LINER CLIP	\$	<i>na</i>	35.00	
1SET	FRONT BUMPER CLIP	\$	<i>na</i>	66.00	
1	REAR FENDER LINER CLIP	\$	<i>na</i>	35.00	<i>455m</i>
1	REAR NUMBER PLATE WITH HOLDER	\$	<i>na</i>	200.00	
1	FRONT WHEEL RIM	\$	<i>na</i>	1,879.40	
1	FRONT TYRE 195/65/15	\$	<i>na</i>	350.00	
1	FRONT WHEEL RIM COVER	\$	<i>na</i>	211.50	<i>X</i>
1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>Net</i>	200.00	
2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	120.00	
1	WINDSCREEN MOULDING	\$	<i>na</i>	160.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
<b>TOTAL</b>		<b>\$</b>		<b>7,117.20</b>	

**TOTAL PARTS \$ 27,808.13****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *na* 170.00 *X*

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM 3855H**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>8801</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>506</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>5001</i>
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SMM 3855H**

To transfer of Front Fender fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *2ol*

To transfer of Rear Fender fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 18,020.00****Over All Total \$ 45,828.13****(PART-BY-PART) Repair Days***25 Days**5 days*

L&C Auto Consultants hereby notify the Repairer of the following:

- To remove before the spray painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No major modifications to be made
- Supplementary costs must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20002846/KSD3N2  
 Date: 02/04/2020

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000576
Claimant Vehicle No :	SMM3855H	Insured Vehicle No :	SLQ3148G
Date of Loss:	15/02/2020	Nature of Claim:	TP
		Claim No:	M2001276

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMM3855H	Engine No:	22R2C54599
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FUX03083546
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	72393 km
Colour:	Metallic Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,808.12	2,885.57	24,922.55	89.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,020.00	1,450.00	16,570.00	91.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>45,828.12</b>	<b>4,335.57</b>	<b>41,492.55</b>	<b>90.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,207.97</b>	<b>303.49</b>	<b>2,904.48</b>	<b>90.54</b>
<b>Nett Amount (S\$)</b>	<b>49,036.09</b>	<b>4,639.06</b>	<b>44,397.03</b>	<b>90.54</b>

## INSPECTION

Date of Assignment:	20/02/2020	
Date Inspected:	18/02/2020	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: 54,335.58

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
<b>Parts:</b>	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM3855H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Buckled	442.60 FL	-	*442.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	332.70 FL	-	*332.70 FL
3	1		*REAR BUMPER TOWING COVER	Missing	15.40 FL	-	*15.40 FL
4	1		*GUARD,REAR BUMPER,CENTER	Torn	576.30 FL	-	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	-	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	-	*- FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	-	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Cracked	925.60 FL	-	*925.60 FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	-	*- FL
10	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	-	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	-	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	-	*- FL
13	1		*REAR BUMPER SIDE RH	Mtg Cracked	123.70 FL	-	*123.70 FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	-	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	-	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	-	*- FL
17	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
18	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	-	*- FL
19	1		*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	-	*- FL
20	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	-	*- FL
21	1		*PIPE ASSY,EXHAUST,TAIL	Repair	1,655.40 FL	-	*- FL
22	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	-	*- FL
23	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL	-	*- FL
24	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	-	*- FL
25	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	88.50 FL	-	*- FL
26	1		*LOCK ASSY,BACK DOOR,W/COURTESY LAMP SWITCH	Repair	467.00 FL	-	*- FL
27	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	-	*- FL
28	1		*LINER,REAR WHEEL HOUSE,RH	Repair	139.80 FL	-	*- FL
29	1		*DUCT ASSY,QUARTER VENT,RH	Serviceable	67.00 FL	-	*- FL
30	1		*REINFORCEMENT,FRONT BUMPER	Repair	716.60 FL	-	*- FL
31	1		*REINFORCEMENT,FRONT BUMPER,NO 2	Serviceable	246.10 FL	-	*- FL
32	1		*ABSORBER,FRONT BUMPER,LOWER	Serviceable	132.70 FL	-	*- FL
33	1		*ABSORBER,FRONT BUMPER ENERGY	Cracked	79.60 FL	-	*79.60 FL
34	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	80.10 FL	-	*- FL
35	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	82.30 FL	-	*- FL
36	1		*COVER SUB-ASSY,ENGINE,NO 1	Serviceable	472.40 FL	-	*- FL
37	1		*COVER SUB-ASSY,ENGINE UNDER,NO 2	Serviceable	241.90 FL	-	*- FL
38	1		*FRONT LED LAMP (LOWER) LH	Serviceable	951.40 FL	-	*- FL
39	1		*FRONT HEADLAMP LH	Serviceable	2,637.60 FL	-	*- FL
40	1		*COMPUTER SUB-ASSY,HEADLAMP LH NO 1	Serviceable	960.50 FL	-	*- FL
41	1		*FRONT LED LAMP (LOWER) RH	Serviceable	951.40 FL	-	*- FL
42	1		*FRONT HEADLAMP RH	Serviceable	2,637.60 FL	-	*- FL
43	1		*COMPUTER SUB-ASSY,HEADLAMP,RH NO 1	Serviceable	960.50 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
44	1		*GRILLE SUB-ASSY,RADIATOR	Cracked	346.00 FL	-	*346.00 FL
45	1		*GRILLE,RADIATOR,LOWER NO 1	Serviceable	170.10 FL	-	*- FL
46	1		*EMBLEM ASSY,RADIATOR GRILLE	Necessary	90.80 FL	-	*90.80 FL
47	1		*FRONT FENDER RH	Repair	977.80 FL	-	*- FL
48	1		*LINER,FRONT FENDER,RH	Serviceable	206.70 FL	-	*- FL
49	1		*EMBLEM,SIDE PANEL RH	Not Necessary	54.60 FL	-	*- FL
50	1		*FRONT FENDER LH	Repair	977.80 FL	-	*- FL
51	1		*LINER,FRONT FENDER,LH	Serviceable	202.50 FL	-	*- FL
52	1		*EMBLEM,SIDE PANEL LH	Not Necessary	54.60 FL	-	*- FL
53	1		*FRONT BONNET	Repair	983.10 FL	-	*- FL
54	1		*JAR ASSY,WINDSHIELD WASHER	Serviceable	219.10 FL	-	*- FL
55	1		*INLET SUB ASSY,WASHER	Serviceable	67.00 FL	-	*- FL
56	1		*MOTOR AND PUMP ASSY,WINDSHIELD WASHER	Serviceable	292.40 FL	-	*- FL
57	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 F	-	*47.00 FN
58	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 F	-	*52.90 FN
59	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 F	-	*53.50 FN
60	1		*SET PARKING AID	Dented	700.00 FS	-	*200.00 FS
61	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	-	*66.00 FS
62	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
63	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
64	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	-	*- FS
65	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	-	*- FS
66	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	-	*- FS
67	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	-	*- FS
68	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
69	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
70	1		*SET FRNT RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
71	1		*SET FRNT LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	-	*- FS
72	1		*FRONT FENDER LINER CLIP	Not Necessary	35.00 FS	-	*- FS
73	1		*SET FRONT BUMPER CLIP	Not Necessary	66.00 FS	-	*- FS
74	1		*REAR FENDER LINER CLIP	Not Necessary	35.00 FS	-	*- FS
75	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	200.00 FS	-	*- FS
76	1		*FRONT WHEEL RIM	Serviceable	1,879.40 FS	-	*- FS
77	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	-	*- FS
78	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	-	*- FS
79	1		*FRONT NUMBER PLATE WITH MOULDING	Dented	200.00 FS	-	*45.00 FS
80	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	-	*- FS
81	1		*WINDSCREEN MOULDING	Not Necessary	160.00 FS	-	*- FS
82	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	-	*- FS
83	1		*FRONT BUMPER	Mtg Distorted	387.00 FS	-	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>34,576.10</b>	<b>3,657.10</b>
- List Item Discount on L Items 25.00/25.00% (S\$)	6,767.98	733.18
- Nett Item Discount on N Items 0.00/25.00% (S\$)	0.00	38.35
<b>Total Parts (S\$)</b>	<b>27,808.12</b>	<b>2,885.57</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	880.00
3	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
12	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	7,500.00	500.00
13	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
14	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
16	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
17	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			18,020.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >