

ASS. REC. BY: Ran

REF: NS/INC20002850/Fyd302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: 8KQ 3073A

Policy No. 5115454553 (7/2/2020-6/2/2021)

Claims No. MT/1084810-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SAC 79975 Yr Regn: 17/09/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i40 c.c. 1695

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 601292 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPHHL891000079533

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WALKE

Front Rear

R/Bal. 6 mm R/Bal. 7 mm

L/Bal. 6 mm L/Bal. 7 mm

D.O.A. 17/02/2020 D.O.I. 18/02/2020

Survey held at cometdelgro (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear & rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/07/1997 S- OS/10119017 338 / Uyd302

8KQ 3073A-X

RECEIVED 03 MAR 2020

D.O.A. 25/9/2019

MLC EX

US\$7500/- with 5 repair days (Red \$7824-26, 51%)

Confirmation 28/02/2020 with LIMITS

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to? 3/3/20 Typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (+)

Survey Fee:	<u>160</u>
Transportation:	
3 - RS	
Photos	
Others	
TOTAL	<u>160</u>

Report Format: Lump Sum / L.P.J. 12 \$7500/-

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	17/02/2020 12:48
Vehicle No. (For Motor)	SKQ3073A	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5115454553		ZAWIYAH BINTE ABU BAKAR	S1416798P	GPC	drive CLASSIC	SKQ3073A	SKQ3073A	07/02/2020	06/02/2021

TP Claims against NTUC Income: Follow-Through Survey

Date : 28/02/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1085806-002	COMFORTDELGRO	SHD 4825U	GBC 593R	25/02/2020	8:45	\$ 2,345.22	\$ 1,021.00
2	MT/1083588-002	COMFORTDELGRO	SHD 3523V	FBQ 5834P	07/02/2020	10:00	\$ 6,204.40	\$ 3,750.00
3	MT/1085036-002	COMFORTDELGRO	SHC 7305P	SLB 3273G	19/02/2020	14:40	\$ 7,372.68	\$ 4,100.00
4	MT/1085219-002	COMFORTDELGRO	SHD 3699Z	GR 5818Y	20/02/2020	11:15	\$ 2,045.38	\$ 1,000.00
5	MT/1085285-002	CITYCAB P/L	SHC 7042V	GBD 9858M	19/02/2020	17:00	\$ 2,692.98	\$ 1,500.00
6	MT/1084810-002	CITYCAB P/L	SHC 7997S	SKQ 3073A	17/02/2020	15:00	\$ 15,324.26	\$ 7,500.00
7	MT/1085980-002	COMFORTDELGRO	SHA 4627K	SDD 6366L	26/02/2020	7:50	\$ 1,734.53	\$ 740.00
8								
9								
10								
11								

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2020 14:05
Date Of Accident	17/02/2020 15:00
Exact Location Of Accident	PIE TWDS TUAS BEFORE EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC7997S
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	STEPHEN YU AH KAU
NRIC No	SXXXX779J
Date Of Birth	25/01/1948
Occupation	OUTDOOR
Date Of Driving Pass	07/11/1978
Driving Experience	41 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96319773
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	101 09-174 WHAMPOA DRIVE
Postcode	323101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BEDOK S NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ3073A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMED YAZEED BIN IBRAHIM
NRIC/Passport Number	
Contact Number	91809903
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name STEPHEN YU AH KAU

Approximate Age 72

Injuries Sustain CHEST,NECK

Injured person in which vehicle? SHC7997S

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

A 246-9476 B 5003073A	PIE - 1409 Tues before Bank Exit	
-------------------------------------	---	---

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attended police report.

T/20200218/2038.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB FTE LTD
REG NO. 1995028307
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wei Yieing
NRIC/FIN No.:

CityCab Driver's License No.:



**SINGAPORE
POLICE FORCE**



T/20200218/2038

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

1 of 4

Report No. T/20200218/2038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/02/2020 12:19	Vide Report No.:	Station Diary No.: 21
--	------------------	--------------------------

Informant's Particulars

Name of Informant: STEPHEN YU AH KAU			Address: APT BLK 101 WHAMPOA DRIVE #09-174 SINGAPORE 323101	
ID Type / ID No.: NRIC NO / S2503779J			Contact No.:	Mobile: 96319773
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 72	Date of Birth: 25/01/1948	Type of Informant: Driver	
Race: Chinese			Language: Malay	Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident

Details Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/02/2020 15:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Towards Tuas direction, in between Bedok North and Eunos				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7997S	Car				Slightly Damaged	1
SKQ3073A	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200218/2038

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

2 of 4

Report No. T/20200218/2038

CONTINUATION OF REPORT

Driver			
Name	STEPHEN YU AH KAU	ID No.	S2503779J
Related Vehicle	SHC7997S (Car)	Contact No.	96319773
Hospital/Clinic	C & K FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	18/02/2020	Date Discharge	18/02/2020
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Driver			
Name	MOHAMED YAZEED BIN IBRAHIM	ID No.	S9040874G
Related Vehicle	SKQ3073A (Car)	Contact No.	91809903
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 17/02/2020 at about 1500hrs, I was driving my taxi bearing plate number SHC7997S, along PIE heading towards Tuas direction with a passenger. At that time, I was driving along lane 2.

While driving, before the exit to Jln Eunus, that is when all of a sudden, I felt an impact coming from the rear of my vehicle. As a result of the impact, my taxi was moved forward and I quickly applied the brakes. At that time, there were no vehicle ahead of mine.

I disembarked from the vehicle and discovered that there is another vehicle bearing plate number SKQ3037A, silver Suzuki had collided the rear of my vehicle. As a result of the collision, there were damages at the rear of my taxi.

I made a check on my passenger and was informed that she does not require any medical attention at that point of time.

I exchanged particulars with the other driver and Traffic police came at scene. I do not have the incident reference number.

Due to the accident, I felt some pain around my chest and neck area. I went for a medical checkup the following day and was given 7 days MC.

I wish to state that I have in-car camera installed in my vehicle facing the front and back.



**SINGAPORE
POLICE FORCE**



T/20200218/2038

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

3 of 4

Report No. T/20200218/2038

CONTINUATION OF REPORT






Team: ARC Repair TP(CFSO)1		JOB CARD		Sales Order: 3992785		JC NO.: 305382272	
JMER		REGN NO: SHC7997S		MILEAGE			
CITYCAB PTE LTD		MAKE: HYUNDAI		FUEL			
7010070		MODEL: I-40		DATE/TIME IN		17.02.2020 15:00	
JMER NO. 383 SIN MING DRIVE		YR OF MANU: 17.09.2015		TARGET DATE			
ESS Singapore SINGAPORE 575717		CHASSIS CODE: KMHLB41UMGU079538		COMPLETION DATE/TIME			
65551188							
(R)							
(P)							
JUNT CARD NO.							

Accident Date: 17.02.2020
NATURE: 3P 17.02.2020

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
000450	23-01	TOWING FEE
000460	PB	PANEL BEATING
000470	SP	SPRAYPAINT CHARGE
000480	17-01	CHECK ALL LIGHTING
000490	20-00	TUFF COAT ON AFFECTED PARTS.
000500	20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR
000510	20-05	RENEW ADVERTISEMENT STICKER-
000520	L	RENEW REAR WINDSCREEN GLASS
000530	L	REMOVE / REFIX REVERSE SENSOR
000540	20-06	REMOVE/REFIX EXHAUST PIPE TO ASST REPAIR



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Judgment Slip		Exit Pass	
Vehicle No. SHC7997S	LTS NTUC	Vehicle No. SHC7997S	
Service Advisor	Signature/Date	Name of Service Advisor	Date
Returned to Service Reception upon collection		To be kept by Security Guard	

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305382272
 REGN NO : SHC7997S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.09.2015
 DATE/TIME IN : 17.02.2020 15:00
 ACCIDENT DATE : 17.02.2020

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT			
0026 04-01-0103-0785-G	I40VC MLDG-CR PIECE	1	85.00	20.00	68.00 45.00 <i>45.00</i>
0027 04-01-0103-0780-G	I40VC MT'G CLIP-RR COMBI	2	3.80	20.00	3.04 7.60 <i>7.60</i>
0028 04-01-0103-1053-G	I40VC TRIM-TRANSVERSE RR	1	57.70	20.00	46.16 57.70 <i>46.16</i>
0029 04-01-0103-0830-G	I40VC PANEL ASSY-RR FLOOR	1	746.60	20.00	597.28 746.60 <i>597.28</i>
0030 04-01-0103-2158-G	I40VC REINF SPARE TIRE CA	1	223.10	20.00	178.48 223.10 <i>178.48</i>
0031 03-01-0103-0121-G	I40VC GUARD ASSY-RR WHEEL	1	169.30	20.00	135.44 169.30 <i>135.44</i>
0032 04-01-0103-0585-G	I40VC LAMP ASSY-RR COMB O	1	697.80	20.00	558.24 697.80 <i>558.24</i>
0033 04-01-0103-0583-G	I40VC LAMP ASSY-RR COMB I	1	565.60	20.00	452.48 565.60 <i>452.48</i>
0034 04-01-0103-0581-G	I40VC LAMP ASSY-RR COMB O	1	697.80	20.00	558.24 697.80 <i>558.24</i>
0035 04-01-0103-0584-G	I40VC LAMP ASSY-RR COMB I	1	565.60	20.00	452.48 565.60 <i>452.48</i>
0036 04-01-0103-0696-G	I40VC PANEL ASSY-BACK #	1	526.70	20.00	421.36 526.70 <i>421.36</i>
0037 09-01-0103-0104-G	I40VC LAMP ASSY-LICENSE P	2	67.90	20.00	54.32 135.80 <i>54.32</i>

2068.8

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305382272
 REGN NO : SHC7997S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.09.2015
 DATE/TIME IN : 17.02.2020 15:00
 ACCIDENT DATE : 17.02.2020

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT			
0014 04-01-0103-0695-G	I40VC CLAMP-SPARE TIRE	1	X5.60	20.00	4.48 <i>80%</i>
0015 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00	50.00 <i>NEE</i>
0016 04-01-0103-0577-G	I40VC PANEL ASSY-TRUNK LI	1	2,174.90	20.00	1,739.92 <i>80%</i>
0017 04-01-0103-0604-G	I40VC LATCH ASSY-HOOD	1	X102.60	20.00	82.08 <i>80%</i>
0018 04-01-0103-0713-G	I40VC HINGE ASSY-TRUNK LI	1	142.30	20.00	113.84 <i>80%</i>
0019 04-01-0103-0712-G	I40VC HINGE ASSY-TRUNK LI	1	142.30	20.00	113.84 <i>80%</i>
0020 04-01-0103-0787-G	I40VC EMBLEM-I40	1	28.70	20.00	22.96 <i>NEE</i>
0021 04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	28.70	20.00	22.96 <i>NEE</i>
0022 04-01-0103-0800-G	I40VC SYMBOL MARK-TRUNK L	X	18.70	20.00	14.96 <i>NEE</i>
0023 04-01-0103-0784-G	I40VC MLDG-BACK PANEL	1	227.90	20.00	182.32 <i>DEE</i>
0024 28-01-0103-0009-A	(I40)REAR BOOT LOGO CCTPL	1 N	30.00	2.00	30.00 <i>NEE</i>
0025 28-01-0103-0010-A	(I40)REAR BOOT TEL NUMBER	1 N	30.00	0.20	30.00 <i>NEE</i>

2762.6

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305382272
 REGN NO : SHC7997S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.09.2015
 DATE/TIME IN : 17.02.2020 15:00
 ACCIDENT DATE : 17.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	553.00	20.00	442.40	cra
0002	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	q cra
0003	04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	103.50	20.00	82.80	Br
0004	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	428.40	20.00	342.72	Br
0005	04-01-0103-0743-G	I40VC STAY-RR BUMPER RH	1	80.30	20.00	64.24	Br
0006	04-01-0103-0742-G	I40VC STAY-RR BUMPER LH	1	X 80.30	20.00	64.24	1 xnn
0007	04-01-0103-0783-G	I40VC BRKT ASSY-RR BUMPER LH	1	X 35.60	20.00	28.48	xnn
0008	04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER RH	1	35.60	20.00	28.48	Br
0009	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	hec
0010	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00	135.70	Br
0011	04-01-0103-0851-G	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48	mis
0012	04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	30.60	20.00	24.48	mis
0013	04-01-0103-0808-G	I40VC BRACKET ASSY-RR TOW	1	X 94.60	20.00	75.68	1 xnn

~~447.7~~
 \$1512

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305382272
 REGN NO : SHC7997S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.09.2015
 DATE/TIME IN : 17.02.2020 15:00
 ACCIDENT DATE : 17.02.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0038 04-01-0103-0575-G I40V2 PANEL ASSY-QUARTER	1	X	2,171.40	20.00	1,737.12 <i>x(R)</i>
0039 04-01-0103-0745-G I40VC MOULDING-RR WDO GLA	1	/	28.30	20.00	22.64 <i>net</i>
0040 05-01-0199-0032-A (ALL)WINDSCREEN AHESIVE-3	2	N	46.00	2.00	46.00 <i>net</i>
0041 02-01-0103-0053-G I40VC MUFFLER ASSY-LH	1	X	967.70	20.00	774.16 <i>1xm</i>
0042 02-01-0103-0054-G I40VC MUFFLER ASSY-RH	1	/	949.60	20.00	759.68 <i>Sc</i>
0043 02-01-0103-0086-G I40VC PIPE-EXHAUST FR	1	/	730.10	20.00	584.08 <i>1BT</i>
0044 03-01-0103-0131-G I40V2 CROSSMEMBER-RR	1	X	655.00	20.00	524.00 <i>1xm</i>
SUB-TOTAL					: 11,894.26

JOB NATURE

0000 23-01	TOWING FEE	60.00
0001 PB	PANEL BEATING	1400.00 <i>\$1120</i>

6149.62

17088
6441.12

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305382272
 REGN NO : SHC7997S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.09.2015
 DATE/TIME IN : 17.02.2020 15:00
 ACCIDENT DATE : 17.02.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 SP SPRAYPAINT CHARGE	1000.00		560		
0003 17-01 CHECK ALL LIGHTING	50.00				
0004 20-00 TUFF COAT ON AFFECTED PARTS.	50.00				
0005 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR	120.00		580		
0006 20-05 RENEW ADVERTISEMENT STICKER-	400.00				
0007 L RENEW REAR WINDSCREEN GLASS	120.00				
0008 L REMOVE / REFIX REVERSE SENSOR	80.00		60		
0009 20-06 REMOVE/REFIX EXHAUST PIPE TO ASST REP	150.00				
SUB-TOTAL :					3,430.00
TOTAL :					15,324.26

9422.52

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Cons
 the Repa

- To resurvey seller
- To display damaged
- Parts prices are subject to
- Third party survey is not a
- No official cost estimate is
- Supplementary work is

Acknowledged by Receiver:
 Signature:
 Date:

20/2/2020 Ram (LKK)
 1600hrs 19/02/2020
 parasuram@lkk.com
 28622778 (L/S)
 aft repair photo
 5 repair days

Our Job Ref No : 305382272

Date : 24/02/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No : SHC7997S

Date of Accident : 17-Feb-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SKQ3073A

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$7,500.00


\$7,500.00

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : RAM

Date : 28/02/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

X

VEHICLE : SHC7997S TYPE OF CLAIM : 3P

MODEL : I40 SURVEY BY : LKK - RAM

JOB NO : 305382272 DATE : 18.02.20

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
	CHECK AND X ITEMS - REPLACED			
1	REAR BUMPER UNDER COVER	1	228.00	cmf
2	REAR BUMPER STAY LH	1	80.30	nee
3	REAR BUMPER BRKT RH	1	35.60	Br
4	REAR BUMPER REFLECTOR RH/LH	2	30.60	each mg
5	EXHAUST CENTRE PIPE	1	730.10	Et
	* Last Entry *			

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305383507
REGN NO : SHD4825U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 25.02.2020 09:55
ACCIDENT DATE : 25.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G IONIQV2 MOULDING ASSY-RR 1 451.25 20.00 361.00 DEF
0002 FNPS NO PLATE(S) 1 N 50.00 2.00- 50.00 CVA

SUB-TOTAL : 411.00

JOB NATURE

0000 PB PANEL BEATING 320.00
0001 SP SPRAYPAINT CHARGE 200.00
0002 20-00 TUFF COAT ON AFFECTED PARTS. 30.00
0003 20-22 REMOVE/REFIX REVERSE SENSOR 60.00
SUB-TOTAL : 610.00

TOTAL : 1,021.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

2ds

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20002850/Fyd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 04-03-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 3073A	Veh. Inspected	SHC 7997S	
Policy No.	5115454553	Coverage (\$)	0.00	
Claim No.	MT/1084810-002	Excess (\$)	0.00	
Assign From		Assign Date	18/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU079538	Colour	YELLOW	
Odometer	601292	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2020	Inspection Date	18/02/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7997S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	I40VC COVER ASSY-RR BUMPE	CRACKED	553.00	553.00
1	I40VC COVER-RR BUMPER LWR	CRACKED	228.00	228.00
1	I40VC ABSORBER-RR BUMPER	BROKEN	103.50	103.50
1	I40VC BEAM-RR BUMPER	BROKEN	428.40	428.40
1	I40VC STAY-RR BUMPER RH	BENT	80.30	80.30
1	I40VC STAY-RR BUMPER LH	NOT NECESSARY	80.30	-
1	I40VC BRKT ASSY-RR BUMPER LH	NOT NECESSARY	35.60	-
1	I40VC BRKT ASSY-RR BUMPER RH	BROKEN	35.60	35.60
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40VC REFLECTOR / REFLEX AS	MISSING	30.60	30.60
1	I40VC REFLECTOR / REFLEX AS	MISSING	30.60	30.60
1	I40VC BRACKET ASSY-RR TOW	NOT NECESSARY	94.60	-
1	I40VC CLAMP-SPARE TIRE	NOT NECESSARY	5.60	-
1	I40VC PANEL ASSY-TRUNK LI	BUCKLED	2,174.90	2,174.90
1	I40VC LATCH ASSY-HOOD	NOT NECESSARY	102.60	-
1	I40VC HINGE ASSY-TRUNK LI	BENT	142.30	142.30
1	I40VC HINGE ASSY-TRUNK LI	BENT	142.30	142.30
1	I40VC EMBLEM-I40	NECESSARY	28.70	28.70
1	I40VC EMBLEM-CRDI	NECESSARY	28.70	28.70
1	I40VC SYMBOL MARK-TRUNK L	NECESSARY	18.70	18.70
1	I40VC MLDG-BACK PANEL	DEFORMED	227.90	227.90
1	I40VC MLDG-CR PIECE	SCRATCHED	85.00	85.00
2	I40VC MTG CLIP-RR COMBI	NECESSARY	3.80	3.80
1	I40VC TRIM-TRANSVERSE RR	DEFORMED	57.70	57.70
1	I40VC PANEL ASSY-RR FLOOR	NOT NECESSARY	746.60	-
1	I40VC REINF SPARE TIRE CA	NOT NECESSARY	223.10	-
1	I40VC GUARD ASSY-RR WHEEL	NOT NECESSARY	169.30	-
1	I40VC LAMP ASSY-RR COMB O	CRACKED	697.80	697.80
1	I40VC LAMP ASSY-RR COMB I	NOT NECESSARY	565.60	-
1	I40VC LAMP ASSY-RR COMB O	CRACKED	697.80	697.80

Report Ref No. NS/INC20002850/Fyd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	I40VC LAMP ASSY-RR COMB I	NOT NECESSARY	565.60	-
1	I40VC PANEL ASSY-BACK	BUCKLED	526.70	526.70
2	I40VC LAMP ASSY-LICENCE P	NOT NECESSARY	67.90	-
1	I40V2 PANEL ASSY-QUARTER	TO REPAIR SEE LABOUR	2,171.40	-
1	I40VC MOULDING-RR WDO GLA	NECESSARY	28.30	28.30
1	I40VC MUFFLER ASSY-LH	NOT NECESSARY	967.70	-
1	I40VC MUFFLER ASSY-RH	SCRATCHED	949.60	949.60
1	I40VC PIPE-EXHAUST FR	BENT	730.10	730.10
1	I40V2 CROSSMEMBER-RR	NOT NECESSARY	655.00	-
	LESS 20% DISCOUNT		-2,900.64	-1,610.46
			11,602.56	6,441.84
	<u>SPECIAL NETT ITEMS</u>			
1	HYUNDAI REVERSE SENSOR AS (SN)	TORN	135.70	135.70
1	I40VC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	(I40) REAR BOOT LOGO CCTPL (SN)	NECESSARY	30.00	30.00
1	(I40) REAR BOOT TEL NUMBER (SN)	NECESSARY	30.00	30.00
2	(ALL) WINDSCREEN AHESIVE-3 (SN)	NECESSARY	46.00	46.00
1	ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	400.00
			691.70	691.70
	<u>LABOUR</u>			
	TOWING FEE.		60.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF I40V2 PANEL ASSY-QUARTER.		1,400.00	1,120.00
	SPRAYPAINT CHARGE.		1,000.00	600.00
	CHECK ALL LIGHTING.		50.00	50.00
	TUFF COAT ON AFFECTED PARTS.		50.00	50.00
	REMOVE / REFIX UPHOLSTERY ASST REPAIR.		120.00	80.00
	RENEW REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	60.00
	REMOVE / REFIX EXHAUST PIPE TO ASST REP.		150.00	150.00
			3,030.00	2,170.00

Report Ref No. NS/INC20002850/Fyd3e2

GRAND TOTAL		15,324.26	9,303.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			7,500.00

Report Ref No. NS/INC20002850/Fyd3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or resting on this Report, in whole or in part, does so at his or her own risk.