

EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221003

Supplementary Estimate : TI20/010

1st Accident.

Date : 15/02/2020

Vehicle Num. : SGC 9333 G

Make/Model : NISSAN

Chassis/Eng# :

Accident Date : 08/02/2020

Claim No. : SNM20D200737

Reference :

Policy No. :

Shirley.

JN1TAAE1220880076

S/N Quantity Particular Unit Price Amount S\$

LIST ITEMS :				
1.	1	BUMPER FACE FRONT	2088.63	✓ 485.67
2.	1	BUMPER SIDE RETAINER FRONT		✓ 25.57
3.	1	BUMPER REINFORCEMENT - FRONT		* 365.51
4.	1/LH	HEAD LAMP ASSY - LH	1879.76	✓ 1,577.39
List Total S\$.				2,454.14

LABOUR :

ACCIDENT REPAIR PANEL BEATING

RESPRAY PAINT WORK ON REPAIR AREA

RUSTPROOFING TREATMENT

WIRING SERVICE & FOCUS HEAD LAMP

430

~~650.00~~ 200
~~680.00~~ 200
100.00 x
~~80.00~~ 30

Labour Total S\$.

1,510.00

SingDollars : Three Thousand Nine Hundred Sixty-Four & Cents Fourteen Only

Total S\$ 3,964.14

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2309.76

Adrian Li

H/S: 1-8K

H/S 24/02/20

032up

EVER SEN AUTO SERVICE