

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

*Not Withheld
U/Sep 8?
Resurvey After Paint*

Estimate bill : TT 09 / 20 / TP / WT

Registration No : PA4355E

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Make / model : Nissan Urvan 3.0 D

Mileage :

Date : 18 / 02 / 2020

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHA8067E, YP6155S AND PA4355E ALONG CTE (AYE) TWDS TUAS BEFORE BRADDELL RD ON 14 FEBRUARY 2020 AT ABOUT 1550 HRS.

1pc	Front windscreen		\$	1,443.00	X
1pc	Front windscreen rubber		\$	165.00	X
1pc	Front windscreen moulding		\$	198.00	—
1pc	Front wiper panel garnish		\$	375.00	X
1pc	Front panel		\$	1,288.00	—
2pcs	Front cornel panel	(Each \$300.00)	\$	600.00	X
1pc	Front grille		\$	611.00	—
1set	Front grille clip		\$	86.00	—
1pc	Front grille emblem		\$	123.00	—
2pcs	Front head-lamp	(Each \$411.00)	\$	822.00	—
2pcs	Front signal lamp	(Each \$174.00)	\$	348.00	—
1pc	Front bumper		\$	621.00	—
2pcs	Front bumper fog lamp	(Each \$367.00)	\$	734.00	X
2pcs	Front bumper fog lamp grille	(Each \$123.00)	\$	246.00	X
1pc	Front bumper reinforcement		\$	495.00	✓
1pc	Rear windscreen		\$	1,221.00	X
1pc	Rear windscreen rubber		\$	165.00	X
1pc	Rear windscreen moulding		\$	165.00	✓
1pc	Rear boot		\$	1,998.00	—
1pc	Rear boot outer handle		\$	411.00	X
2pcs	Rear boot damper	(Each \$278.00)	\$	556.00	X
1pc	Rear boot upper lock		\$	489.00	—
2pcs	Rear tail lamp	(Each \$255.00)	\$	510.00	✓
	Sub total :		\$	13,670.00	
	Less 10% discount:		\$	1,367.00	
	A total :		\$	12,303.00	
Total amount of Page 1 :				\$	12,303.00

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

Estimate bill : TT 09 / 20 / TP / WT

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Registration No : PA4355E

Make / model : Nissan Urvan 3.0 D

Mileage :

Date : 18 / 02 / 2020

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHA8067E, YP6155S AND PA4355E ALONG CTE (AYE) TWDS TUAS BEFORE BRADDELL RD ON 14 FEBRUARY 2020 AT ABOUT 1550 HRS.

1pc	Rear end panel		\$	405.00	✓
1pc	Rear bumper (Step board)		\$	285.00	✓
1pc	Rear bumper parktronic sensor		\$	200.00	✓
2pcs	Rear bumper side bracket	(Each \$36.00)	\$	72.00	✓
1pc	Rear silencer box (Tail pipe)		\$	BENT 1,221.00	✓
1pc	Radiator support panel		\$	NN 465.00	X
	Sub total :		\$	2,648.00	
	Less 10% discount:		\$	264.80	
	B total :		\$	2,383.20	
	Special net items :				
1pc	Front license smart plate		\$	35.00	✓
1pc	Rear boot emblem		\$	123.00	✓
1pc	Rear boot '70 kmh' label		\$	15.00	✓
1pc	Rear boot 'Emergency Door' label		\$	15.00	✓
1pc	Rear boot 'Pull to Open' label		\$	15.00	✓
	C total		\$	203.00	
	Total amount of Page 2 :		\$	2,586.20	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01 201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL 6481 7773 / 6481 1403 FAX 6484 4978

E-mail tsac303@singnet.com.sg

M / s : **First Capital Insurance Ltd**
36, Robinson Road, #16-01
City House, Singapore 068877

Supplementary bill : TT 09 / 20 / TP / WT

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Registration No : PA4355E

Make / model : Nissan Urvan 3.0 D

Mileage :

Date : 20 / 02 / 2020

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHA8067E, YP6155S AND PA4355E ALONG CTE (AYE) TWDS TUAS BEFORE BRADDELL RD ON 14 FEBRUARY 2020 AT ABOUT 1550 HRS.

Supplementary rear spare part items :

1pc	Air con cooling coil air duct	✓	CRA	
2pcs	Air con cooling coil casing	✓	CRA	
2pcs	Heater cooling coil casing	✓	CRA	
1pc	Heater cooling coil hose (Short)	✓	DENTED	\$ 40.00
	Sub total :			\$ 40.00
	Less 10% discount:			\$ 4.00
	A total :			\$ 36.00

Special net items :

1bte	Air con compressor oil treatment			\$ 150.00	} \$10 NEC
-	Filling air con 134a gas			\$ 30.00	
-	Conduct air con vacuum test			\$ 180.00	
1bte	Coolant			\$ 300.00	
	B total :			\$ 250.00	
	Remove and refit front dash-board			\$ 300.00	
	Grand final amount for supplementary :			\$ 516.00	

15,405.20#

Tropical Tech Automobile Services

(Authorised Signature)
William Tan