



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2203158

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 26/05/2022
Reference CC4/FCI20002868/Aea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMR 9656A
Insured Veh. SHC 7591D
Claim No. D20001073MFSH
Policy No. D-20094921MFSH
Accident Date 15/02/2020
Inspection Date 25/02/2020

Description	Total
Survey Inspection	196.00
Digital Photographs	
Transportation	
Subtotal	196.00
GST (7%)	13.72
Grand Total	209.72

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20002868/Aea3q2	
			Date: 26/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7591D	Veh. Inspected	SMR 9656A
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20001073MFSH	Excess (\$)	0.00
	Assign From	KAREN	Assign Date	18/02/2020
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHD841CMLU030900	Colour	BLUE
	Odometer	1095 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	KUMHO	6 mm
	L/H Front Tyre	205/55 R16	KUMHO	6 mm
	R/H Rear Tyre	205/55 R16	KUMHO	6 mm
	L/H Rear Tyre	205/55 R16	KUMHO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2020	Inspection Date	25/02/2020
	Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 9656A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR -RH	DISTORTED	1,831.10	1,831.10
1	FRONT DOOR CHECK -RH	NOT NECESSARY	39.80	-
2	FRONT DOOR STICKER-RH @\$18.00	NECESSARY	36.00	36.00
1	FRONT DOOR RUBBER -RH	NOT NECESSARY	112.30	-
1	FRONT DOOR HINGE ,TOP -RH	NOT NECESSARY	41.10	-
1	FRONT DOOR HINGE ,LOWER -RH	NOT NECESSARY	41.10	-
1	FRONT DOOR REGULATOR GEAR -RH	NOT NECESSARY	250.40	-
1	FRONT DOOR REGULATOR GEAR MOTOR-RH	NOT NECESSARY	297.80	-
1	FRONT DOOR LOCK -RH	NOT NECESSARY	191.50	-
1	ROCKER PANEL -RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-568.22	-373.42
			2,272.88	1,493.68
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS ,RH FRONT ROCKER PANEL INNER ,CUT /WELD ,RH FRONT ROCKER PANEL OUTER ,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL -RH .		1,000.00	500.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	600.00
	TO CHECK WIRING .		20.00	20.00
	TO TUFF -KOTE.		50.00	50.00
	TO TRANSFER DOOR AND DOOR FITTING.		80.00	80.00
	TO RESET CHECK LIGHT.	NOT NECESSARY	60.00	-
			2,010.00	1,250.00
GRAND TOTAL			4,282.88	2,743.68
RECOMMENDED COST OF REPAIRS				2,743.68

Report Ref No. CC4/FCI20002868/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 9656A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

