

22/03/2002

ASS. REC. BY:

REF:

CS/SPF20002869/K/d302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Frankie Thuy

of

SPF

Date/Time: 19/2/2020 @ 1:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

3HD 511B

Insured:

TP 948U

at Workshop m/s

Transcab

Tel:

6287 6666

of

No. 2 Amk St. 63

Policy No:

Claim No:

ACS/105/009/2020/005

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:37pm 19/2/2020

Person Contacted:

Candy

Vehicle:

IN / OUT

Date/Time

Action/Instruction

Johnny ✓

3HD 511B - CE3 / A16 / 1902 / 054 / K/d3

D.O.A. 28/11/2019

Do Not Finalise

ASS. REC. BY:

REF: SP11/Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV ☒

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

1 1/2 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

1-Buy %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S140 511BYr Regn: 07, 17Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Traller or \_\_\_\_\_

Make: Renault Latitude1995Colour M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading 322878

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VI-1 ABL 15AUC 283480Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Sailun

Front

Rear

R/Bal. 9 mmR/Bal. 7 mmL/Bal. 9 mmL/Bal. 7 mmD.O.A. 5/12/20D.O.I. 20/2/2020

Survey held at \_\_\_\_\_

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

866.71 submitCred: 23,144.29 ; 96910Weekend- 0Repair days- 1Total - 1Repair range 866.71 - 1000

Date/Time, File Pass to?

☐

: Prell. Report

☒

: Final Report

Date/Time, File Return to?

Days Of Repair: 1.5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + R.S. \$ \_\_\_\_\_

Fees: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL

220Report Format: TP

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

## Nivitha (LKK Auto)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Wednesday, 19 February 2020 1:53 PM  
**To:** 'Veron Chen (LKKAuto)'; 'assignments'  
**Cc:** Cui Fen ENG (SPF); Hafizul Farhan RAHMAT (SPF); Lai Kuen LUI (SPF)  
**Subject:** RE : Pre-Repair Inspection for Vehicle SHD 511 B

Your reference: SHD 511 B

Our reference: ACS/105/009/2020/005

Veron,

Please conduct Pre-Repair Inspection for vehicle SHD 511B at the address listed below :

TRANSCAB AUTO SERVICES PTE LTD

No. 2 Ang Mo Kio Street 634

Singapore 569111

Please contact Zhe Wei at 62876666 for appointment.

Thanks.

Frankie Thay

1 Logistics Services Executive

Police Logistics Base

1 Hemmant Road, Singapore 438675

Logistics Support & Services Division

Police Logistics Department



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD511B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Feb 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003349
Chassis No.:	VF1ABL15AUC283480
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jul 2017
First Registration Date:	10 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$26,147.00
<b>Total Rebate Amount:</b>	<b>\$41,145.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Feb 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/02/2020 11:35
Date Of Accident	05/02/2020 19:45
Exact Location Of Accident	LOWER DELTA ROAD TOWARDS DELTA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD511B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	ONG HWA SENG
NRIC No	SXXXX717A
Date Of Birth	10/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	25/01/1979
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97341386
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 706 JURONG WEST STREET 71 #09-58
Postcode	640706
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20200205/2350

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	TP948U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







# SINGAPORE POLICE FORCE



T/20200205/2350

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

1 of 3

Report No. T/20200205/2350

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/02/2020 22:19	Vide Report No.:	Station Diary No.: 130
--	------------------	---------------------------

**Informant's Particulars**

Name of Informant: ONG HWA SENG			Address: APT BLK 706 JURONG WEST STREET 71 #09-58 SINGAPORE 640706	
ID Type / ID No.: NRIC NO / S1501717A			Contact No.: Home/Office: Mobile: 97341386	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 59	Date of Birth: 10/01/1961	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4,5 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 05/02/2020 19:45	Type of Location:
Location: Along Road 1 LOWER DELTA ROAD  along Lower Delta Road towards Delta Road, after Jalan Bukit Merah junction, before busstop				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD511B	Car				No Damage	1
TP948U	Motorcycle					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



# SINGAPORE POLICE FORCE



T/20200205/2350

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

2 of 3

Report No. T/20200205/2350

**CONTINUATION OF REPORT**

<b>Driver</b>				
Name	ONG HWA SENG		ID No.	S1501717A
Related Vehicle	SHD511B (Car)		Contact No.	97341386
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
<b>Rider</b>				
Name	MENDEL KOH		ID No.	NIL
Related Vehicle	TP948U (Motorcycle)		Contact No.	83993611
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 05.02.2020 at about 1945hrs, I was driving my taxi, SHD511B, red Renault, along Lower Delta Road towards Delta Road. After Jalan Bukit Merah junction, I was travelling on the second lane. I saw one Traffic Police motorcycle behind my taxi. I signaled left to change lane to the third lane. Somewhere before the busstop, suddenly the motorcycle collided onto the rear of my taxi.

I then immediately stopped my taxi at the side of the road. The Traffic Police motorcycle had fell on the road. The officer brought up his motorcycle and parked his motorcycle at the side of the road. He informed that he was not injured. We then exchanged particulars. He was Mendel Koh, HP: 8399 3611, T3M13, riding motorcycle TP948U, white Yamaha. He informed that he was looking at another lorry on the left when the accident happened.

My taxi did not sustain any damages. There is only a tyre mark on the rear bumper of my taxi. I am not sure if the motorcycle is damaged.

Another Traffic Police officer came to scene. I handed over my in-vehicle car camera footage to the officer, Sgt (2) T180096 Shivasuria. I was instructed to lodge a Police Traffic Accident report. The incident number of the accident is A/20200205/0102.



**SINGAPORE  
POLICE FORCE**



T/20200205/2350

3 of 3

Report No. T/20200205/2350




Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report D / Sr Staff Sgt MOHAMED FIRDAUS BIN KAMSANI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/02/2020 22:19
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168  SN 34 SIGNATURE 	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B****AAD2002-043***Not Authorised**Presumy B4 paint**8866.71*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

20 FEB 2020

**SHD 511B**

VF1ABL15AUC283480

RENAULT

LATITUDE

5.2.2020

**A-GC**

10/7/2017

	<b>PART</b>
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR RH
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	OUTER PANEL REAR (End Panel)
1	OUTER PANEL REAR (End Panel) TRIM
1	TAILLAMP RH
1	TAILLAMP PANEL RH
1	TAILLAMP LH
1	TAILLAMP PANEL LH
1	BOOT REAR
1	BOOT FINISHER
1	BOOT WHEATERSTRIP
1	BOOT REFLECTOR LAMP LH
1	BOOT REFLECTOR LAMP RH
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT INNER TRIM BOARD

	<b>LIST</b>
\$	<i>R</i> 561.70 <i>X</i>
\$	<i>nd/w</i> 411.90 <i>✓</i>
\$	<i>Sn</i> 98.10
\$	<i>Sn</i> 82.10
\$	<i>Sn</i> 59.80
\$	<i>Sn</i> 16.60
\$	<i>Sn</i> 80.80
\$	<i>Sn</i> 54.20
\$	<i>Sn</i> 16.60
\$	<i>n</i> 547.80
\$	<i>n</i> 114.50
\$	<i>n</i> 100.90
\$	<i>n</i> 745.80
\$	<i>Sn</i> 404.56
\$	<i>Sn</i> 313.10
\$	<i>n</i> 401.40
\$	<i>Sn</i> 401.40
\$	<i>n</i> 401.40
\$	<i>n</i> 1,677.20
\$	<i>Sn</i> 344.70
\$	<i>Sn</i> 178.20
\$	<i>Sn</i> 277.70
\$	<i>Sn</i> 277.70
\$	<i>nn</i> 82.40
\$	<i>nn</i> 95.80
\$	<i>Sn</i> 611.00

*X*

**Trans-cab Auto Services Pte Ltd**

AAD2002-043

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B**

1	BOOT LOCK	\$	246.60	}	X
1	BOOT HINGE LH	\$	254.20		
1	BOOT HINGE RH	\$	253.80		
1	BOOT STRUT LH	\$	145.10		
1	BOOT STRUT RH	\$	145.10		
1	EXHAUST CAP REAR	\$	125.40		

**TOTAL \$ 9,527.56****10% \$ 952.76****\$ 8,574.80****Special Nett**

1SET	PARKING AID	\$	700.00	}	X
1SET	REAR BUMPER CLIP	\$	66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	33.00		
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00		
1SET	BUMPER RETAINER RH CLIP RR	\$	20.00		
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00		
1SET	BUMPER RETAINER CLIP LH RR	\$	20.00		
1SET	BUMPER LOWER REAR RIVET	\$	22.00		
1SET	BUMPER LOWER REAR CLIP	\$	66.00		
1	BOOT STICKER "Trans-cab"	\$	30.00	X	
1	BOOT STICKER "6555-3333"	\$	30.00	X	
1	BOOT INNER TRIM CLIP	\$	45.00	X	
1SET	BOOT FINISHER CLIP	\$	24.20	X	
1	TAILLAMP CLIP LH	\$	5.00	X	
1	TAILLAMP CLIP RH	\$	5.00	X	
1	Rear Bumper Protector	\$	100.00	30.00	
1	REAR LICENCE PLATE WITH HOLDER	\$	80.00	X	

**TOTAL \$ 1,266.20****TOTAL PARTS \$ 9,841.00****LABOUR**

To Rust-Proofing Of The Affected Areas. \$ 170.00 X

**Trans-cab Auto Services Pte Ltd**

AAD2002-043

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>5</i> 380.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1200</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>800</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2200</i>
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>14,170.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>24,011.00</b>	

**PART BY PART ( REPAIR DAY)****20 DAYS**

*1 1/2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF20002869/Ktd3e2	
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675 ATTN : FRANKIE THAY		Date : 02-03-2020	
		Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	TP 948U	Veh. Inspected	SHD 511B
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2020/005	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	19/02/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1ABL15AUC283480	Colour	METALLIC WHITE / RED
Odometer	322878	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	SAILUN	9 mm
L/H Front Tyre	215/60 R16	SAILUN	9 mm
R/H Rear Tyre	215/60 R16	SAILUN	7 mm
L/H Rear Tyre	215/60 R16	SAILUN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	05/02/2020	Inspection Date	20/02/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>1.500 Working Days</b>	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 511B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	561.70	-
1	BUMPER LOWER REAR	DENTED / CUT	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	547.80	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-

Report Ref No. CS/SPF20002869/Ktd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	EXHAUST CAP REAR	SERVICEABLE	125.40	-
	LESS 10% DISCOUNT		-952.76	-41.19
			8,574.80	370.71
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	100.00	30.00
1	REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
			1,266.20	96.00
	<b><u>LABOUR</u></b>			
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-

Report Ref No. CS/SPF20002869/Ktd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR, BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT LOCK, BOOT HINGE LH AND BOOT HINGE RH.		6,000.00	120.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			14,170.00	400.00
<b>GRAND TOTAL</b>			<b>24,011.00</b>	<b>866.71</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>866.71</b>

Report Ref No. CS/SPF20002869/Ktd3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$866.71-\$1,000.00**

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**