



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005255
INV Date 28/07/2020
Reference CC4/FCI20002876/Eka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKN 7350P
Insured Veh. SHC 7706R
Claim No. D20000985MFSH
Policy No. D-20094921MFSH
Accident Date 06/02/2020
Inspection Date 20/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20002876/Eka3q2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 28-07-2020
	Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7706R	Veh. Inspected	SKN 7350P
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20000985MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI ELANTRA	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KMHDH41CMEU207825	Colour	WHITE
Odometer	56493	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--	----------------------------------------------------------------------------

5. General Information

Accident Date	06/02/2020	Inspection Date	20/02/2020
Survey held at	ETHOZ PROTECT PTE LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	----------------------------------------------------------------------------------------------------------------------------------------

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 7350P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOTLID EMBLEM CENTRE	NECESSARY	59.60	59.60
1	REAR BOOTLID EMBLEM 'ELANTRA'	NECESSARY	74.50	74.50
1	REAR BUMPER	DENTED	681.90	342.80
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER GARNISH	BROKEN	351.20	351.20
1	REAR BUMPER SIDE RETAINER LH	BROKEN	42.10	42.10
1	REAR BUMPER SIDE RETAINER RH	BROKEN	42.10	42.10
1	REAR BUMPER INNER BRACKER LH	NOT NECESSARY	89.10	-
1	REAR BUMPER INNER BRACKER RH	NOT NECESSARY	89.10	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	362.10	-
1	REAR END PANEL	NOT NECESSARY	462.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	98.10	-
	LESS 20% DISCOUNT		-480.54	-192.46
			1,922.16	769.84
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOTLID EMBLEM 'ELITE' (SN)	NECESSARY	45.00	45.00
1	REVERSE SENSOR (SN)	SHORTED	220.00	220.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
			305.00	265.00
<u>LABOUR</u>				
	LABOUR TO CARRY OUT REAR REPAIR.INCLUSIVE OF THE REPAIR OF REAR BOOTLID.		800.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	30.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA.		600.00	500.00
	SPRAY RUST PROOF ON AFFECTED AREA.		50.00	30.00
	TO DETACH & RENEW REVERSE SENSOR .		60.00	30.00
			1,545.00	990.00
GRAND TOTAL			3,772.16	2,024.84



RECOMMENDED COST OF REPAIRS			2,024.84
------------------------------------	--	--	-----------------

Report Ref No. CC4/FCI20002876/Eka3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 7350P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

