

Steve (LKK) *WHL P/P*
20/2/20, 11.00am
P/P
Ry Del SH
4 days

PLEASE ARRANGE TO SURVEY VEHICLE AT 30 BUKIT BATOK CRESCENT (S 658075)

Lee Chen Sin
 CLAIM DEPARTMENT
 DID : 66547520
 FAX :

Date : 13/02/2020
 To : MS FIRST CAPITAL INSURANCE LIMITED
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : LEONG CHONG
 : AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
 Certificate No : P10014346R02 Accident Date : 06/02/2020
 Vehicle No : SKN-7350-P Make & Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	List Item		
	RESTORE		
1	REAR BOOTLID X R		
1	REAR BOOTLID EMBLEM CENTRE / MC	59.60	✓
1	REAR BOOTLID EMBLEM "ELANTRA" / MC	74.50	✓
1	REAR BUMPER / DD	681.90	✓ 342.80
10	REAR BUMPER CLIP / MC	50.00	✓
1	REAR BUMPER LOWER GARNISH / BR	351.20	✓
1	REAR BUMPER SIDE RETAINER LH / BR	42.10	✓
1	REAR BUMPER SIDE RETAINER RH / BR	42.10	✓
1	REAR BUMPER INNER BRACKET LH ? NN	89.10	✗

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Date : 13/02/2020

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LEONG CHONG

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10014346R02

Accident Date : 06/02/2020

Vehicle No : SKN-7350-P

Make & Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER INNER BRACKET RH [?] NN	89.10	×
1	REAR BUMPER REINFORCEMENT [?] NN	362.10	×
1	REAR END PANEL ^{or ?}	462.90	×
1	REAR END PANEL TOP GARNISH ^X NN	98.10	×
Sub Total		2402.70	
Discount 20% On Parts		(480.54)	
Special Nett Item			
1	REAR BOOTLID EMBLEM "ELITE" ^{/ MC}	45.00	
1	REVERSE SENSOR ^{/ SL}	220.00	
1	END PANEL SEALANT [?] NN	40.00	×

Date : 13/02/2020

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LEONG CHONG

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10014346R02

Accident Date : 06/02/2020

Vehicle No : SKN-7350-P

Make & Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	305.00	
	Labour & Misc		
	LABOUR TO CARRY OUT REAR REPAIR	800.00	400
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30
	TO SPRAY PAINTING ON REAR AFFECTED AREA	600.00	500
	SPRAY RUST PROOF ON AFFECTED AREA	50.00	30
	TO DETACH & RENEW REVERSE SENSOR	60.00	30

Date : 13/02/2020

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LEONG CHONG

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10014346R02

Accident Date : 06/02/2020

Vehicle No : SKN-7350-P

Make & Model : HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1545.00	

3,772.16

Remarks:

SUB TOTAL

GST 7.0 % 264.05

TOTAL 4,036.21

Surveyor's name: _____

Principal's name: LEONG CHONG

Survey Date & Time: _____