



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 . Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060
VEHICLE NUM: SKR 3852 M
MAKE & MODEL: HONDA ODYSSEY
MILEAGE:
TYRE:
CHASSIS NUM:

ATTN	NO	DESCRIPTION - PARTS	QTY	PRICE
	1	REAR WINDSCREEN MOULDING	1	\$289.00
	2	TAILGATE / NEC	1	\$1,400.00
	3	TAILGATE WIPER / nb 1,170	1	\$246.00
	4	TAILGATE WIPER MOTOR X SVC	1	\$297.00
	5	TAILGATE LOGO (HONDA) X SVC	1	\$99.00
	6	TAILGATE LAMP (L+R) / NEC	1	\$1,688.00
	7	TAILGATE CENTER EMBLEM GARNISH (ODYSSEY) X SVC	1	\$96.00
	8	TAILGATE CARPLATE LAMP (L+R) X SVC	1	NIL.
	9	TAILGATE SWITCH X SVC	1	\$466.00
	10	TAILGATE CENTER CHROME X SVC	1	\$488.00
	11	TAILGATE LOCK / SC4 300	1	\$491.00
	12	TAILGATE LOCK CATCH X / Suppl. 300	1	\$79.00
	13	TAILGATE INNER TRIM TOP (L+R) X SVC	2	\$216.00
	14	TAILGATE INNER TRIM TOP CENTER X SVC	1	\$271.00
	15	TAILGATE INNER BOARD LOWER X SVC 300	1	\$971.00
	16	TAILGATE INNER HANDLE X	1	\$39.00
	17	TAILGATE INNER HANDLE SWITCH X	1	\$306.00
	18	TAILGATE HINGE (L+R) X	2	\$214.00
	19	TAILGATE DAMPER (L+R) X SVC	2	\$646.00
	20	TAILGATE STOPPER (L+R) X	2	\$34.00
	21	TAILGATE WEATHERSTRIP X	1	\$346.00
	22	TAIL LAMP (L+R) X	1	\$2,240.00
	23	TAIL LAMP PANEL (L+R) X / cut. 716 \$1120	2	\$964.00
	24	REAR BUMPER X SVC	1	\$1,097.00
	25	REAR BUMPER TOP (L+R) / CRU. 750	2	\$636.00
	26	REAR BUMPER TOP RETAINER (L+R) X	2	\$408.00
	27	REAR BUMPER RETAINER (L+R) X	2	\$346.00
	28	REAR BUMPER REINFORCEMENT BAR X SVC	1	NIL.
	29	REAR BUMPER BRACKET (L+R) X	2	NIL.
	30	REAR BUMPER BEAM X	1	NIL.
	31	REAR BUMPER SPONGE X	1	NIL.
	32	REAR BUMPER REVERSE SENSOR SET X SVC	4	\$1,642.00
	33	REAR BUMPER LOWER LIP (L+R) X / SC4 400	1	\$519.00
	34	REAR BUMPER REFLECTOR (L+R) X / CRU 259.5	1	\$264.00
	35	REAR BUMPER REFLECTOR GARNISH (L+R) X / SC4 \$122.00	1	\$302.00
	36	REAR FENDER (L+R) X SVC	2	\$3,642.00
	37	REAR FENDER WINDOW MOULDING (L+R) X SVC	2	\$418.00
	38	REAR FENDER CHROME STRIP (L+R) X SVC	2	\$432.00
	39	REAR FENDER INNER TRIM TOP (L+R) X SVC	2	\$296.00
	40	REAR FENDER INNER TRIM LOWER (L+R) X / CRU. 685 \$817.00	2	\$1,634.00

41	REAR FENDER COWLING (L+R)	X SVC	2	\$408.00	
42	END PANEL	X R	1	\$1,006.00	
43	END PANEL TOP GARNISH	X SVC	1	\$49.00	
44	REAR BUZZER	? / CHU 150	1	\$841.00	
45	REAR SMART LOCK ANTENNA	? X	1	\$907.00	
46	END PANEL TOP GARNISH INNER GARNISH	X	1	\$49.00	
47	END PANEL INNER LOCK HOOK	X	1	\$29.00	
48	SPAREWHEEL PANEL	X	1	\$1,104.00	
49	SPAREWHEEL PANEL TOP BOARD	X	1	\$405.00	
50	EXHAUST PIPE	X SVC.	1	\$966.00	
51	EXHAUST GASKET	X	1	\$191.00	
52	EXHAUST BRACKET (L+R)	X	2	\$96.00	
53	EXHAUST HEAT SHIELD	X	1	\$231.00	
		P = \$10,876	6,200.5	-20%	4,960.4
		-20% = \$8760.80	SUBTOTAL	\$	-
			LESS 10%	\$	-
			PARTS TOTAL	\$	-
	SPECIAL NETT			QTY	PRICE
1	REAR WINDSCREEN SEALANT	/ NEC 3/8	1	\$	120.00 30
2	TAILGATE WIPER BLADE	X SVC	1	\$	120.00 x
3	TAILGATE INNER TRIM TOP CLIPS (CENTER)	X SVC	10	\$	100.00 x
4	TAILGATE INNER TRIM TOP CLIPS (L+R)	X SVC	20	\$	200.00 x
5	TAILGATE INNER BOARD CLIPS	X / ME	10	\$	100.00 30
6	REVERSE CAMERA (L+R)	X SVC	2	\$	1,900.00 x
7	REAR CARPLATE	X SVC	1	\$	120.00 x
8	REAR CARPLATE FRAME	X SVC	1	\$	120.00 x
9	TAIL LAMP CLIPS	X / NEC	4	\$	80.00 10
10	REAR BUMPER CLIPS	/ NEC	10	\$	100.00 30
11	REAR BUMPER TOP CLIPS	X	10	\$	100.00 x
12	REAR FENDER SEALANT	X	1	\$	120.00 x
13	REAR FENDER WINDOW SEALANT	X SVC	1	\$	120.00 x
14	REAR FENDER INNER TRIM CLIPS (TOP)	X	20	\$	200.00 x
15	REAR FENDER INNER TRIM CLIPS (BOTTOM)	X / NEC	20	\$	200.00 30
16	REAR FENDER COWLING CLIPS	X SVC	20	\$	200.00 x
17	END PANEL SEALANT	X SVC	1	\$	120.00 x
18	END PANEL TOP GARNISH CLIPS	X / NEC	10	\$	100.00 20
19	FLOOR PANEL SEALANT	X SVC	1	\$	120.00 x
20	SPARE TYRE	X SVC 5/11/150	1	\$	800.00 x
21	SPARE RIM	X SVC	1	\$	1,000.00 150
			SPECIAL NETT TOTAL	\$	6,040.00
	LABOUR			QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	700-600	1	\$	5,100.00 400
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	700-600	1	\$	3,300.00 500
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$	250.00 30
4	TO RNR REAR WINDSCREEN		1	\$	400.00 120
5	TO RNR REAR BOOT MECHANISM		1	\$	400.00 60
6	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS		1	\$	400.00 100

7	TO RNR REAR FENDER QUARTER WINDOW	1	\$ 400.00	X
8	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$ 150.00	30
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	1	\$ 250.00	X
10	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	1	\$ 120.00	30
11	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	1	\$ 400.00	X
12	TO DO WATER LEAK TEST .	1	\$ 100.00	X
13	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$ 250.00	X
	LABOUR = \$1,700.			
	TOTAL = \$10,550.80	TOTAL	\$ 11,520.00	1,700
	-80% = \$8,450.	GRAND TOTAL COST	\$ 17,560.00	

Repair - 4 days

Lump Sum Repair
After part photo

Sunpin (LKK)

20/02/2020

TP without prejudice

Sunpin@lkkauto.com

P = 4,960.4

N = 150

L = 1,700

6,810.4

- 20%

5,448.32

4/5

\$5,450

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: