

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 26 February 2020

To : LKK

By Fax: 6256-4315

Attn : Mr Rasul

Tel:

VEHICLE NO : FBQ 9284A

Yamaha T150 Sniper

ACCIDENT DATE: 14 February 2020

	Description	Qty	Quotation \$
1	Rear Mudguard <i>SVL</i>	1	260.00 <i>X</i>
2	Swing Arm <i>BT</i>	1	950.00 <i>✓</i>
3	Exhaust Guard <i>NH</i>	1	250.00 <i>X</i>
4	Front Panel <i>CVT</i>	1	280.00 <i>✓</i>
5	Front Fender <i>NH</i>	1	205.00 <i>X</i>
6	Front LH Signal <i>CVT</i>	1	95.00 <i>✓</i>

Sub-Total *1192.50* 2,040.00
 Less 10% 204.00
 Sub-Total 1,836.00

Nett Items

<i>Rev</i> 1	Front number plate <i>BT</i>		15.00 <i>✓</i>
2	To check fork alignment <i>NH</i>		60.00 <i>X</i>
3	Labour to remove & replace necessary parts, align etc exhaust pipe	<i>135.00</i>	220.00 <i>120/-</i>

Sub-Total 295.00
 Nett Total 2,131.00


1327.50

L/S 1050.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.

Thank you



S9 MOTOR TRADING PTE LTD

18/02/2020 @ 1500pm
Not Antenna
1/sum
2 days
Ryan
LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: