



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007540
INV Date 11/11/2020
Reference CC6/CTI20002883/Kea3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SMR 3794Z
Insured Veh. YP 7347Z
Claim No. SNM20D200936
Policy No. DMCVSN1828371901
Accident Date 15/02/2020
Inspection Date 18/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20002883/Kea3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 7347Z	Veh. Inspected	SMR 3794Z
Policy No.	DMCVSN1828371901	Coverage (\$)	0.00
Claim No.	SNM20D200936	Excess (\$)	0.00
Assign From		Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDZS3EU10J052245	Colour	METALLIC RED
Odometer	5147	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	9 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	9 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	9 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/02/2020	Inspection Date	18/02/2020
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 3794Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED / DENTED	566.90	566.90
1	FRONT BUMPER SPONGE	SERVICEABLE	91.70	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.70	-
1	FRONT BUMPER LOWER GRILLE	CRACKED	468.70	468.70
1	FRONT BUMPER UPPER GRILLE	DISTORTED	411.67	411.67
1	FRONT BUMPER LOGO	NECESSARY	81.70	81.70
12	FRONT BUMPER CLIP @\$3.89	NECESSARY	46.68	46.68
	LESS 25% DISCOUNT		-516.51	-393.91
			1,549.54	1,181.74
	<u>LABOUR</u>			
	TO KNOCK,JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		400.00	250.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		300.00	220.00
			700.00	470.00
	GRAND TOTAL		2,249.54	1,651.74
	RECOMMENDED COST OF REPAIRS			1,651.74

Report Ref No. CC6/CTI20002883/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 3794Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 3794Z

RE-INSPECTION

