



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 614801PLY

Date: 28th May 2020

Our Ref: CS1/MSG20002884/R1tf3s2

M/s MSIG Insurance (Singapore) Pte Ltd

4 Shenton Way #21-01

SGX Centre

Singapore 068807

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO. SKM 1361C
INSURED: PUBLIC LIABILITY ACCIDENT ON 23/10/2018**

We thank you for your instruction on 22/05/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKM 1361C from M/s Borneo Motors (Singapore) Pte Ltd.
- b) Final Repair Bill of SKM 1361C from M/s Borneo Motors (Singapore) Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKM 1361C
Make & Model	: Toyota Sienta
Year of Registration	: 2018
Chassis Number	: MHFZ28H3400058468



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$2,503.49 (before GST) quoted by M/s Borneo Motors (Singapore) Pte Ltd. is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.

Vehicle Inspection By:

MOHD. RASUL BIN MOHD YUNUS
AMSOE, AMIRTE, AMSAE-A, M. MATAI
Automotive Assessor

ADRIAN LING WAI PING
B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser