

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186

Tel : 6343-0934 Fax : 6343-0921

Email : jmartauto@gmail.com

Registration No: 201400246D

GST Reg. No: 201400246D

CC6/A1G20002888/Ad93

18-Feb-20

Our ref : TP/4818/20

Tan Choon Ngee

TPA/16

Jiale

ACR 50713343

RE : estimate cost for vehicle no : SJU 1798X

1 pc	rear lh railing door <i>Dented</i>		1,635.00	✓
1 pc	rear lh railing door outer moulding <i>Dented</i>		133.00	+
1 pc	rear lh railing outer garnish w/chrome <i>Dented</i>		1350.00	✓ 659
1 pc	rear lh fender <i>rip</i>		855.00	+
1 pc	rear lh fender garnish w/clips <i>pebond</i>		235.00	✓
1 pc	rear bumper <i> Torn</i>		1,600.00	✓ 782
1 pc	rear bumper lh retainer long <i>and</i>	3371	60.00	✓
1 pc	rear bumper lh retainer short <i>and</i>	2528.25	50.00	+
			5,918.00	
			less 25%	
			1,479.50	
			4,438.50	
1 pc	rear lh tyre <i>new</i>	400	300.00	snett +
1 pc	rear lh rim <i>lat</i>		400.00	✓
Panel beating. <i>50</i>			1,000.00	600
Spray painting. <i>1460</i>			1,000.00	780
Transfer door parts.			80.00	
			7,218.50	
			Plus 7% GST	
			505.30	
			7,723.80	

SD : Seven thousand seven hundred twenty-three & cents eighty only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
h/s 18/02/20

05 Days

total 4388.25

h/s: 3510

3510

0. 0

1,635. +

659. +

235. +

782. +

60. =

3,371. *

3,371. x

75. %

2,528.25 *

400. +

=

400. *

600. +

780. +

80. =

1,460. *

2,528.25 +

400. +

1,460. =

4,388.25 *

4,388.25 x

80. %

3,510.6 *

0. 0

L/s - \$3500