

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

Estimate No: ES2090541/AMK
Date: 23 Jul 2020
Policy No: 5089709683-02 DC
Veh Reg No: SLM6373Z
Make/Model: TOYOTA SIENTA 1.5G CVT
Chassis No: NSP1707041204
Engine No: 2NR8642353
Reg. Date: 04/04/2017

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 20/09/2019
TP Veh Reg No: SKX2716Z

Not Authorized
Resurvey After Paint
Delay

Estimate Repair Cost to Vehicle No :SLM6373Z

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	401.20	1 PC	401.20	?
2 REAR BUMPER CENTRE PAD	201.33	1 PC	201.33	✓
3 REAR BUMPER RH SIDE PAD	101.70	1 PC	101.70	✓
4 REAR BUMPER RH REFLECTOR	62.30	1 PC	62.30	?
5 REAR BUMPER CLIP	3.89	8 PC	31.12	?
6 TAILGATE LOGO	69.15	1 PC	69.15	✓
			866.80	
		Less 25%	216.70	650.10
Special Net				
7 REVERSE SENSOR	200.00	1 SET	200.00	X
			200.00	200.00
Labour				
8 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMP, KNOCKING & REPAIR TAILGATE & REALIGN THE SAME	350.00	1 LA	350.00	200/
9 PUTTY & RESPRAY REAR BUMPER, TAILGATE & ALL AFFECTED AREAS	500.00	1 LA	500.00	400/
			850.00	850.00
Total				SS 1,700.10
Add GST @ 7%				119.01
Total Amount Payable				SS 1,819.11

*** SURVEY VEHICLE AT ANG MO KIO WORKSHOP**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE