



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004727
INV Date 06/07/2020
Reference CC4/FCI20002891/Kba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SGH 6381K
Insured Veh. SHA 8738C
Claim No. D20001003MFSH
Policy No. D-20094921MFSH
Accident Date 11/02/2020
Inspection Date 20/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002891/Kba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8738C	Veh. Inspected	SGH 6381K
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20001003MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	20/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100313633	Colour	METALLIC GREY
Odometer	311765	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	8 mm
L/H Front Tyre	195/65 R15	MICHELIN	8 mm
R/H Rear Tyre	195/65 R15	MICHELIN	7 mm
L/H Rear Tyre	195/65 R15	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2020	Inspection Date	20/02/2020
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 6381K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	551.60	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	65.70	-
15	REAR BUMPER CLIPS	NOT NECESSARY	58.35	-
1	REAR BUMPER BRACKET RH	SERVICEABLE	89.77	-
1	TAILLAMP RH	SERVICEABLE	564.70	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	180.70	-
8	REAR FENDER RH COWLING CLIPS	NOT NECESSARY	38.00	-
	LESS 25% DISCOUNT		-387.21	-
			1,161.61	-
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING.	NOT NECESSARY	40.00	-
	TO REMOVE AND REINSTALL /REPLACE REAR BUMPER SENSORS .		60.00	50.00
	TO SPRAY ANTI -RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS .TO KNOCK & REPAIR REAR FENDER RH ,END PANEL,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH AND REAR BUMPER.		500.00	80.00
	TO SPRAY REAR BUMPER ,REAR FENDER RH ,END PANEL.		600.00	200.00
			1,260.00	330.00
	GRAND TOTAL		2,421.61	330.00
	RECOMMENDED COST OF REPAIRS			330.00

Report Ref No. CC4/FCI20002891/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 6381K

INSPECTION





TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 6381K

RE-INSPECTION

