



联立机构(新)有限公司  
LIANNEX CORPORATION (S) PTE LTD.

18, Sungei Kadut Way, Singapore 728789.  
Tel: 6368 2668 Fax: 6367 8866 Email: liannexc@singnet.com.sg  
Company Reg. No: 199304670R

18/2/2020

To : AXA Insurance Pte Ltd  
c/o : Attending surveyor

BY HAND ONLY

Dear Sirs ,

**THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PA 737 M**

Traffic accident on 17/2/20 involving PA 737 M ,YL 8364 M and YP 1758 K along Tampines Avenue 10.

We append below our repair estimate for PA 737 M (Isuzu LT434).

**Parts required :- Net items**

|            |   |         |               |
|------------|---|---------|---------------|
| 1 pc       | Rear centre bumper assy.                          | / CR4.  | \$ 4600.00    |
| 1 pc       | Rear centre bumper structural frame               | / BT    | \$ 1400.00    |
| 1 pc       | Rear underrun bumper                              | X SVC   | \$ 2800.00    |
| 2 pcs      | Rear reverse lamp                                 | X SVC   | \$ 220.00     |
| 2 pcs      | Rear lower signal lamp                            | X SVC   | \$ 220.00     |
| 2 pcs      | Rear taillamp                                     | X SVC   | \$ 1960.00    |
| 1 pc       | Rear centre lid cover assy.                       | / DD    | \$ 4800.00    |
| 4/R 2 1 pc | Rear centre lid cover self retracting hinge assy. |         | \$ 2200.00    |
| 1 pc       | Rear centre lid cover centre chrome moulding      | / Nec   | \$ 290.00     |
| 1 pc       | Rear centre lid cover outer lock                  | / CR4   | \$ 70.00      |
| 1 pc       | Rear centre lid cover inner lock assy             | X SVC   | \$ 310.00     |
| 2 pcs      | Rear centre lid cover damper                      | / BT    | \$ 820.00     |
| 1 pc       | Rear centre lid cover inner heat insulation       | / Nec   | \$ 700.00     |
| 1 pc       | Rear number plate lamp                            | X SVC   | \$ 90.00      |
| 1 pc       | Rear top lid cover assy.                          | / CR4.  | \$ 3200.00    |
| 1 set      | Rear top lid cover hinge                          | X SVC   | \$ 480.00     |
| 1 pc       | Rear top lid cover outer lock (left)              | / CR4   | \$ 50.00      |
| 4 pcs      | Rear air cond. Fan assy.                          | X SVC   | \$ 1960.00    |
|            |   |         | \$26170.00    |
|            | Less 10% trade discount                           |         | \$ 2617.00    |
|            |   |         | \$23553.00    |
| 1 pc       | Sticker ' 60 KM/H '                               | / Nec   | \$ 20.00 s/n  |
| 1 pc       | Rear number pale                                  | / CR4.  | \$ 50.00 s/n  |
| 1 set      | Rear reverse sensor assy.                         | / short | \$ 460.00 s/n |
|            | b.c.f.  |         | \$24133.00    |

...2/-

**LIANNEX CORPORATION (S) PTE LTD**

**PA 737 M**


|  |            |         |
|--|------------|---------|
| b.b.f.   | \$24133.00 |         |
| a. To supply and spray insulation foam on all affected accident parts. <i>7</i>  | \$ 2400.00 | 1,000 ? |
| b. To check wiring system.   | \$ 150.00  | 40      |
| c. To putty and spray painting on rear centre bumper, rear centre lid cover, rear top lid cover, body panel and all affected accident parts including <b>design painting</b> on same. (multi-colour) <i>7. panel - 300</i> | \$ 3200.00 | 2,200   |
| d. To jack out rear chassis frame and cross member. To knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.  | \$ 3500.00 | 2,000   |
| Total repair cost <i>ldy - 300-</i>  | \$33383.00 |         |

**NOTE :-**

The above estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

Parts quoted is subject to 7% GST.

**LIANNEX CORPORATION (s) PTE LTD**

  
David Liang, H/P 96662662  
Claims Consultant

*Repair ldy - 7*

*Lump Sum Repair  
After paint photo*

*Sun Pm CLKC.*

*19/02/2022*

*TP with an proforma*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: