



联立机构(新)有限公司  
LIANNEX CORPORATION (S) PTE LTD.

18, Sungei Kadut Way, Singapore 728789.  
Tel: 6368 2668 Fax: 6367 8866 Email: liannexc@singnet.com.sg  
Company Reg. No: 199304670R

18/2/2020

To : AXA Insurance Pte Ltd  
c/o : Attending surveyor

BY HAND ONLY

Dear Sirs ,

**THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PA 737 M**

Traffic accident on 17/2/20 involving PA 737 M ,YL 8364 M and YP 1758 K along Tampines Avenue 10.

We append below our repair estimate for PA 737 M (Isuzu LT434).

**Parts required :- Net items**

1 pc	Rear centre bumper assy.	/ CR4.	\$ 4600.00	3335	
1 pc	Rear centre bumper structural frame	X SVC	\$ 1400.00	X	
1 pc	Rear underrun bumper	/ BT	\$ 2800.00	2,400	
2 pcs	Rear reverse lamp	X SVC	\$ 220.00	X	
2 pcs	Rear lower signal lamp	X SVC	\$ 220.00	X	
2 pcs	Rear taillamp	X SVC	\$ 1960.00	X	
1 pc	Rear centre lid cover assy.	/ DD	\$ 4800.00	3800	
4/R 2	1 pc	Rear centre lid cover self retracting hinge assy.	X SVC	\$ 2200.00	X
1 pc	Rear centre lid cover centre chrome moulding	/ NEC	\$ 290.00	/	
1 pc	Rear centre lid cover outer lock	/ CR4	\$ 70.00	/	
1 pc	Rear centre lid cover inner lock assy.	X SVC	\$ 310.00	X	
2 pcs	Rear centre lid cover damper	/ BT	\$ 820.00	/	
1 pc	Rear centre lid cover inner heat insulation	/ NEC.	\$ 700.00	500	
1 pc	Rear number plate lamp	X SVC	\$ 90.00	X	
1 pc	Rear top lid cover assy.	/ CR4.	\$ 3200.00	2,800	
1 set	Rear top lid cover hinge	/ BT	\$ 480.00	350	
1 pc	Rear top lid cover outer lock (left)	/ CR4	\$ 50.00	/	
4 pcs	Rear air cond. Fan assy.	X SVC	\$ 1960.00	X	
			\$26170.00	14,415	
	Less 10% trade discount		\$ 2617.00	-10%	
			\$23553.00	12,973.50	
1 pc	Sticker '60 KM/H'	/ NEC	\$ 20.00	s/n /	
1 pc	Rear number pale	/ CR4.	\$ 50.00	s/n /	
1 set	Rear reverse sensor assy.	/ short	\$ 460.00	s/n /	
	b.c.f.		\$24133.00	530	

...2/-

# LIANNEX CORPORATION (S) PTE LTD

PA 737 M


b.b.f.	\$24133.00	
a. To supply and spray insulation foam on all affected accident parts. <i>7 / Nec</i>	\$ 2400.00	1,000
b. To check wiring system.	\$ 150.00	40
c. To putty and spray painting on rear centre bumper, rear centre lid cover, rear top lid cover, body panel and all affected accident parts including design painting on same. (multi-colour) <i>7. panel - 300</i>	\$ 3200.00	2,200
d. To jack out rear chassis frame and cross member. To knock/straighten all necessary parts including repairing and changing of all damaged parts and align same.	\$ 3500.00	2,000
Total repair cost <i>ldy - 300</i>	\$33383.00	5,240

## NOTE :-

The above estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

Parts quoted is subject to 7% GST.

LIANNEX CORPORATION (S) PTE LTD

  
David Liang, H/P 96662662  
Claims Consultant

Repair dly - 7/9

Lump Sum Repair  
After paint photo

Sun Pm CLIC.

19/02/2022

TP with an proforma

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P = 12,973.5  
S/N = 530  
2 = 5,240  
18,743.5  
- 20%  
14,994.80

LIS  
\$15,000  
9 days