

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE:	06/02/20	LOCATION:	Gul Workshop
VEHICLE NO:	XD8406E	Q REF No:	Q20/02/1116
DRIVER:	MOHD ROHIZAT BIN BUANG	DEPARTMENT:	WTS Lorry Crane Department
ATTENTION TO:		ACCIDENT DATE:	05/02/20
PREPARED BY:	Chan Soo Lye	REF No:	JW-0220-172

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	PLAST, FOOTPLATE LHS <i>CR</i>	1	967.4	967.40
Labour Costs				
1	TO REMOVE DAMAGED PARTS AND REPLACE FRONT LHS FOOTPLATE.	1	350	<i>250</i> 350.00
TOTAL:				1,317.40
Total Amount				SGD 1,317.40

Remarks:

[Signature]
Signature of Workshop Dpt

[Signature]
Signature of Department Head

[Signature]
Signature of Claim Department

Surveyor Sign: *[Signature]*

Surveyor Name: *RASUL - HP 90010068*

Date: *28/02/2020*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice"
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date: