

kh

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

M S Motor Pte Ltd
190 Woodlands Industrial Pk E5
#07-17
Singapore 757516

Not Authorised
11 Sep 82150h
Running After Rain
3 days

Vehicle No : SJT 5522 D
Make : Toyota Altis
Year : 2009

2/Sum - \$2,250.00

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

2 pcs	Front headlamp assy	<i>257.80</i>	<i>mm</i>	\$550.10	\$1,100.20	✓
2 pcs	Front fog lamp assy			\$185.20	\$370.40	X
1 pc	Front grille	<i>257.60</i>		<i>nd/dt</i>	\$305.10	7✓
1 pc	Front grille emblem	<i>photo</i>		<i>mm</i>	\$55.70	7✓
1 pc	Front support panel			<i>mm</i>	\$653.20	X
1 pc	Front bumper			<i>mm</i>	\$498.10	✓
1 pc	Front bumper reinforcement			<i>mm</i>	\$385.70	X
2 pcs	Front bumper side retainer			\$55.10	\$110.20	✓
1 pc	Front bumper lower grille	<i>photo</i>		<i>cm</i>	\$175.60	X
					\$3,654.20	
				Less 25 %	\$913.55	
					\$2,740.65	

2,244.90
561.23
1683.67

S Nett Item

1 pc	Front no plate		<i>mm</i>	\$35.00	✓
20 pcs	Front bumper clip		<i>mm</i>	\$2.00	\$40.00
					75

Labour Charges

Remove/renew the above parts. Knock out & reshape front o/s fender inner panel.	\$1,000.00	<i>850</i>
To putty & spray paint front accident affected portion.	\$1,000.00	<i>800</i>
Check/reconnect wiring.	\$20.00	✓
To spray anti rust on accident affected portion.	<i>mm</i>	\$100.00 X
Remove/refit air con condenser & to top up gas element	<i>mm</i>	\$180.00 X
Total	\$5,115.65	

1070