

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 29831

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0180/2020/NS
Date	:	18-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Automobiles Pte Ltd
Address	:	55 Ubi Road 1 Singapore 408699
Telephone	:	+65 6366 2323
Type of Claim	:	Own Damage Claim
Policy No.	:	
Vehicle No	:	SMP 5762 M
Model Code	:	A4 Sedan 2.0 TFSI 8V
Model / Year	:	30/9/2019
Engine No	:	CVK 086099
Chassis No	:	WAUZZZF4XKA104128
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Jan-20
Place of Accident	:	Republic Plaza Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMP 5762 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Chek function and renew according to damage.	S/N \$	360.00 ✓	
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$	300.00 600 ✓	
3	To install rear windscreen solar film.	S/N \$	400.00 X	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00 ✓ photo	✓
5	To remove and reinstall rear seat, back rest, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00 ✓ photo	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,860.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMP 5762 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and transfer lhs rear door's multi-lovk system and power window devices. Inspect for damages.	S/N \$ 280.00 /	✓
7	To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender. To renew lhs rear door. Re-organise crash management components. Reinstall all parts removed. \$00	\$ 6,300.00 4000 3500	✓
8	To respray lhs rear fender, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works. 5.5 x 550	\$ 4,750.00 3025	✓
9	To carry out diagnostic check.	S/N \$ 192.00 /	✓
TOTAL LABOUR CHARGES		: \$ 15,382.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 5762 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	SIDE PANEL - LH / <i>DD</i>	\$ 2,518.00	2014.40
2	REAR WINDSCREEN / <i>MC</i>	\$ 1,085.00	868
3	SIDE WINDOW - LH / <i>MC</i>	\$ 579.00	463.20
4	PRIMER / <i>MC</i>	\$ 19.00	14.80
5	REAR DOOR - LH / <i>DD</i>	\$ 2,243.00	1794.40
6	REAR DOOR OUTER SEAL - LH / <i>MC</i>	NEC \$ 193.00	154.40
7	BONDING AGENT / <i>MC</i>	NEC \$ 46.00	36.72
8	CLEANING SOLUTION / <i>MC</i>	NEC \$ 64.00	X NN
9	SEALING STRIP / <i>MC</i>	\$ 16.00	X NN
10	REAR DOOR CATCH / <i>X</i> Screw loose ✓ NEC	\$ 113.00	90.40 ✓
11	ACRYLIC SEALANT / <i>MC</i>	S/N \$ 180.00	✓
12	CAVITY WAX / <i>MC</i>	S/N \$ 140.00	✓
13	STONE CHIP / <i>MC</i>	S/N \$ 180.00	✓
14	METAL FILLER POWDER / <i>MC</i>	S/N \$ 280.00	✓
15	1/4 GLASS SEALANT / <i>MC</i>	S/N \$ 100.00	✓
16	REAR WINDSCREEN SEALANT / <i>MC</i>	S/N \$ 200.00	✓
17	SUNDRIES ? NEC	\$ 500.00	✓ 25.76
TOTAL SPARE PARTS		: \$ 8,456.00	
TOTAL LABOUR CHARGES		: \$ 15,382.00	
GRAND TOTAL		: \$ 23,838.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

19/2/99, 11:20am
Steve (LKK) OD - Not Authn (Repd)
EXCESS - ?
P/P
Ry Bel ST
12 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant