

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 29177

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/00166/2020/NS  
**Date** : 13-Feb-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Adrian*

*We took 7 DAYS exclude 1 Sunday*

*jb 24 Apr 20*

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms See Mui Kheng Joanna  
**Address** : 781 Upper Changi Road East  
#03-36  
Singapore 486069  
**Telephone** : (HP) 98301888  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1800106939  
**Vehicle No** : **SLB 5577 S**  
**Model Code** : Audi A5 SB 2.0 TFS  
**Model / Year** : 6/9/2018  
**Engine No** : CVK 063501  
**Chassis No** : WAUZZZF53JA107430  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 10-Feb-20  
**Place of Accident** : AYE Near Clementi Ave 6

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLB 5577 S

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To renew 1/4 glass to facilitate fender renewal.	S/N \$ 300.00	\$ 300.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	\$ 1,400.00
5	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	\$ 560.00
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: \$ 4,020.00</b>	<b>\$ 4,020.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLB 5577 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
		C/F		\$ 4,020.00
6	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N	\$ 400.00	
7	To dismantle rear bumper, rear lid, rhs rear door, rhs front door and rhs sill panel trim. Cut out and weld rhs rear fender. To renew rhs front door, rhs rear door, rhs sill panel trim and rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 8,800.00	\$ 4,000.00
8	To respray rear bumper, rhs rear fender, rhs front door, rhs rear door, door handles, door hinges, rhs sill panel trim, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 8,500.00	\$ 4,050.00
9	To renew rhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
10	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 22,192.00</b>	<b>\$ 12,542.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLB 5577 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	SIDE PANEL - RH	\$ 2,354.00	\$ 1,883.20
2	SIDE WINDOW - RH	\$ 676.00	\$ 540.40
3	WHEEL HOUSING LINER - RH	\$ 259.00	
4	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 86.00	
5	REAR BUMPER	\$ 2,385.00	\$ 1,908.00
6	REAR BUMPER FIXING PARTS	\$ 156.00	
7	REAR BUMPER SECURING STRIP	\$ 210.00	
8	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	
9	CHROME TRIM	\$ 958.00	
10	FRONT DOOR - RH	\$ 2,946.00	\$ 2,356.80
11	FRONT DOOR OUTER SEAL	NEC \$ 209.00	\$ 167.20
12	BONDING AGENT	NEC \$ 46.00	\$ 36.72
13	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
14	DOOR ATTACHMENT PARTS	\$ 122.00	
15	FRONT DOOR CATCH	\$ 113.00	
16	DOOR HINGE HALF UPPER PART - RH	\$ 42.00	
17	HINGE HALVES - RH LOWER	\$ 43.00	
18	HINGE HALVES - RH LOWER	\$ 43.00	
19	DOOR HINGE HALF LOWER PART - RH	\$ 71.00	
20	DOOR HANDLE TRIM PLATE - RH	\$ 83.00	
<b>SUB TOTAL SPARE PARTS CHARGES</b>		<b>\$ 10,907.00</b>	<b>\$ 6,943.52</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLB 5577 S

S/N	Parts Description	C/F	Damaged Parts & Prices	
			S/Nett	Remarks
				\$ 6,943.52
21	DOOR HANDLE TRIM - RH		\$ 128.00	\$ 102.40
22	REAR DOOR - RH		\$ 2,946.00	\$ 2,356.80
23	REAR DOOR OUTER SEAL	NEC	\$ 209.00	\$ 167.20
24	BONDING AGENT	NEC	\$ 46.00	\$ 36.72
25	CLEANING SOLUTION	NEC	\$ 64.00	\$ 51.20
26	REAR DOOR CATCH		\$ 113.00	\$ 90.40
27	DOOR HANDLE TRIM PLATE - DRIVER DOOR		\$ 83.00	
28	DOOR HANDLE TRIM - RH		\$ 128.00	
29	LOCK CYLINDER - DRIVER DOOR		\$ 508.00	
30	EXTERIOR DOOR HANDLE - RH		\$ 40.00	
31	DOOR HANDLE SENSOR - RH		\$ 215.00	
32	DOOR TRIM - RH		\$ 150.00	\$ 119.60
33	SIDE MEMBER TRIM - RH		\$ 778.00	
34	SIDE MEMBER ATTACHMENT PARTS		\$ 123.00	\$ 98.00
35	ADHESIVE TAPES		\$ 200.00	\$ 159.60
36	REAR ALUMINIUM RIM - LH		\$ 964.00	\$ 770.80
37	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
38	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
39	STONE CHIP	S/N	\$ 180.00	\$ 180.00
40	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
41	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
42	SUNDRIES		\$ 400.00	\$ 19.76
<b>TOTAL SPARE PARTS CHARGES</b>			<b>\$ 18,882.00</b>	<b>\$ 11,796.00</b>
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 22,192.00</b>	<b>\$ 12,542.00</b>
<b>GRAND TOTAL</b>			<b>\$ 41,074.00</b>	<b>\$ 24,338.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant