

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 29177

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/00166/2020/NS
Date	:	13-Feb-20

Yvonne

24338

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms See Mui Kheng Joanna
Address	:	781 Upper Changi Road East #03-36 Singapore 486069
Telephone	:	(HP) 98301888
Type of Claim	:	Own Damage Claims
Policy No.	:	1800106939
Vehicle No	:	SLB 5577 S
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	6/9/2018
Engine No	:	CVK 063501
Chassis No	:	WAUZZZF53JA107430
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Feb-20
Place of Accident	:	AYE Near Clementi Ave 6

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 5577 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	\$360.00
2	To renew 1/4 glass to facilitate fender renewal.	S/N \$ 300.00 ✓	\$300.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	\$1400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	\$1400.00
5	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 ✓	\$560.00
SUB TOTAL LABOUR CHARGES		: <u>\$ 4,020.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 5577 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 400.00 X	
7	To dismantle rear bumper, rear lid, rhs rear door, rhs front door and rhs sill panel trim. Cut out and weld rhs rear fender. To renew rhs front door, rhs rear door, rhs sill panel trim and rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 8,800.00 4000	\$4000.00
8	✓ To respray rear bumper, rhs rear fender, rhs front door, rhs rear door, door handles, door hinges, rhs sill panel trim, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	4050 \$ 8,500.00	7xSSO = 3850 Handle x 2 = 200 \$4050.00
9	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓	\$280.00
10	To carry out diagnostic check.	S/N \$ 192.00 ✓	\$192.00
TOTAL LABOUR CHARGES		: \$ 22,192.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 5577 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	SIDE PANEL - RH <i>Dented</i>	\$ 2,354.00	✓ <i>\$1883-20</i>
2	SIDE WINDOW - RH <i>new</i>	\$ 676.00	✓ <i>\$540-40</i>
3	WHEEL HOUSING LINER - RH <i>new</i>	\$ 259.00	+
4	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 86.00	+
5	REAR BUMPER <i>Repa torn</i>	\$ 2,385.00	✓ <i>\$1908-00</i>
6	REAR BUMPER FIXING PARTS	\$ 156.00	+
7	REAR BUMPER SECURING STRIP	\$ 210.00	+
8	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	+
9	CHROME TRIM <i>new</i>	\$ 958.00	+
10	FRONT DOOR - RH <i>Dented</i>	\$ 2,946.00	✓ <i>\$2356-80</i>
11	FRONT DOOR OUTER SEAL <i>new</i>	NEC \$ 209.00	✓ <i>\$167-20</i>
12	BONDING AGENT <i>new</i>	NEC \$ 46.00	✓ <i>\$36-72</i>
13	CLEANING SOLUTION <i>NEC</i>	NEC \$ 64.00	✓ <i>\$51-20</i>
14	DOOR ATTACHMENT PARTS <i>new new</i>	\$ 122.00	+
15	FRONT DOOR CATCH <i>new</i>	\$ 113.00	+
16	DOOR HINGE HALF UPPER PART - RH	\$ 42.00	+
17	HINGE HALVES - RH LOWER	\$ 43.00	+
18	HINGE HALVES - RH LOWER	\$ 43.00	+
19	DOOR HINGE HALF LOWER PART - RH <i>new</i>	\$ 71.00	+
20	DOOR HANDLE TRIM PLATE - RH <i>new new</i>	\$ 83.00	+
SUB TOTAL SPARE PARTS CHARGES		: \$	<u><u>10,907.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 5577 S

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
21	DOOR HANDLE TRIM - RH	ut	\$	128.00 ✓	\$102.40
22	REAR DOOR - RH	Dented	\$	2,946.00 ✓	\$2356.80
23	REAR DOOR OUTER SEAL	Nec	NEC \$	209.00 ✓	\$167.20
24	BONDING AGENT	Nec	NEC \$	46.00 ✓	\$36.72
25	CLEANING SOLUTION	Nec	NEC \$	64.00 ✓	\$51.20
26	REAR DOOR CATCH	Nec	\$	113.00 X	\$90.40
27	DOOR HANDLE TRIM PLATE - DRIVER DOOR	Nec	\$	83.00 X	
28	DOOR HANDLE TRIM - RH	Nec	\$	128.00 X	
29	LOCK CYLINDER - DRIVER DOOR	Nec	\$	508.00 X	
30	EXTERIOR DOOR HANDLE - RH	Regis	\$	40.00 ✓	
31	DOOR HANDLE SENSOR - RH	Nec	\$	215.00 X	
32	DOOR TRIM - RH	Nec	\$	150.00 X	\$119.60
33	SIDE MEMBER TRIM - RH	Regis	\$	778.00 X	
34	SIDE MEMBER ATTACHMENT PARTS	Nec	\$	123.00 X	\$98.00
35	ADHESIVE TAPES	Nec	\$	200.00 ✓	\$159.60
36	REAR ALUMINIUM RIM - LH	ut	\$	964.00 ✓	\$770.80
37	ACRYLIC SEALANT	} Nec	S/N \$	180.00 ✓	\$180.00
38	CAVITY WAX		S/N \$	140.00 ✓	\$140.00
39	STONE CHIP		S/N \$	180.00 ✓	\$180.00
40	METAL FILLER POWDER		S/N \$	280.00 ✓	\$280.00
41	1/4 GLASS SEALANT	} Nec	S/N \$	100.00 ✓	\$100.00
42	SUNDRIES		\$	400.00 3	\$19.76

TOTAL SPARE PARTS CHARGES

: \$ 18,882.00

TOTAL LABOUR CHARGES

: \$ 22,192.00

GRAND TOTAL

: \$ 41,074.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adnan Lj

Surveyed Date

: 19/02/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: not authorised, 14 days.

07 Days.

M.S.

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant