

## ...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Feb 2020		19 Feb 2020 18:10 <a href="#">Edit Adj Rpt</a>	<b>S\$5,050.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,050.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>TITANIUM LIMOUSINES PTE. LTD.,</b> Co. Reg. No.: 201213055R									
Vehicle Reg. No.: <b>SLN4199T</b>		Date of Loss: 10/02/2020 18:00 - :59 [33 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM20D200873</b>		Policy/Cover Note No.: DMB1SN15211419044							
Vehicle Reg. No. (Insured): <b>CB6951U</b>		Policy No. (Claimant): 5108520702							
		Excess: S\$0.00							
Repairer: <b>Team Autopro Pte Ltd (Sin Ming)</b> 385 Sin Ming Drive, #01-02 Vicom Inspection Centre, 575718 Sin Ming - Tel: 62581955									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Cecilia Low</b> - 63896530]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 28/02/2020]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLN4199T (SNM20D200873)  
[CB6951U]  
TP  
TITANIUM LIMOUSINES PTE. LTD.  
Feb 10 2020 6:00PM  
[-]  
Team Autopro Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	23/03/20 09:04	General View					 Load PDF		

## Linked Accident Report Documents

<b>Assessment Reports</b>										View <input type="button" value="View in Browser"/>	
										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)								Thumbnail	Print
1	12/02/20 17:56	Accident Statement									Load HTM
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)								Thumbnail	Print
1	12/02/20 17:54	Accident Photo									Load JPG
2	12/02/20 17:54	Accident Photo									Load JPG
3	12/02/20 17:54	Accident Photo									Load JPG
4	12/02/20 17:54	Accident Photo									Load JPG
5	12/02/20 17:54	Accident Photo									Load JPG
6	12/02/20 17:54	Accident Photo									Load JPG
7	12/02/20 17:54	Accident Photo									Load JPG
8	12/02/20 17:54	Accident Photo									Load JPG
9	12/02/20 17:54	Accident Photo									Load JPG
10	12/02/20 17:54	Accident Photo									Load JPG
11	12/02/20 17:54	Accident Photo									Load JPG
12	12/02/20 17:54	Accident Photo									Load JPG
13	12/02/20 17:54	Accident Photo									Load JPG
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)								Thumbnail	Print
1	12/02/20 17:53	Sketch Plan									Load TIF
2	12/02/20 17:53	Sketch Plan #2									Load TIF
3	12/02/20 17:54	Common Statement									Load TIF
4	12/02/20 17:54	Common Statement									Load TIF
5	12/02/20 17:54	Common Statement									Load TIF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002907/BVF3E2

Date: 31/03/2020

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN15211419044  
Claimant Vehicle No: SLN4199T Insured Vehicle No: CB6951U  
Date of Loss: 10/02/2020 Nature of Claim: TP Claim No: SNM20D200873

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLN4199T Engine No: 65492080052921  
Make & Model: MERCEDES-BENZ E220, 2.0 (A) Chassis No: WDD2130042A116221  
Reg. Date: 03/05/2017 (Man. Year: 2016) Odometer: 196453 km  
Colour: Black  
Engine Capacity: 1950 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,444.51	5,497.88	2,946.63	34.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	860.00	1,000.00	53.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,304.51</b>	<b>6,357.88</b>	<b>3,946.63</b>	<b>38.30</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,304.51</b>	<b>5,050.00</b>	<b>5,254.51</b>	<b>50.99</b>

## INSPECTION

Date of Assignment: 19/02/2020  
Date Inspected: 20/02/2020 Inspected At: Team Autopro Pte Ltd  
160 SIN MING DR  
#01-14 SIN MING AUTO CITY  
SINGAPORE 575722  
Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2020)
<b>Parts:</b> 143	MERCEDES-BENZ E220 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN4199T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	3,284.00 FL	*3,037.82 FL
2	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	215.00 FL	*- FL
3	1		*HEADLAMP PANEL LH	Not Damaged	285.20 FL	*- FL
4	1		*FRONT BUMPER	Cut	2,657.00 FL	*1,662.71 FL
5	1		*FRONT BUMPER LOWER	Not Damaged	327.00 FL	*- FL
6	2		*FRONT BUMPER RETAINER	Necessary	344.00 FL	*164.00 FL
7	1		*FRONT FENDER LH	Dented	922.00 FL	*922.00 FL
8	1		*FRONT FENDER INNER SHIELD LH	Not Damaged	218.70 FL	*- FL
9	1		*FRONT BUMPER CARRIER	Not Damaged	241.00 FL	*- FL
10	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
11	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
12	2		*FRONT BUMPER SENSORS	Cut	500.00 FS	*200.00 FS
13	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
14	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,293.90</b>	<b>6,076.53</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	849.39	578.65
<b>Total Parts (\$\$)</b>	<b>8,444.51</b>	<b>5,497.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	RUST PROOFING	New	80.00	40.00
3	SPRAY PAINTING	New	800.00	400.00
4	CHECK WIRING	New	80.00	20.00
5	RESET AND RE-PROGRAMME FAULT CODE	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,860.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >