

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Date: 30/01/2020

Policy No. A28795104

MSIG Insurance (Singapore) Pte Ltd
Motor Claims Department
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Owner: SKYWAY MOTOR PTE LTD

Not Notarized
11 Rm @ 18,000/-
Repair After Paint

28 days

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR1766E

1pc	rear tailgate	R	\$ 1,100.90	✓
1pc	rear tailgate spoiler	MS	\$ 720.20	✓
2pcs	rear tailgate hinge @\$53.60	R	\$ 107.20	X
1pc	rear tailgate "HONDA" logo	MS	\$ 27.00	✓
1pc	rear tailgate "VEZEL" emble	MS	\$ 55.10	✓
1pc	rear tailgate "HYBRID" emblem	MS	\$ 68.50	✓
1pc	rear tailgate windscreen glass	Shatter	\$ 1,150.00	✓
1set	rear tailgate windscreen moulding	MS	\$ 120.00	✓
2pcs	rear tailgate number plate lamp @\$38.50	MS	\$ 77.00	X
1pc	rear tailgate outer garnish	MS	\$ 220.30	✓
1pc	rear tailgate outer handle sensor	MS	\$ 240.30	X
2pcs	rear tailgate reflector @\$350.80	CM	\$ 701.60	✓
1pc	rear tailgate inner lock	Ju	\$ 198.40	✓
1pc	rear tailgate inner rubber	MS/MS	\$ 135.20	✓
1pc	rear tailgate inner garnish	MS	\$ 252.70	✓
1pc	rear tailgate inner handle garnish	MS	\$ 20.70	X
2pcs	rear tailgate inner side garnish @\$100.40	MS/MS	\$ 200.80	✓
1pc	rear tailgate inner top garnish	MS	\$ 120.30	✓
1pc	rear tailgate wiper motor	Ju	\$ 250.90	✓
2pcs	rear tailgate absorber @\$180.90	MS	\$ 361.60	X
2pcs	rear taillamp @\$460.60	CM	\$ 921.20	✓
2pcs	rear taillamp panel @\$156.20	MS/MS	\$ 312.40	4
2pcs	rear taillamp inner panel @\$195.90	MS/MS	\$ 391.80	4
1pc	rear bumper	MS	\$ 986.30	✓
2pcs	rear bumper side bumper @\$195.20	MS	\$ 390.40	✓
2pcs	rear bumper side retainer @\$24.80	MS	\$ 49.60	✓
2pcs	rear bumper reflector @\$151.50	CM	\$ 303.00	✓
1pc	rear end panel	MS	\$ 530.90	✓
1pc	rear end panel inner garnish	MS	\$ 109.90	✓
1pc	rear end panel inner sensor	CM	\$ 195.50	2
1pc	rear end panel outer sensor	CM	\$ 180.25	2

Balance c/f

\$ 10,499.95



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Date: 30/01/2020

Policy No. A28795104

MSIG Insurance (Singapore) Pte Ltd
Motor Claims Department
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR1766E

	Balance b/f		\$ 10,499.95	
2pcs	rear fender @\$950.90	Bu	\$ 1,901.80	✓
2pcs	rear fender inner garnish @\$321.90	cls D.I	\$ 643.80	✓
2pcs	rear fender inner trim @\$125.10	cls D.I	\$ 250.20	2+
2pcs	rear fender protector @\$150.00	cls M.I N/S Bu	\$ 300.00	✓
1pc	rear spare tyre panel	Bu	\$ 1,130.60	✓
1pc	rear spare tyre cardboard	Sn	\$ 350.40	✓
1pc	rear spare tyre inner garnish	Sn	\$ 285.50	✓
1pc	rear spare tyre inner garnish base	Sn	\$ 420.80	✓
1pc	rear spare tyre lower garnish	D.I	\$ 181.90	✓
1pc	rear hybrid battery	Sn	\$ 8,350.00	✓
1pc	rear exhaust box	Bu	\$ 850.10	✓
1pc	rear exhaust box top cover	R	\$ 150.80	✓
2pcs	rear exhaust box mounting @\$38.50	Tu	\$ 77.00	✓
1pc	rear RH door	R	\$ 950.50	✓
1pc	rear RH door frame sticker	Sn	\$ 95.00	✓
1pc	rear RH door inner lock	R	\$ 191.50	✓
1pc	front bonnet	Bu	\$ 892.30	✓
2pcs	front bonnet hinge @\$65.80	D.I	\$ 131.60	✓
1pc	front bonnet inner lock	D.I	\$ 87.70	✓
1pc	front bonnet lock side garnish	CM	\$ 85.00	✓
2pcs	front headlamp @\$1759.40	cls Bu N/S CM	\$ 3,518.80	✓
2pcs	front headlamp lower bracket @\$35.00	CM	\$ 70.00	✓
2pcs	front headlamp top bracket @\$28.85	\$ M.I	\$ 57.70	✓
1pc	front centre grille base	CM	\$ 542.20	✓
1pc	front centre grille chrome	CM	\$ 108.00	✓
1pc	front centre grille outer garnish	CM	\$ 385.00	✓
1pc	front centre grille "HONDA" logo	M	\$ 58.85	✓
1pc	front bumper	Bu	\$ 927.50	✓
2pcs	front bumper side retainer @\$21.70	D.I	\$ 43.40	✓
1pc	front bumper grille	D.I	\$ 260.00	✓
	Balance c/f		\$ 33,797.90	



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Date: 30/01/2020

Policy No. A28795104

MSIG Insurance (Singapore) Pte Ltd
Motor Claims Department
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR1766E

	Balance b/f		\$ 33,797.90	
1pc	front bumper reinforcement	R1	\$ 321.50	✓
2pcs	front bumper RH fog lamp	mgcar	\$ 285.85	✓
1pc	front bumper RH fog lamp base	DI1	\$ 80.25	✓
2pcs	front bumper RH fog lamp cover	DI1	\$ 85.58	✓
1pc	front support panel	R1	\$ 676.20	✓
1pc	front support panel top garnish	Refarm	\$ 95.00	✓
2pcs	front support panel side garnish @\$75.85	ols cm	\$ 151.70	✓
1pc	front air con condenser	R1	\$ 668.10	✓
1pc	front air con condensor pipe 1	Sn	\$ 185.50	✓
1pc	front air con condensor pipe 2	Sn	\$ 190.50	✓
1pc	front air con condensor cowling	Sn	\$ 195.50	✓
1pc	front air con condensor motor	Sn	\$ 285.25	✓
1pc	front air con condensor motor fan	Sn	\$ 98.25	✓
1pc	front air con compressor	Sn	\$ 1,250.50	✓
1pc	front air con condensor pipe	Sn	\$ 190.50	✓
1pc	front radiator	Sn	\$ 1,250.60	✓
1pc	front radiator cowling	Sn	\$ 190.25	✓
1pc	front radiator motor	Sn	\$ 280.50	✓
1pc	front radiator motor fan	Sn	\$ 95.20	✓
1pc	front HYBRID water pump	Sn	\$ 850.50	✓
1pc	front ABS pump	cm	\$ 2,850.50	✓
1pc	front RH engine mounting	cm	\$ 290.80	✓
1pc	front windscreen glass	cm	\$ 1,850.50	✓
1set	front windscreen glass moulding	Sn	\$ 180.50	✓
1pc	front wiper garnish	DI1	\$ 325.20	✓
2pcs	front wiper garnish side cover @\$55.00	Sn	\$ 110.00	✓
1pc	front wiper tank	DI1	\$ 281.20	✓
1pc	front wiper tank motor	Sn	\$ 185.50	✓
1pc	front air chamber	Sn	\$ 123.25	✓
1pc	front dashboard	Sn	\$ 2,850.50	✓
	Balance c/f		\$ 50,273.08	



辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Date: 30/01/2020

Policy No. A28795104

MSIG Insurance (Singapore) Pte Ltd
Motor Claims Department
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLR1766E

	Balance b/f			\$ 50,273.08
2pcs	front fender @\$580.00	old Bn	new Bn	\$ 1,160.00 ✓
2pcs	front fender protector @\$195.00	old		\$ 390.00 ✓
1pc	front fender RH inner shield	su		\$ 195.20 X
10pcs	front fender RH inner shield clip @\$5.00	an		\$ 50.00 X
				\$ 52,068.28
	less 20%			
				\$ 10,413.66
				\$ 41,654.62
1set	rear reverse sensor	old	s.nett	\$ 280.00 2000
1pc	rear reverse camera	su	s.nett	\$ 350.00 X
1set	front & rear number plate @\$50.00	old	s.nett	\$ 100.00 9000
	remove & refix rear hybrid battery & reset ECU			\$ 480.00 3500
	remove & refix front/rear windscreen glass			\$ 240.00 ✓
	remover & refit petrol tank			\$ 250.00 600
	remover & refit cushion			\$ 220.00 1200
	car-on-liner			\$ 250.00 ✓
	wiring			\$ 350.00 1800
	sealant NEC			\$ 160.00 8000
	spray painting			\$ 2,800.00 2200
	labour charges			\$ 2,200.00 2100
	Total			
				\$ 49,334.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

