



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMN 3247 H

Parts	(a) Cost / List Price Items	\$	3,309.00
	Plus/Less 20%	\$	661.80
	Total of Cost / List	\$	2,647.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	2,942.20
Labour		\$	2,230.00
Total		\$	5,172.20

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/2/20 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 25/2/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com

Spare Parts

Vehicle No. : **SMN 3247 H**
Make & Model : **HONDA FREED**
Chassis No : **GB71072761**

Submit By : _____
Year Manufacture : _____
Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price
1	Rear windscreen moulding	1	\$120.00	✓
2	Rear windscreen sealant	1	\$50.00	S.N 405a
3	Reverse sensor	1	\$200.00	S.N 7
4	Rear number plate	1	\$45.00	S.N X
5	Rear No.plate lamp LH	1	\$38.50	X
6	Rear No.plate lamp RH	1	\$38.50	X
7	Rear bumper	1	\$925.00	✓
8	Rear bumper clip	10	\$35.00	✓
9	Rear bumper side retainer LH	1	\$34.90	X
10	Rear bumper side retainer RH	1	\$34.90	X
11	Rear bumper reflector LH	1	\$45.80	X
12	Rear bumper reflector RH	1	\$45.80	X
13	Tail door	1	\$1,100.00	✓
14	Tail door lock	1	\$157.10	X
15	Tail door emblem	1	\$35.50	✓
16	Wording "FREED"	1	\$65.00	✓
17	Wording "HYBRID"	1	\$75.00	✓
18	Tail door trim	1	\$355.00	X
19	Tail door trim clip	10	\$35.00	X
20	Boot weatherstrip	1	\$168.00	X
21				
22				
23				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SMN 3247 H** Submit By : **Carmen Lim**
Make & Model : **0** Year of Manufacture : **2019**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$800.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$800.00	600
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$100.00	30
4	To remove & refit rear windscreen.	\$120.00	✓
5	To transfer boot mechanism to new boot	\$120.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.