

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEL KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 8666 FAX NO.6386 8862
 CO/GST REG NO.201019626G
SHB 9753X - AIG

Not Attached
1-B1

Andrea

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer :

SHB 9753X - Andrea
VF1ABL15AUC273225
RENAULT
LATITUDE
31.12.2013 02.01.2015
AIG

PART			LIST	
1	1	BUMPER COVER REAR L70Y	\$	<i>Ref 1/2/21</i> 561.70 ✓ ✓
2	1	BUMPER LOWER REAR L70D	\$	<i>C 121</i> 389.60 ✓ ✓
3	1	BUMPER BRACKET CTR REAR L70Y	\$	<i>121</i> 57.50 ✓ ✓
4	1	BUMEP R BRACKET SIDE LH REAR L70Y	\$	<i>R1</i> 68.90 ✓ ✓
5	1	BUMEP R RETAINER LH REAR L70Y	\$	<i>C 121</i> 22.80 ✓ ✓
6	1	BUMEP R BRACKET SIDE RH REAR L70Y	\$	<i>R1 C 121</i> 68.90 ✓ ✓
7	1	BUMEP R RETAINER RH REAR L70Y	\$	<i>C 121</i> 22.80 ✓ ✓
8	1	BUMPER REFLECTOR LH L70Y	\$	<i>any 011</i> 22.10 ✓ ✓
9	1	BUMPER REFLECTOR RH L70Y	\$	<i>R1</i> 22.10 ✓ ✓
10	1	BUMPER BRACKET KIT REAR L70Y	\$	<i>C 121</i> 132.10 ✓ ✓
11	1	BUMPER BEAM REAR L70Y	\$	<i>121</i> 394.00 ✓ ✓
12	1	BUMPER BEAM BRACKET LH REAR L70Y	\$	<i>R1</i> 114.50 ✓ ✓
13	1	BUMPER BEAM BRACKET RH REAR L70Y	\$	<i>R1</i> 114.50 ✓ ✓
14	1	BUMEP R BLOCK LH REAR L70Y	\$	76.10 ? } <i>SVL</i>
15	1	BUMEP R BLOCK RH REAR L70Y	\$	76.10 ? } <i>SVL</i>
16	1	EXHAUST REAR L70Y	\$	<i>121</i> 1,365.60 ✓ ✓
17	1	EXHAUST CAP REAR L70Y	\$	116.80 ? <i>SVL</i>
18	1	BOOT REAR L70D	\$	<i>R1</i> 1,455.70 ✓ ✓
19	2	BOOT RUBBER PLUG L70D	\$	<i>R1</i> 112.40 X
20	1	BOOT FINISHER L70Y (Moulding)	\$	<i>R1</i> 238.20 X
21	1	LICENCE PLATE LAMP L70Y LH	\$	<i>R1</i> 25.60 X
22	1	LICENCE PLATE LAMP L70Y RH	\$	<i>R1</i> 25.60 X
23	1	BOOT SWITCH L70Y	\$	<i>R1</i> 85.20 X
24	1	BOOT LOCK L70Y	\$	<i>R1</i> 102.70 ✓ ✓
25	1	BOOT LOCK CATCH L70Y	\$	<i>R1</i> 37.70 ✓ ✓
26	1	BOOT STRUT LH	\$	<i>R1</i> 139.90 X
27	1	BOOT STRUT RH	\$	<i>R1</i> 139.90 X
28	1	BOOT BUFFER LH	\$	<i>R1</i> 19.10 X
29	1	BOOT BUFFER RH	\$	<i>R1</i> 19.10 X
30	1	BOOT LOCK LINKAGE L70Y	\$	17.50 ? } <i>SVL</i>
31	1	BOOT LOCK LINKAGE HOLDER L70Y	\$	78.30 ? } <i>SVL</i>

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42, SUNGAI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 8666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9753X - AIG

Andrea

32	1	BOOT TRIM BOARD L70Y	\$	Br 463.60 X
33	1	BOOT LOCK CATCH TRIM BOARD L70Y	\$	" 126.30 X
34	1	BOOT WHEATERSTRIP L70Y	\$	P/S/L 163.70 ✓
35	1	BOOT REFLECTOR LAMP LH L70Y	\$	C/L 250.00 ✓
36	1	BOOT REFLECTOR LAMP RH L70Y	\$	C/R 250.00 ✓
37	1	BOOT HINGE LH L70Y	\$	R 186.40 X
38	1	BOOT HINGE RH L70Y	\$	R 186.40 X
39	1	BOOT BADGE 'RENAULT'	\$	R 114.20 ✓
40	1	BOOT BADGE	\$	R 114.20 ✓
41	1	FENDER PANEL REAR LH L70Y	\$	Br 1,671.80 ✓
42	1	FUEL FLAP L70Y	\$	R 174.10 X
43	1	TAILLAMP LH L70Y	\$	C/L 280.00 ✓
44	1	TAILLAMP PANEL LH L70Y	\$	R 460.00 X
45	1	WHEELARCH REAR LH L70Y	\$	Se 275.40 X
46	1	FENDER PANEL REAR RH L70Y	\$	Br 1,671.80 ✓
47	1	TAILLAMP RH L70Y	\$	C/R 280.00 ✓
48	1	TAILLAMP PANEL RH L70Y	\$	R 460.00 ✓
49	1	WHEELARCH REAR RH L70Y	\$	Se 275.40 X
50	1	AIR VENT	\$	Se 49.30 ✓
51	1	WINDSCREEN REAR L70Y	\$	Se 741.50 X
52	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Br/Br 1,109.70 ✓
53	1	SPARE WHEEL PANEL INNER TRIM	\$	Br/Br 480.50 ✓
54	1	WHEEL SIDE PANEL BRACKET RH (Luggage Floor	\$	Se 61.50 ✓
55	1	OUTER PANEL REAR L70Y (End Panel)	\$	R 745.80 ✓
56	1	OUTER PANEL REAR L70Y (End Panel) TRIM	\$	R 205.00 ✓
57	1	FENDER WHEEL HOUSE PANEL INNER RR RH	\$	1,728.00 ✓
58	1	FENDER WHEEL HOUSE PANEL INNER RR LH	\$	1,728.00 ✓
59	1	SPARE TYRE BOARD	\$	600.00 ✓
60	1	FENDER INNER BOARD LH L70Y	\$	Br/Br 503.90 ✓
61	1	FENDER INNER BOARD RH L70Y	\$	Br/Br 503.90 ✓
62	1	CHASSIS PANEL RR RH L70Y (EXT RR RH SIDE)	\$	206.60 ✓
63	1	CHASSIS PANEL RR LH L70Y (EXT RR RH SIDE)	\$	206.60 ✓
64	1	FUEL FLAP (DOOR)	\$	R 174.10 X
65	1	DOOR PANEL REAR RH L70Y	\$	R 1,441.50 X
66	1	DOOR PANEL REAR LH L70Y	\$	R 1,441.50 X

TOTAL	\$	25,453.70
10%	\$	2,545.37
	\$	22,908.33

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42, SUNGAI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 9753X - AIG

Andrea

Specical Nett

1SET	PARKING AID L70Y	\$	600.00 ✓✓
1SET	REAR BUMPER CLIP	\$	rec 60.00 ✓✓
1SET	BUMPER BRACKET CTR CLIP (Necessary)	\$	rec 30.00 ✓✓
1SET	BUMPER LOWER REAR RIVET (Necessary)	\$	rec 20.00 ✓✓
1SET	BUMPER LOWER REAR CLIP (Necessary)	\$	rec 60.00 ✓✓
1SET	BUMPER BEAM BOLT	\$	rec 30.00 ✓✓
2	EXHAUST NUT L70Y	\$	8.00 } 3svc
2	EXHAUST SCREW L70Y	\$	18.60 }
1	EXHAUST MOUNTING REAR L70Y	\$	Tr 16.20 ✓✓
1	EXHAUST BRACKET REAR L70Y	\$	20.20 } 3svc
1SET	SCREW	\$	34.00 }
1SET	BOOT FINISHER NUT L70Y (Necessary)	\$	rec 13.60 ✓✓
2	BOOT LOCK SCREW	\$	12.00 } 3svc
2	BOOT LOCK CATCH SCREW	\$	13.80 }
1SET	BOOT TRIM BOARD CLIP L70Y (Necessary)	\$	rec 15.00 ✓✓
1SET	BOOT HINGE BOLT L70Y	\$	rec 49.00 X
2SET	WHEELARCH CLIP (Necessary)	\$	rec 60.00 X
2	WINDSCREEN SEALANT	\$	rec 147.90 60ml ✓
1	CAP HUB RH FRT	\$	rec 35.60 X
1	RIM (ROUE 7J 16H 2547) RH FRT	\$	rec 350.00 X
1	TYRE RH FRT	\$	rec 300.00 X
1	CAP HUB LH FRT	\$	rec 35.60 X
1	RIM (ROUE 7J 16H 2547) LH FRT	\$	rec 350.00 X
1	TYRE LH FRT	\$	rec 300.00 X
2	DOOR STICKER "6555-3333"	\$	rec 160.00 X

TOTAL	\$	2,739.50
--------------	-----------	-----------------

TOTAL PARTS	\$	25,647.83
--------------------	-----------	------------------

Towing Fees.

\$

120.00 50/ ✓

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And Renewal
 Of Parts, Adjust And Realign The Same

\$

2800/ ✓
5,600.00

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO:6287 6666 FAX NO:6366 8862
 CO/GST REG NO.201019626G
 SHB 9753X - AIG

Andrea

To Rust-Proofing Of The Affected Areas.	\$	170.00	150 ✓
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1600 ✓
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	280 ✓
To reinstall rear bumper parking sensor.	\$	170.00	60 ✓
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	} 120 ✓
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	
To transfer of fender fittings and conduct water seepage test.	\$	170.00	} 150 ✓
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	} 200 ✓
To repair and realign rear exhaust pipe.	\$	170.00	
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60 ✓
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment.	\$	220.00	60 ✓
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	X

Andrea

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGAI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHB 9753X - AIG

TOTAL	\$	14,570.00
Over All Total	\$	40,217.83

Repair Days**20 Days**
(PARTS BY PARTS)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: