


SUB TOTAL			\$ 81.60
Labour Charge			
Panel Beating	1	\$ 800.00	\$ 800.00
Spray Painting Charge	1	\$ 800.00	\$ 800.00
Wiring Charge	1	\$ 150.00	\$ 150.00
Tuff Kote	1	\$ 150.00	\$ 150.00
Towing Charge	1	\$ 60.00	\$ 60.00
Remove/Refix Radiator	1	\$ 90.00	\$ 90.00
Remove/Refix Aircon & Refill Gas	1	\$ 150.00	\$ 150.00
TOTAL LABOUR			\$ 2,200.00
ESTIMATE TOTAL			\$ 19,693.92
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

600/-
600/-
30/-
30/-
122
122

18/02/2020 e 1708WS
 NA Andrew
 1/3000
 6 days.
 8643.80
 Supp 64.40
 8708.20
 4/s 6900/-
 Ryan
 LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 19-Feb-20

INSURANCE: komac

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA8694U

Description	Qty	List Price	Amount
FRONT BUMPER GRILLE AIR DUCT <i>broken</i> 80.50	1	\$167.80	\$ 167.80
SUB TOTAL			\$ 167.80
LESS 20%			\$ 33.56
DISCOUNTED TOTAL			\$ 134.24
ESTIMATE TOTAL			\$ 134.24

64.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared

J yan
2kk Auto 20/02/2020
