

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 13-Feb-20

INSURANCE: Lonpac

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA8694U

Description	Qty	List Price	Amount	
Bonnet <i>Detail</i>	1	\$ 2,253.80	\$ 2,253.80	
Bonnet Rubber (RH) <i>NH</i>	1	\$ 12.40	\$ 12.40	
Bonnet Hinge (RH) <i>NH</i>	1	\$ 118.70	\$ 118.70	
Bonnet Lock <i>NH</i>	1	\$ 127.30	\$ 127.30	
Bonnet Absorber <i>NH</i>	1	\$ 35.70	\$ 35.70	
Bonnet Insulator <i>NH</i>	1	\$ 230.10	\$ 230.10	
Bonnet Seal <i>NH</i>	1	\$ 38.30	\$ 38.30	
Bonnet Insulator Clips <i>NH</i>	1	\$ 8.40	\$ 8.40	
Radiator Grille <i>CRACK</i>	1	\$ 1,227.50	\$ 1,227.50	
Front Bumper Cover <i>trim</i>	1	\$ 418.30	\$ 418.30	
Front Bumper Grille (RH) <i>cut</i>	1	\$ 186.90	\$ 186.90	
Front Bumper Towing Cover <i>trim</i>	1	\$ 29.00	\$ 29.00	
Front Bumper Moulding Centre Upper (LH/RH) <i>trim cut</i>	2 1	\$ 108.50	\$ 217.00	
Front Bumper Lower Stiffener <i>NH</i>	1	\$ 85.10	\$ 85.10	
Front Bumper Lip <i>NH</i>	1	\$ 135.10	\$ 135.10	
Front Bumper Bracket Top (LH/RH) <i>NH</i>	2	\$ 35.00	\$ 70.00	
Front Bumper Bracket (LH/RH) <i>o/s broken N/S NH</i>	2	\$ 28.00	\$ 56.00	
Front Bumper Side Bracket Support <i>NH</i>	2	\$ 12.00	\$ 24.00	
Front Bumper Clips 10 pcs <i>NH</i>	1	\$ 22.00	\$ 22.00	
Front Bumper Strip Assy <i>NH</i>	1	\$ 29.40	\$ 29.40	
Headlamp Support Panel Assy <i>CRACK / distorted</i>	1	\$ 949.30	\$ 949.30	
Headlamp (LH/RH) <i>o/s broken N/S CRACK</i>	2	\$ 3,987.30	\$ 7,974.60	
Headlamp Halogen Bulb (LH/RH) <i>NH</i>	2	\$ 14.40	\$ 28.80	
Day Light ,LH <i>NH</i>	1	\$ 642.50	\$ 642.50	
Day Light , RH <i>cut / missing broken</i>	1	\$ 642.50	\$ 642.50	
Day Light Wire, RH <i>NH</i>	1	\$ 585.50	\$ 585.50	
BUZZER ASSY - PIEZO (RH) <i>NH</i>	1	\$ 388.00	\$ 388.00	
Front Fender (RH) <i>Detail</i>	1	\$ 490.70	\$ 490.70	
Front Fender Shield (LH/RH) <i>o/s deformed N/S NH</i>	2	\$ 114.70	\$ 229.40	
Front Fender Retainer <i>NH</i>	2	\$ 41.40	\$ 82.80	
Wiper Container <i>o/s deformed</i>	1	\$ 356.70	\$ 356.70	
Wiper Container Motor <i>NH</i>	1	\$ 267.50	\$ 267.50	
Wiring-Front <i>NH</i>	1	\$ 3,802.10	\$ 3,802.10	
SUB TOTAL			\$ 21,765.40	
LESS 20%			\$ 4,353.08	
DISCOUNTED TOTAL			\$ 17,412.32	
Emblem-Blue Drive (LH/RH) <i>New</i>	NETT	1	\$ 26.60	\$ 26.60
Front Number Plate <i>NH</i>	NETT	1	\$ 25.00	\$ 25.00
Front No Plate Trim Cover <i>NH</i>	NETT	1	\$ 30.00	\$ 30.00


SUB TOTAL			\$ 81.60
Labour Charge			
Panel Beating	1	\$ 800.00	\$ 800.00 600/-
Spray Painting Charge	1	\$ 800.00	\$ 800.00 600/-
Wiring Charge	1	\$ 150.00	\$ 150.00 30/-
Tuff Kote	1	\$ 150.00	\$ 150.00 30/-
Towing Charge	1	\$ 60.00	\$ 60.00 12/-
Remove/Refix Radiator	1	\$ 90.00	\$ 90.00 12/-
Remove/Refix Aircon & Refill Gas	1	\$ 150.00	\$ 150.00 12/-
TOTAL LABOUR			\$ 2,200.00
ESTIMATE TOTAL			\$ 19,693.92
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

18/02/2020 e 1708WS

NA Authnd

1/sum

4 days.



LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: