

Not Notarised
1/ Sep 8 2020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

AAD2002-114

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident : 19 FEB 2020

Third Party Insurer :

Date of Registration:

SHF 620J

VF1ABL15AUC278507

RENAULT

LATITUDE

17.2.2020

AIG

27/6/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER BRACKET FRT RH
1	TOW COVER FRT
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	BONNET
1	WIPER RESERVOIR MOTOR
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK

	LIST	
\$	Bul	747.20 ✓
\$	SL	344.70 X
\$	SL	394.68 X
\$	Di	101.40 ✓
\$	SL	10.70 X
\$	SL	292.50 X
\$	SL	147.00 X
\$	SL	207.21 X
\$	N	663.70 X
\$	Cut	743.60 ✓
\$	N	437.10 ✓
\$	SL	191.40
\$	SL	11.80
\$	SL	106.40
\$	SL	60.90
\$	SL	969.90
\$	SL	225.36 X
\$	SL	686.00
\$	SL	592.70
\$	N	41.60
\$	N	1,312.70
\$	SL	82.60
\$	SL	179.60
\$	SL	29.30
TOTAL	\$	8,580.05
10%	\$	858.01

Trans-cab Auto Services Pte Ltd

AAD2002-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

		\$	7,722.05	
Special Nett				
1 BUMPER CLIP FRT	\$	nn	66.00	✓
1 BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	} X
1 BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1 BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2 FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
1 WHEELARCH CLIP FRT RH	\$	nn	30.50	
1 FRONT RIGHT TYRE	\$	sh	300.00	
1 FRONT RIGHT TYRE RIM	\$	sh	380.00	
1SET Front licence plate with holder	\$	sh	80.00	
1SET RADIATOR GRILLE SCREW	\$	sh	16.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	
TOTAL	\$		1,136.00	
TOTAL PARTS	\$		8,858.05	

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J**AAD2002-114**

To rust-proofing of the affected areas.	\$	170.00	301
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
TOTAL	\$	14,000.00	
Over All Total	\$	22,858.05	

LUMP SUM (REPAIR DAY)**20 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: