

ASS. REC. BY:

REF: CS/SMD 20002938/0413

Special Instruction:

Surveyor: marcus**ASSIGNMENT (Office)**From (Person): Grace Tso

of

SMDDate/Time: 20.2.2020 12.09 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMA 8361X

Insured:

GBH 60535at Workshop m/s Fastrich

Tel:

6746 5405of 1 - 100% BUILT BY 6 101 46/48/50

Policy No:

Claim No:

CMTD20000790 / RUC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19.2.2020**CA / REV / REP. / REV 24 HRS**

ny

H.O.D. Endorsement:

Date/Time: 20/2/2020 3.42 p.m

Person Contacted:

Shirley

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMA 8361X - X</u>
	<u>GBH 60535 - X</u>
<u>21/2-</u>	<u>sent pending estimate via email</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Sms/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Rear solar film

28/1/20 1/5 6850 confirmed with HCR (Red: 17500, 7106)

RECEIVED 03 MAR 2020

Veh No: SMA8361X Yr Regn: 6/18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Shattered

Date/Time, File Pass to?

1) 3/3 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐: Preli. Report☒: Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech. Invs (\$☐: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

450

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 20 February 2020 12:08 PM
To: Ong Shiyang; Chua, Gek Tiang Ruth; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Jason; Lina Pang; Ye, Yong Kang Melvin
Subject: CMTD2000790/RUC - LKK(MC/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Our Reference : CMTD2000790/RUC
Your Reference : SMA8361X

Without Prejudice
EMAIL ONLY

Date: 20/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S FASTECH AUTO PTE LTD

Dear Shi Ying,

ACCIDENT INVOLVING GBH6053S & SMA8361X ON 19.02.2020

We refer to your email reply of today.

We will appoint **Mr. Marcus Chua** of **LKK Auto** to conduct the survey.

Hi LKK Auto,

Please make the arrangement to survey for **SMA8361X** on a without prejudice and any admission of liability basis.

Please be informed that **Ms. Ruth Chua** the handler of this case who can be contacted at 63295 153/
ruth.chua@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, **Ms. Ruth.**

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance / ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>

Sent: Thursday, February 20, 2020 11:39 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: RE: CMTD2000790/RUC - PRI/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Without Prejudice

Dear Grace,

Please arrange (LKK Auto Consultants - Marcus Chua) to conduct the pre- repair survey.

Thank you.

Best Regards,

Shiyong

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Thursday, February 20, 2020 11:18 AM

To: Ong Shiyong <shiyong.ong@fastechauto.com.sg>; Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000790/RUC - PRI/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Our Reference : CMTD2000790/RUC

Your Reference : SMA8361X

Without Prejudice

EMAIL ONLY

Date: 19/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S FASTECH AUTO PTE LTD

Dear Shi Ying,

ACCIDENT INVOLVING GBH6053S & SMA8361X ON 19.02.2020

We refer to your Notice of Accident dated 20.02.2020.

Please be informed that **Ms. Ruth Chua** the handler of this case who can be contacted at 63295 153/
ruth.chua@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompō SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompō Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ong Shiying <shiying.ong@fastechauto.com.sg>

Sent: Thursday, February 20, 2020 10:15 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>

Subject: REQUEST FOR PRE-REPAIR INSPECTION FOR SMA 8361X DOA: 19.02.2020

Without Prejudice

Dear Sir/Madam

Your insured's vehicle: GBH 6053S.

Date of accident: 19/02/2020

Please arrange Pre-repair Inspection for my client's vehicle no: SMA 8361X.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS

AMENDMENT NO. 1 OF 2016 paragraph 2.3, please provide a list of at least 10 motor surveyors within 2 days of the notice.

Thank you.

Best Regards,

Shiying

Fastech Auto Pte Ltd

1 Kaki Bukit Avenue 6 #01-46/48/50

Autobay Singapore 417883

Tel: 6746 5405

Fax: 6745 8520

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 21 February 2020 4:42 PM
To: Admin-D (LKKAuto); 'Teo, Grace'; 'Chua, Gek Tiang Ruth'; assignments
Cc: 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD2000790/RUC - LKK(MC/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMA 8361X on 20/2/2020
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 20 February 2020 3:34 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Chua, Gek Tiang Ruth' <ruth.chua@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD2000790/RUC - LKK(MC/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 20 February 2020 12:08 PM
To: Ong Shiyong; Chua, Gek Tiang Ruth; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Jason; Lina Pang; Ye, Yong Kang Melvin
Subject: CMTD2000790/RUC - LKK(MC/ GBH6053S(NR) & SMA8361X DOA: 19.02.2020

Australian National University

Rank No 1 in Australia & World Top 30. Meet Uni Staff Fri 22Feb 4-7pm. July intake Open
OverseasEducation.sg

OPEN

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

May 2017 Audi A3 1.0 TFSI.



1 Lady Owner. Low Km. Agent
Warranty 2.25 Yr. Excellent
Condition.
Direct Owner StarAd

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category Sort by Date Posted 20 results/page

3 vehicles

Shuttle Hybrid 1.5A X

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Shuttle Hybrid 1.5A X		Any	Any	2018	Any	Any	Any	Available
	Honda	Shuttle Hybrid 1.5A X	\$79,800	\$8,680 /yr	30-Jun-2018	1,496 cc	17,000 km	Stationwagon	Available
Fuel Type: Petrol-Electric X Model High Spec! Almost New With Full Accessories. 6 Airbags With Cruise Control And Paddle Shift. Best Fuel Efficient Stationwagon L...									
Posted: 09-Feb-2020 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda									
	Honda	Shuttle Hybrid 1.5A X	\$88,800	\$9,390 /yr	12-Dec-2018	1,496 cc	-	Stationwagon	Available
Fuel Type: Petrol-Electric Almost New Car And Park In Showroom, 2018 New Facelift, Immediate Delivery, Full Accessories With Front And Rear Recording Camer...									
Posted: 13-Jan-2020 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda									
	Honda	Shuttle Hybrid 1.5A X	\$75,000	\$8,880 /yr	20-Apr-2018	1,496 cc	37,000 km	Stationwagon	Available
Fuel Type: Petrol-Electric Very Good Fuel Consumption With Good Pickup. Almost New With Full Accessories And High Spec x Model. 4 Years Warranty Remaining...									
Posted: 27-Dec-2019 Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda									

[Save this search criteria, to get email alerts whenever a match is found.](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view Expired ads									

20 results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Shuttle Hybrid 1.5A X, Shuttle Hybrid 1.5A X Singapore, used Shuttle Hybrid 1.5A X Singapore, used Shuttle Hybrid 1.5A X, used vehicles Singapore or even buy used Shuttle Hybrid 1.5A X Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	553I

Vehicle Details

Vehicle No.:	SMA8361X
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	LEB6551428
Chassis No.:	GP71209374
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,651.00
Original Registration Date:	21 Jun 2018
First Registration Date:	21 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2028
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	20 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$34,400.00
COE Rebate Amount:	\$28,250.00
Total Rebate Amount:	\$32,000.00

The information contained herein is correct as at 20 Feb 2020

OK

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorised
date
2/5/2010
5 days

VEHICLE NO: SMA 8361X

QTY	PARTICULAR	
1 PCS	REAR WINDSCREEN	1250.00
1 PCS	REAR WINDSCREEN MOULDING	78.00
1 PCS	TAILGATE	1131.10
1 PCS	TAILGATE 'H' LOGO	38.50
1 PCS	TAILGATE 'SHUTTLE' EMBLEM	
1 PCS	TAILGATE 'HYBRID' EMBLEM	
1 PCS	TAILGATE OUTER CHROME MOULDING	619.30
1 PCS	TAILGATE LOCK STRIKER	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE INNER TRIM BOARD	336.20
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
2 PCS	TAILGATE REFLECTORS @\$525.00	380.30
1 PCS	REAR BUMPER	936.50
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.00	45.50
1 SET	REAR BUMPER CLIPS	
2 PCS	REAR BUMPER SIDE GRILLES @\$115.00	68.50
2 PCS	REAR BUMPER SPONGES @\$205.00	
1 PCS	REAR END PANEL	646.10
1 PCS	REAR END PANEL TOP GARNISH	
2 PCS	TAILLAMPS @\$750.00	487.50
2 PCS	REAR FENDERS @\$1050.00	
2 PCS	REAR FENDER INNER TRIM BOARDS @\$485.10	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOP BOARD	
1 PCS	REAR EXHAUST	
1 PCS	TAILGATE TOP SPOILER	

Shattered	\$1,800.00	/
ner	\$166.30	/
Body	\$1,866.20	/
ner	\$60.00	/
ner	\$58.00	/
ner	\$65.00	/
ner	\$745.20	/
ner	\$80.50	X
ner	\$322.20	X
ner	\$299.50	X
ner	\$685.10	/
ner	\$50.00	/
ner	\$1,050.00	IPC
ner	\$1,418.20	/
ner	\$170.00	IPC
ner	\$50.00	/
ner	\$230.00	IPC
ner	\$410.00	X
ner	\$945.20	/
ner	\$311.20	X
ner	\$1,500.00	IPC
ner	\$2,100.00	X
ner	\$970.20	X
ner	\$1,450.00	X
ner	\$688.00	X
ner	\$859.20	X
ner	\$850.00	/
	\$19,200.00	

20%

1 SET	S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR	
1 PCS	REAR REVERSE CAMERA	
1 PCS	REAR END PANEL SEALANT	
1 PCS	REAR WINDSCREEN SOLAR FILM	
1 PCS	REAR WINDSCREEN INNER SEAL	
1 PCS	REAR WINDSCREEN PRIVATE HIRE STICKER	
1 PCS	REAR LICENCE PLATE W/HOLDER	
1 PCS	REAR FLOOR PANEL INSULATOR	

shaded	\$280.00	200
shaded	\$480.00	380
ner	\$50.00	/
ner	\$380.00	200
ner	\$50.00	40
ner	\$20.00	/
ner	\$50.00	X
ner	\$200.00	X

LABOUR CHARGES	
TO CHECK WIRING	\$80.00
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00
TO DISMANTLE & REPLACING REAR WINDSCREEN	\$150.00
TO DISMANTLE & REFIX TAILGATE MECHANISM	\$100.00
TO DISMANTLE & REFIX CUSHION UPHOLSTREY	\$120.00
TO SPRAY RUST PROOFING	\$100.00
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00

	\$80.00	30
	\$80.00	50
	\$150.00	120
	\$100.00	80
	\$120.00	80
	\$100.00	60
	\$100.00	X

LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$1,500.00 600
\$1,500.00 1000

TOTAL \$24,440.00

Auto Collision is hence notify
the Repairer of the following:

- To repair only with original spray painting
- To repair only damaged parts) spray resurvey
- To repair only in respect to confirmation
- To repair only on a "Without Prejudice" basis
- To repair only in respect to approval
- To repair only item(s) must be resurveyed and approved to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

70,90.50
207
5672.40
8582.40
6864.82



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20002938/Utf3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 03-03-2020	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 6053S	Veh. Inspected	SMA 8361X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000790/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71209374	Colour	BLACK	
Odometer	79288	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND REAR WINDSCREEN SHATTERED.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2020	Inspection Date	20/02/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 8361X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SHATTERED	1,800.00	1,250.00
1	REAR WINDSCREEN MOULDING	NECESSARY	166.30	78.00
1	TAILGATE	BADLY DENTED	1,866.20	1,131.10
1	TAILGATE "H" LOGO	NECESSARY	60.00	38.50
1	TAILGATE "SHUTTLE" EMBLEM	NECESSARY	58.00	58.00
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	65.00	65.00
1	TAILGATE OUTER CHROME MOULDING	CRACKED	745.20	619.30
1	TAILGATE LOCK STRIKER	NOT NECESSARY	80.50	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	322.20	-
1	TAILGATE INNER LOCK	NOT NECESSARY	299.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	685.10	336.20
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
2	TAILGATE REFLECTORS @\$525.00	N/S CRACKED	1,050.00	380.30
1	REAR BUMPER	DENTED / DEFORMED	1,418.20	936.50
2	REAR BUMPER SIDE RETAINERS	N/S BENT	170.00	45.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE GRILLES @\$115.00	N/S TORN	230.00	68.50
2	REAR BUMPER SPONGES @\$205.00	NOT FITTED	410.00	-
1	REAR END PANEL	DENTED	945.20	646.10
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	311.20	-
2	TAILLAMPS @\$750.00	N/S CRACKED	1,500.00	487.50
2	REAR FENDERS @\$1050.00	TO REPAIR SEE LABOUR	2,100.00	-
2	REAR FENDER INNER TRIM BOARDS @\$485.10	NOT NECESSARY	970.20	-
1	REAR FLOOR PANEL	NOT NECESSARY	1,450.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	688.00	-
1	REAR EXHAUST	NOT NECESSARY	859.20	-
1	TAILGATE TOP SPOILER	CRACKED	850.00	850.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-1,418.10
			19,200.00	5,672.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	480.00	380.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	380.00	200.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN PRIVATE HIRE STICKER (SN)	NECESSARY	20.00	20.00
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
			1,510.00	890.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		100.00	80.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDERS.		1,500.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,730.00	2,020.00
	GRAND TOTAL		24,440.00	8,582.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,850.00

Report Ref No. CS/SMO20002938/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.