



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005215
INV Date 27/07/2020
Reference CC3/CTI20002944/Fea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SH 6051X
Insured Veh. YL 5354L
Claim No. SNM20D200903
Policy No. DMCVSN3022801900
Accident Date 17/02/2020
Inspection Date 19/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20002944/Fea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 5354L	Veh. Inspected	SH 6051X
Policy No.	DMCVSN3022801900	Coverage (\$)	0.00
Claim No.	SNM20D200903	Excess (\$)	0.00
Assign From		Assign Date	19/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003564969	Colour	BLUE
Odometer	323169	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DAVANTI	8 mm
L/H Rear Tyre	195/65 R15	DAVANTI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/02/2020	Inspection Date	19/02/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6051X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRUNK LID COVER	DENTED	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	SERVICEABLE	457.90	-
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	254.40	-
1	REAR TRUNK LID RUBBER	NOT NECESSARY	365.20	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	BROKEN	1,569.70	733.50
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	360.80	-
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	CRACKED	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	ROOF TOP MOULDING (CENTRE)	MISSING	950.00	950.00
1	ROOF TOP GARNISH SUB ,LH	NECESSARY / MISSING	75.00	75.00
1	ROOF TOP GARNISH SUB ,RH	NECESSARY / MISSING	75.00	75.00
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	TORN	552.60	552.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-
1	REAR BUMPER UNDER SIDE COVER (LH)	NOT NECESSARY	232.00	-
1	REAR BUMPER TOWING COVER	BROKEN	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER ,REAR BUMPER ,SIDE ,LH	NOT NECESSARY	94.80	-
1	SEAL ,REAR BUMPER SIDE ,LH	TO REPAIR SEE LABOUR	148.40	-
1	TAIL LAMP ASSY (UPPER) (LH)	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER) (LH)	SCRATCHED	548.40	548.40
1	TAIL LAMP QUARTER PANEL	NOT NECESSARY	216.00	-
1	REAR END PANEL	BUCKLED	602.10	602.10
1	REAR END PANEL GARNISH	NOT NECESSARY	165.80	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-

Report Ref No. CC3/CTI20002944/Fea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR BOARD (LH)	NOT NECESSARY	301.00	-
2	REAR FENDER SHIELD (LH/RH)	NOT NECESSARY	134.20	-
2	REAR FENDER TRIMBOARD (LH/RH)	NOT NECESSARY	725.00	-
1	REAR FENDER TOP COVER (BLACK COLOR) (LH)	NOT NECESSARY	301.10	-
1	REAR WINDSCREEN GLASS WITH MOULDING	NECESSARY	1,778.30	1,778.30
1	SMART TRANSMITTER KEY	NOT NECESSARY	447.10	-
2	BOOTLID HINGE ASSY LH/RH (ADDITIONAL)	BENT	119.60	119.60
1	SPOILER SUB ASSY (ADDITIONAL)	BROKEN	953.70	953.70
1	STOP LAMP CENTER (ADDITIONAL)	BROKEN	198.40	198.40
	LESS 25% DISCOUNT		-4,032.68	-2,552.25
			12,098.02	7,656.75
	<u>SPECIAL NETT ITEMS</u>			
1	FUEL LID PETROL STICKER (SN) (ADDITIONAL)	NOT NECESSARY	20.00	-
1	REAR NO PLATE WITH TRIM COVER (SN)	SCRATCHED	100.00	55.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			451.70	205.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SEAL ,REAR BUMPER SIDE ,LH .		1,600.00	1,280.00
	SPRAY PAINTING CHARGE.		800.00	600.00
	WIRING CHARGE.		120.00	80.00
	TUFF KOTE.		50.00	50.00
	TOWING CHARGE.		60.00	60.00
	REMOVE /REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE /REFIX REAR WINDSCREEN GLASS .		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	60.00
	REAR WHEEL ALIGNMENT .	NOT NECESSARY	120.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESET BOOT LID SMART KEY .	NOT NECESSARY	120.00	-
			3,260.00	2,290.00
GRAND TOTAL			15,809.72	10,151.75
RECOMMENDED COST OF REPAIRS				10,151.75

Report Ref No. CC3/CTI20002944/Fea3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.