



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8942D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	489.60	-
1	FRONT BUMPER LOGO-TOYOTA	NECESSARY	56.90	56.90
1	FRONT NUMBER PLATE GARNISH	CRUSHED	126.50	126.50
	LESS 25% DISCOUNT		-168.25	-45.86
			504.75	137.54
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE AND CASING (SN)	CUT	80.00	45.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
			125.00	75.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		600.00	200.00
	RESPRAY FRONT BUMPER .		250.00	200.00
			850.00	400.00
	GRAND TOTAL		1,479.75	612.54
	RECOMMENDED COST OF REPAIRS			612.54

Report Ref No. CC4/FCI20002948/Eha3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.