



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002948/Eha3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-04-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1400L	Veh. Inspected	SHA 8942D
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001024MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	19/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103564222	Colour	YELLOW
Odometer	343221	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	VALLEY STONE	5 mm
L/H Front Tyre	195/65 R15	VALLEY STONE	5 mm
R/H Rear Tyre	195/65 R15	VALLEY STONE	5 mm
L/H Rear Tyre	195/65 R15	VALLEY STONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2020	Inspection Date	20/02/2020
Survey held at	31 CORPORATION RD		
Repairer	DING AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------