

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/02/2020 9:03

JOB-NO: 50112455

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

Page 1 of 1

VEHICLE DETAILS

LICENSE NO: SHA8942D TRANS: AUTO
MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU103564222
ENGINE: 2ZRS064004

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	600.00	0.00	600.00		Y	
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	
TOTAL:		850.00	0.00	850.00			
<u>MATERIALS</u>							
1 FRONT BUMPER x R	1.00	489.60	122.40	367.20	L	Y	
2 FRONT BUMPER LOGO- TOYOTA	1.00	56.90	14.23	42.67	L	Y	
3 FRONT NUMBER PLATE GARNISH	1.00	126.50	31.63	94.87	L	Y	
4 FRONT NUMBER PLATE AND CASING	1.00	80.00	0.00	80.00	S	Y	
5 FRONT BUMPER CLIPS	1.00	45.00	0.00	45.00	S	Y	
TOTAL:		798.00	168.26	629.74			
TOTAL PARTS & LABOUR :		1,648.00	168.26	1,479.74			

EXCESS/LOADING:\$ 0.00

No. Of Day: 2 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 20, 2, 2020

SURVEYED BY: Steve Ch

CONTACT NO: 8322 8817

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00