

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : SFN1787L
Vehicle Model : Hyundai Avante

Not Authorised
Resurvey B4 point

Estimate Repair Cost

No.	Qty	Parts List Items		
1	1	Rear bumper	\$ Bn	450.40 ✓
2	2	Rear bumper brackets	cm \$	158.00 ✓
3	2	Rear bumper retainers	\$ D.1	68.00 ✓
4	1	Rear bumper reinforcement	\$ Bn	460.00 ✓
5	2	Rear bumper reflectors	nls cm \$	222.00 ✓
6	1	Rear bumper lower garnish	\$ Bn	269.00 ✓
7	1 set	Rear bumper clips	\$ Bn	40.00 ✓
8	1	Rear bootlid	\$ Bn	1,782.40 ✓
9	1	Rear bootlid centre logo	\$ Bn	41.00 ✓
10	1	Rear bootlid "AVANTE" emblem	\$ Bn	47.00 ✓
11	1	Rear bootlid lock	\$ Bn	116.20 ✓
12	2	Rear bootlid hinges	\$ Bn	98.00 X
13	1	Rear bootlid weatherstrip	nd 10.1 \$	161.00 ✓
14	2	Rear bootlid reflectors	\$ Bn	588.00 X
15	1	Rear bootlid inner trim	\$ Bn	269.00 X
16	1 set	Rear bootlid inner trim clips	\$ Bn	40.00 X
17	2	Tail lamps	\$ Bn	1,764.00 X
18	2	Tail lamp panels	\$ Bn	338.00 X
19	1	Rear end panel	\$ Bn	499.00 ✓
20	1	Rear end panel top garnish	\$ Bn	79.00 ✓
21	1	Rear spare tyre top board	\$ Bn	299.00 X
22	1	Rear spare tyre compartment	\$ Bn	599.90 X
23	1	Rear exhaust silencer	\$ Bn	608.00 X
24	1 set	Rear exhaust silencer mounting	\$ Bn	64.00 X
			208	
			Total	\$ 9,060.90

Parts Special Nett Items

25	1	Rear number plate	\$ Bn	60.00 455n
26	4	Reverse sensor	shot \$	350.00 2001n
27	1	Reverse camera	\$ Bn	400.00 X
			\$	810.00

Total Parts \$ 9,870.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$	1,500.00	700
2	To putty and respray painting on affected areas.	\$	1,200.00	800
3	To remove, replace rear bootlid fittings to facilitate repair.	\$	300.00	50
4	To remove, replace reverse sensor.	\$	150.00	50
5	To remove, replace reverse camera.	\$	150.00	30
6	To remove, replace rear exhaust silencer.	~ \$	200.00	x
7	To check wiring and lightings.	\$	80.00	20

Total Labour \$ 3,580.00

Total Parts and Labour \$ 13,450.90