

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: XE1195D190702

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date: 20-02-20

Vehicle No: XE1195D

Model/Make: Mitsubishi

Fuso FV51SS3VDEA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tail Lamp 366.25' (252	\$ 450.00	X
2	Tail Lamp Bracket	\$ 300.00	X
3	Safety Bar	\$ 1,800.00	SN 1100 S.N
4	Safety Bar Strip Sticker	\$ 120.00	SN X
5	Number Plate Lamps 02 pcs (@ S\$195.00)	\$ 390.00	N X
	To check all wiring & electrical component for proper function	\$ 30.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 300.00	- 250
	To putty & spray painting & including touch up paint on accident affected are	\$ 300.00	- 280

Total Parts & Labour of estimate for damaged vehicle

\$ 3,690.00

530

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

not authorized
Liu

2 days.
The photo after repair
L/S \$ 1500



M/s Liu's Brother Auto Engrg Wks

P-366.25
252

P-274.68

S.N-1100.00

L-550.00

1924.68

202

1538

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COR - 1500

search fee - 200

loss of use 2x250=500

TOTAL \$ 2002.00

private settlement