



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

25 FEB 2021

Your Ref :
Our Ref : TP/11510/FBP6327K/GBF2488H

BY FAX & HAND

India International Insurance Pte Ltd
64 Cecil Street
#04-00 & #05-00 IOB Building
Singapore 049711

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBP6327K & GBF2488H on 09/02/2020

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$11,664.36
2. Loss of Use (9 days x \$20)	\$ 180.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	<u>\$11,846.36</u>

We attached Signed Authorisation To Act, Discharge Voucher, Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

.....
Raymond Tan
Manager/Insurance Dept



AUTHORISATION TO ACT

I, NTUC Income Insurance Co. Singapore Ltd (the third party claimant) of 2 Tampines Central 6
#06-03 NTUC Income Tampines Point (address), owner of F8P6327K (vehicle no.)
hereby authorize Ban Hock Hin Co. Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. F8P6327K that was damaged pursuant to the accident which occurred on 09/02/2020
(date) along SLE QTE at TPE Exit (location) involving vehicle no/s
GPB2488H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 28th (day) of Feb (month) 2021 (year)



Vivake Menon
Manager
Date: 28 Feb 2021



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

Occupation:



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
MOTOR CLAIMS DEPT

GST Reg No. : M2-0010542-7

Invoice No. : **DLCR40106490-I11510**
Invoice Date : 19/02/2021
Payment Due Date : 21/03/2021

CLAIM NO. : 11510
POLICY NO. : 5113921882
VEHICLE NO. : FBP6327K
MAKE/MODEL : YAM / CZD300A/XMAX300

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	ARM REAR ASSY	REPLACE	1	\$223.00	\$200.70
				Disc %: 10%	
2	AXLE, DRIVE	REPLACE	1	\$63.00	\$56.70
				Disc %: 10%	
3	BALANCER HANDLE	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
4	BALANCER, WHEEL (20G)	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
5	BASE PLATE (GIVI) BOX REAR	REPLACE	1	\$125.00	\$112.50
				Disc %: 10%	
6	BEARING	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
7	BEARING	REPLACE	2	\$59.00	\$106.20
				Disc %: 10%	
8	BEARING	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
9	BEARING 6002	REPLACE	1	\$20.00	\$18.00
				Disc %: 10%	
10	BEARING 6205	REPLACE	1	\$37.00	\$33.30
				Disc %: 10%	
11	BEARING 6303	REPLACE	3	\$10.00	\$27.00
				Disc %: 10%	
12	BEARING 6304	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
13	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
14	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
15	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
16	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
17	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
18	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
19	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
20	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
21	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
22	BOLT	REPLACE	3	\$5.00	\$13.50
				Disc %: 10%	
23	BOLT	REPLACE	6	\$2.00	\$10.80
				Disc %: 10%	
24	BOLT	REPLACE	2	\$5.00	\$9.00
				Disc %: 10%	
25	BOLT, FLANGE	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
26	BOX REAR (GIVI) V56N MAXIA 4	REPLACE	1	\$884.00	\$795.60
				Disc %: 10%	
27	BRACKET ENGINE COMP	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
28	BRACKET FIBRE (FOR 6 LED)	REPLACE	1	\$142.00	\$127.80
				Disc %: 10%	
29	BRACKET REAR BOX (KAPPA)	REPLACE	1	\$187.00	\$168.30
				Disc %: 10%	
30	BUSH SHOCK ABSORBER	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
31	CALIPER ASSY, REAR	REPLACE	1	\$297.00	\$267.30
				Disc %: 10%	
32	CAMERA (V_SYS) M6 (NON-WIFI VERSION) (NEW)	REPLACE	1	\$405.00	\$364.50
				Disc %: 10%	
33	CAP PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
34	CASE, CHAIN TENSIONER	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
35	CHAIN TIMING	REPLACE	1	\$24.00	\$21.60
				Disc %: 10%	
36	CLAMP	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
37	COLLAR, UNION	REPLACE	2	\$23.00	\$41.40
				Disc %: 10%	
38	COVER 5	REPLACE	1	\$10.00	\$9.00
				Disc %: 10%	
39	COVER AIR FILTER	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
40	COVER BATTERY	REPLACE	1	\$20.00	\$18.00
				Disc %: 10%	
41	COVER CAP PROTECTOR EXHAUST INNER	REPLACE	1	\$51.00	\$45.90
				Disc %: 10%	
42	COVER COWLING LH	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
43	COVER CRANKCASE OUTER	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
44	COVER FRONT	REPLACE	1	\$105.00	\$94.50
				Disc %: 10%	
45	COVER LOWER FIRING LH	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
46	COVER METER	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
47	COVER TAIL CENTER	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
48	COVER TAIL LH	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
49	COVER TAIL LOWER LH	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
50	COVER TAIL LOWER RH	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
51	COVER TAIL RH(MATT BLACK)	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
52	COVER, REAR FENDER	REPLACE	1	\$19.00	\$17.10
				Disc %: 10%	
53	CRANKCASE ASSY	REPLACE	1	\$370.00	\$333.00
				Disc %: 10%	
54	DAMPER 5	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
55	DAMPER, PLATE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
56	DAMPER, PLATE	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
57	DAMPER, PLATE	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
58	ELEMENT COVER AIR FILTER	REPLACE	1	\$6.00	\$5.40
				Disc %: 10%	
59	EMBLEM	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
60	EMBLEM	REPLACE	1	\$54.00	\$48.60
				Disc %: 10%	
61	EMBLEM (YAMAHA) LOGO	REPLACE	1	\$19.00	\$17.10
				Disc %: 10%	
62	FENDER FRONT	REPLACE	1	\$24.00	\$21.60
				Disc %: 10%	
63	FILTER OIL	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
64	FOOTBOARD LH	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
65	GASKET CRANKCASE COVER	REPLACE	1	\$19.00	\$17.10
				Disc %: 10%	
66	GASKET EXHAUST PIPE	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
67	GASKET MUFFLER	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
68	GASKET, BREATHER COVER	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
69	GASKET, CRANKCASE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
70	GASKET, CYLINDER	REPLACE	1	\$6.00	\$5.40
				Disc %: 10%	
71	GASKET, CYLINDER HEAD	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
72	GASKET, HEAD COVER 1	REPLACE	1	\$13.00	\$11.70
				Disc %: 10%	
73	GUIDE, STOPPER 1	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
74	GUIDE, STOPPER 2	REPLACE	1	\$68.00	\$61.20
				Disc %: 10%	
75	HANDLE BAR	REPLACE	1	\$54.00	\$48.60
				Disc %: 10%	
76	HANDLE REAR	REPLACE	1	\$90.00	\$81.00
				Disc %: 10%	
77	HOLDER	REPLACE	2	\$38.00	\$68.40
				Disc %: 10%	
78	LEVER BRAKE LH	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
79	LIGHT BOX REAR (GIVI) E160	REPLACE	1	\$147.00	\$132.30
				Disc %: 10%	
80	LIGHT LED (JL) 8 LED AMBER LENS	REPLACE	1	\$373.00	\$335.70
				Disc %: 10%	
81	LIGHT LICENCE ASSY	REPLACE	1	\$37.00	\$33.30
				Disc %: 10%	
82	LIGHT TAIL UNIT ASSY	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
83	LIGHT TAIL UNIT ASSY	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
84	MID BOLT	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
85	MID WASHER PLATE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
86	MIRROR LH	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
87	MUDGUARD REAR	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
88	MUFFLER ASSY	REPLACE	1	\$962.00	\$865.80
				Disc %: 10%	
89	NOZZLE 3	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
90	OIL ENGINE (YAMAHA) 20W-40 (4ST) S.S	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
91	OIL GEAR (UNITED) GL-5	REPLACE	0	\$11.00	\$2.97
				Disc %: 10%	
92	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
93	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
94	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
95	O-RING	REPLACE	2	\$2.00	\$3.60
				Disc %: 10%	
96	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
97	O-RING	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
98	O-RING	REPLACE	1	\$13.00	\$11.70
				Disc %: 10%	
99	O-RING (GEAR STARTER 3)	REPLACE	4	\$6.00	\$21.60
				Disc %: 10%	
100	O-RING THERMOSTAT	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
101	O-RING VALVE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
102	PAD, ADJUSTING (1.60)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
103	PAD, ADJUSTING (1.65)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
104	PAD, ADJUSTING (1.75)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
105	PAD, ADJUSTING (1.80)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
106	PIN, PISTON	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
107	PISTON (STD)	REPLACE	1	\$75.00	\$67.50
				Disc %: 10%	
108	PISTON RING SET (STD)	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
109	PLATE DISC BRAKE REAR	REPLACE	1	\$75.00	\$67.50
				Disc %: 10%	
110	PLATE NUMBER REAR (6.5 INCH X 9 INCH)	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
111	PROTECTOR EXHAUST	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
112	REAR BLINKER (ORANGE)	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
113	REFLECTOR ASSY REAR	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
114	REFLECTOR, FRONT	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
115	RIM SPORT REAR	REPLACE	1	\$342.00	\$307.80
				Disc %: 10%	
116	RIVET	REPLACE	4	\$2.00	\$7.20
				Disc %: 10%	
117	RIVET	REPLACE	2	\$5.00	\$9.00
				Disc %: 10%	
118	ROTOR SENSOR	REPLACE	1	\$26.00	\$23.40
				Disc %: 10%	
119	SCREW (VISOR)	REPLACE	4	\$5.00	\$18.00
				Disc %: 10%	
120	SCREW PLUG	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
121	SEAL	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
122	SEAL OIL	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
123	SEAL OIL	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
124	SEAL OIL	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
125	SEAL OIL PUMP	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
126	SEAL VALVE	REPLACE	4	\$7.00	\$25.20
				Disc %: 10%	
127	SEAT DOUBLE ASSY	REPLACE	1	\$444.00	\$399.60
				Disc %: 10%	
128	SEAT PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
129	SEAT UNDER BOX	REPLACE	1	\$194.00	\$174.60
				Disc %: 10%	
130	SHAFT ASSY	REPLACE	1	\$61.00	\$54.90
				Disc %: 10%	
131	SHAFT, PIVOT	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
132	STAND MAIN	REPLACE	1	\$135.00	\$121.50
				Disc %: 10%	
133	STAND SIDE	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
134	STARTER ONE-WAY ASSY	REPLACE	1	\$82.00	\$73.80
				Disc %: 10%	
135	STAY 1	REPLACE	1	\$133.00	\$119.70
				Disc %: 10%	
136	STAY WINDSHEILD	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
137	STAY WINDSHEILD 2	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
138	STICKER (ORANGEFORCE) BOX REAR NEW	REPLACE	1	\$28.00	\$28.00
139	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	REPLACE	1	\$19.00	\$19.00
140	STICKER(ORANGEFORCE) COVER SIDE LH/RH NEW	REPLACE	1	\$70.00	\$70.00
141	STICKER(ORANGEFORCE) WINDSHIELD NEW	REPLACE	1	\$28.00	\$28.00
142	TENSIONER ASSY, CAM CHAIN	REPLACE	1	\$97.00	\$87.30
				Disc %: 10%	
143	TYRE 140/70-14 (SHINKO) SR568	REPLACE	1	\$140.00	\$126.00
				Disc %: 10%	
144	UPPER COVER METER	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
145	VALVE RELIEF ASSY	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
146	VALVE RIM	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
147	WASHER BOLT (MASTER CYLINDER PUMP)	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
148	WINDSHIELD	REPLACE	1	\$299.00	\$269.10
				Disc %: 10%	
149	LABOUR	Supply/Install	1	\$935.00	\$935.00



S/N	Description	Action	Qty	Unit Price	Amount
150	MISCELLANEOUS FEE (CRANKCASE INSPECTION)		1	\$35.00	\$35.00
151	MISCELLANEOUS FEES		1	\$35.00	\$35.00
152	SPRAY PAINT WHOLE BODY	Spray	1	\$532.00	\$532.00
153	SPRAY PAINT REAR GIVI BOX	Spray	1	\$154.00	\$154.00
154	TRANSPORT CHARGES		1	\$56.00	\$56.00
155	NUT (WINDSCREEN)	REPLACE	4	\$5.00	\$18.00
				Disc %: 10%	
156	BALANCER ASSY	Replace	1	\$229.00	\$206.10
				Disc %: 10%	
157	BEARING 6204 (NSK)	Replace	1	\$14.00	\$12.60
				Disc %: 10%	
158	BODY FRONT UNDER 1	Replace	1	\$38.00	\$34.20
				Disc %: 10%	
159	BOLT CONNECTING ROD	Replace	6	\$4.00	\$21.60
				Disc %: 10%	
160	CLIP COVER (PLASTIC)	Replace	2	\$6.00	\$10.80
				Disc %: 10%	
161	COVER LIGHT BOX V56N	Replace	1	\$78.00	\$70.20
				Disc %: 10%	
162	GROMMET	Replace	2	\$6.00	\$10.80
				Disc %: 10%	
163	LEG SHIELD 1	Replace	1	\$45.00	\$40.50
				Disc %: 10%	
164	NUT	Replace	6	\$6.00	\$32.40
				Disc %: 10%	
165	BEARING 6002-2NS (NACHI)	Replace	1	\$13.00	\$11.70
				Disc %: 10%	
166	COOLANT (MOBIL) ANTIFREEZE	Replace	2	\$12.00	\$21.60
				Disc %: 10%	
SUB TOTAL					\$10,901.27
GST @ 7 %					\$763.09
GRAND TOTAL (SGD)					\$11,664.36

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND

bizSAFE₃



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-20-028000

Date of Request: 17/02/2020

Your Ref No:

Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 17/02/2020
Enquiry By Hasrianah Binte Hassan
TP Vehicle No. GBF2488H
Accident Date 09/02/2020

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBF2488H	India International Insurance Pte Ltd	17/08/2019-16/08/2020	63476100

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-20-028000
Date of Request: 17/02/2020

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 17/02/2020
Enquiry By Hasrianah Binte Hassan
TP Vehicle No. GBF2488H
Accident Date 09/02/2020

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Feb 2020 17:24	Clim Dtl Modified	Claimant's Name: -> NTUC INCOME INSURANCE CO-OPERA. Claimant's ID: -> S97CS0162D.	[A] Lee Su Li
2	20 Feb 2020 17:24	Clim Veh Model Changed	(206489) YAMAHA XMAX 300 292cc.	[A] Lee Su Li
3	20 Feb 2020 17:24	Clim Created	Reg No: FBP6327K. Acct Date: 2020/02/09. Claim Type: TP. Insurer: India International Insurance Pte Ltd (H Q). Workshop: Ban Hock Hin Co. Pte Ltd (HQ)	[A] Lee Su Li
4	20 Feb 2020 17:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lee Su Li
5	20 Feb 2020 17:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/03/02	[A] Lee Su Li
6	20 Feb 2020 17:24	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lee Su Li
7	20 Feb 2020 17:27	Label Added	(30653):Direct Settlement.	[A] Lee Su Li
8	20 Feb 2020 17:27	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lee Su Li
9	25 Feb 2020 10:39	Adj Adjuster Assigned	MARCUS CHUA -> PARASURAM SHANMUGAM	[A] Lee Su Li
10	25 Feb 2020 10:44	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remark: Insured driver hit onto third party stationary motorbike.	[A] CHEW HSIAO TONG
11	25 Feb 2020 14:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/03/02. Mandate Remarks: Please revert on quantum	[I] Lalitha Krishnan
12	25 Feb 2020 14:24	Adj Mandate Set	Approved:0.00:Please revert on quantum	[I] Lalitha Krishnan
13	25 Feb 2021 08:58	Adj Adjuster Assigned	PARASURAM SHANMUGAM -> MARCUS CHUA	[A] CHEW HSIAO TONG
14	25 Mar 2021 09:15	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
15	25 Mar 2021 09:15	Clim Dtl Modified	Insured Name: -> -. Insured ID: -> -. Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN
16	25 Mar 2021 09:15	Clim Dtl Modified	JPJ Reg. Date: -> 2019/05/14.	[A] JOANNE LEE KHANG MIN
17	25 Mar 2021 09:15	Clim Details Notified		[A] JOANNE LEE KHANG MIN
18	27 Mar 2021 12:25	Adj Mandate Request	Cur.Req:11846.36:Liability: 100% *Quantum: (a)CORw/GST: \$11,664.36+ (b)LOU(9days x \$20.00): \$180.00 + (c)Search fee: \$2.00 = Total: \$11,846.36 *Vehicle Model: Yamaha Xmax (292cc) *7 recommendation rep air days + 1PH + 1Sunday = 9days *MV: \$14,000.	[A] CHEW HSIAO TONG
19	29 Mar 2021 19:35	Adj Mandate Set	Approved:11846.36.	[I] C. Meenachi

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2680374	25 Mar 2021 09:15:21	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	FBP6327K	GBF2488H	11.00

