



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

25 FEB 2021

Your Ref :
Our Ref : TP/11510/FBP6327K/GBF2488H

BY FAX & HAND

India International Insurance Pte Ltd
64 Cecil Street
#04-00 & #05-00 IOB Building
Singapore 049711

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBP6327K & GBF2488H on 09/02/2020

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$11,664.36
2. Loss of Use (9 days x \$20)	\$ 180.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
TOTAL	<u>\$11,846.36</u>

We attached Signed Authorisation To Act, Discharge Voucher, Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

.....
Raymond Tan
Manager/Insurance Dept

bizSAFE₃





INTERNATIONAL INSURANCE PTE LTD

In service since 1987

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III - Direct Settlement (PODS)

India Ref:
Claimant Ref :

We/I, Ban Hock Hin Co. Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants (name of Surveyor) with respect to the amount claimed for S\$ 11,664.36 (repair cost), S\$ 180.00 (loss of use/rental), S\$ 2.00 (search fee), vehicle no. FBP6327K that was damaged pursuant to the accident which occurred on 09/02/2020 (date) at SLE CTE at TPE Exit (location) involving vehicle no. GBF248RH (Insured vehicle). This is pursuant to the inspection conducted on 20/02/2020 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NFLC Income Insurance Co-operative Ltd ("the third party claimant") of vehicle no. FBP6327K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to FBP6327K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 11,846.36 to Ban Hock Hin Co. Pte Ltd.

Dated this 25th day of Feb 2021

CLAIMANT:

Signature:

Signed by "the workshop"
(with chop)

Name:

Address:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

Address:

INDIA INTERNATIONAL INSURANCE PTE LTD

CO. REG. NO.: 198703792K

64 CECIL STREET #04/05/06-02 IOB BUILDING SINGAPORE 049711 TEL: 6347 6100 FAX: 6224 4174 • 6225 7743 WEB: www.ill.com.sg

POSTAL ADDRESS: ROBINSON ROAD P.O. BOX NO. 738 SINGAPORE 901438

AUTHORISATION TO ACT

I, NTUC Income Insurance Co-operative Ltd (the third party claimant) of 2 Tampines Central 1
#06-03 NTUC Income Tampines Point (address), owner of F8P6327K (vehicle no.)
hereby authorize Ban Hock Hin Co. Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. F8P6327K that was damaged pursuant to the accident which occurred on 09/02/2020
(date) along SLE CTE at TPE Exit (location) involving vehicle no/s
GPB 2488H ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 28th (day) of Feb (month) 2021 (year)



Vivake Menon:
Manager
Orange Force

Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
MOTOR CLAIMS DEPT

GST Reg No. : M2-0010542-7

Invoice No. : **DLCR40106490-I11510**
Invoice Date : 19/02/2021
Payment Due Date : 21/03/2021

CLAIM NO. : 11510
POLICY NO. : 5113921882
VEHICLE NO. : FBP6327K
MAKE/MODEL : YAM / CZD300A/XMAX300

(Page 1 of 7)

S/N	Description	Action	Qty	Unit Price	Amount
1	ARM REAR ASSY	REPLACE	1	\$223.00	\$200.70
				Disc %: 10%	
2	AXLE, DRIVE	REPLACE	1	\$63.00	\$56.70
				Disc %: 10%	
3	BALANCER HANDLE	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
4	BALANCER, WHEEL (20G)	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
5	BASE PLATE (GIVI) BOX REAR	REPLACE	1	\$125.00	\$112.50
				Disc %: 10%	
6	BEARING	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
7	BEARING	REPLACE	2	\$59.00	\$106.20
				Disc %: 10%	
8	BEARING	REPLACE	1	\$17.00	\$15.30
				Disc %: 10%	
9	BEARING 6002	REPLACE	1	\$20.00	\$18.00
				Disc %: 10%	
10	BEARING 6205	REPLACE	1	\$37.00	\$33.30
				Disc %: 10%	
11	BEARING 6303	REPLACE	3	\$10.00	\$27.00
				Disc %: 10%	
12	BEARING 6304	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
13	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
14	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
15	BEARING PLANE CONNECTING ROD	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
16	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
17	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
18	BEARING PLANE CRANK	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
19	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
20	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
21	BEARING PLANE CRANK	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
22	BOLT	REPLACE	3	\$5.00	\$13.50
				Disc %: 10%	
23	BOLT	REPLACE	6	\$2.00	\$10.80
				Disc %: 10%	
24	BOLT	REPLACE	2	\$5.00	\$9.00
				Disc %: 10%	
25	BOLT, FLANGE	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
26	BOX REAR (GIVI) V56N MAXIA 4	REPLACE	1	\$884.00	\$795.60
				Disc %: 10%	
27	BRACKET ENGINE COMP	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
28	BRACKET FIBRE (FOR 6 LED)	REPLACE	1	\$142.00	\$127.80
				Disc %: 10%	
29	BRACKET REAR BOX (KAPPA)	REPLACE	1	\$187.00	\$168.30
				Disc %: 10%	
30	BUSH SHOCK ABSORBER	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
31	CALIPER ASSY, REAR	REPLACE	1	\$297.00	\$267.30
				Disc %: 10%	
32	CAMERA (V_SYS) M6 (NON-WIFI VERSION) (NEW)	REPLACE	1	\$405.00	\$364.50
				Disc %: 10%	
33	CAP PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
34	CASE, CHAIN TENSIONER	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
35	CHAIN TIMING	REPLACE	1	\$24.00	\$21.60
				Disc %: 10%	
36	CLAMP	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
37	COLLAR, UNION	REPLACE	2	\$23.00	\$41.40
				Disc %: 10%	
38	COVER 5	REPLACE	1	\$10.00	\$9.00
				Disc %: 10%	
39	COVER AIR FILTER	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
40	COVER BATTERY	REPLACE	1	\$20.00	\$18.00
				Disc %: 10%	
41	COVER CAP PROTECTOR EXHAUST INNER	REPLACE	1	\$51.00	\$45.90
				Disc %: 10%	
42	COVER COWLING LH	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
43	COVER CRANKCASE OUTER	REPLACE	1	\$23.00 Disc %: 10%	\$20.70
44	COVER FRONT	REPLACE	1	\$105.00 Disc %: 10%	\$94.50
45	COVER LOWER FIRING LH	REPLACE	1	\$38.00 Disc %: 10%	\$34.20
46	COVER METER	REPLACE	1	\$45.00 Disc %: 10%	\$40.50
47	COVER TAIL CENTER	REPLACE	1	\$27.00 Disc %: 10%	\$24.30
48	COVER TAIL LH	REPLACE	1	\$42.00 Disc %: 10%	\$37.80
49	COVER TAIL LOWER LH	REPLACE	1	\$28.00 Disc %: 10%	\$25.20
50	COVER TAIL LOWER RH	REPLACE	1	\$14.00 Disc %: 10%	\$12.60
51	COVER TAIL RH(MATT BLACK)	REPLACE	1	\$38.00 Disc %: 10%	\$34.20
52	COVER, REAR FENDER	REPLACE	1	\$19.00 Disc %: 10%	\$17.10
53	CRANKCASE ASSY	REPLACE	1	\$370.00 Disc %: 10%	\$333.00
54	DAMPER 5	REPLACE	1	\$38.00 Disc %: 10%	\$34.20
55	DAMPER, PLATE	REPLACE	1	\$3.00 Disc %: 10%	\$2.70
56	DAMPER, PLATE	REPLACE	1	\$17.00 Disc %: 10%	\$15.30
57	DAMPER, PLATE	REPLACE	1	\$9.00 Disc %: 10%	\$8.10
58	ELEMENT COVER AIR FILTER	REPLACE	1	\$6.00 Disc %: 10%	\$5.40
59	EMBLEM	REPLACE	1	\$9.00 Disc %: 10%	\$8.10
60	EMBLEM	REPLACE	1	\$54.00 Disc %: 10%	\$48.60
61	EMBLEM (YAMAHA) LOGO	REPLACE	1	\$19.00 Disc %: 10%	\$17.10
62	FENDER FRONT	REPLACE	1	\$24.00 Disc %: 10%	\$21.60
63	FILTER OIL	REPLACE	1	\$14.00 Disc %: 10%	\$12.60
64	FOOTBOARD LH	REPLACE	1	\$31.00 Disc %: 10%	\$27.90
65	GASKET CRANKCASE COVER	REPLACE	1	\$19.00 Disc %: 10%	\$17.10
66	GASKET EXHAUST PIPE	REPLACE	1	\$9.00 Disc %: 10%	\$8.10
67	GASKET MUFFLER	REPLACE	1	\$7.00 Disc %: 10%	\$6.30
68	GASKET, BREATHER COVER	REPLACE	1	\$7.00 Disc %: 10%	\$6.30



S/N	Description	Action	Qty	Unit Price	Amount
69	GASKET, CRANKCASE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
70	GASKET, CYLINDER	REPLACE	1	\$6.00	\$5.40
				Disc %: 10%	
71	GASKET, CYLINDER HEAD	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
72	GASKET, HEAD COVER 1	REPLACE	1	\$13.00	\$11.70
				Disc %: 10%	
73	GUIDE, STOPPER 1	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
74	GUIDE, STOPPER 2	REPLACE	1	\$68.00	\$61.20
				Disc %: 10%	
75	HANDLE BAR	REPLACE	1	\$54.00	\$48.60
				Disc %: 10%	
76	HANDLE REAR	REPLACE	1	\$90.00	\$81.00
				Disc %: 10%	
77	HOLDER	REPLACE	2	\$38.00	\$68.40
				Disc %: 10%	
78	LEVER BRAKE LH	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
79	LIGHT BOX REAR (GIVI) E160	REPLACE	1	\$147.00	\$132.30
				Disc %: 10%	
80	LIGHT LED (JL) 8 LED AMBER LENS	REPLACE	1	\$373.00	\$335.70
				Disc %: 10%	
81	LIGHT LICENCE ASSY	REPLACE	1	\$37.00	\$33.30
				Disc %: 10%	
82	LIGHT TAIL UNIT ASSY	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
83	LIGHT TAIL UNIT ASSY	REPLACE	1	\$178.00	\$160.20
				Disc %: 10%	
84	MID BOLT	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
85	MID WASHER PLATE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
86	MIRROR LH	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
87	MUDGUARD REAR	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
88	MUFFLER ASSY	REPLACE	1	\$962.00	\$865.80
				Disc %: 10%	
89	NOZZLE 3	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
90	OIL ENGINE (YAMAHA) 20W-40 (4ST) S.S	REPLACE	2	\$12.00	\$21.60
				Disc %: 10%	
91	OIL GEAR (UNITED) GL-5	REPLACE	0	\$11.00	\$2.97
				Disc %: 10%	
92	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
93	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
94	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
95	O-RING	REPLACE	2	\$2.00	\$3.60
				Disc %: 10%	
96	O-RING	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	
97	O-RING	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
98	O-RING	REPLACE	1	\$13.00	\$11.70
				Disc %: 10%	
99	O-RING (GEAR STARTER 3)	REPLACE	4	\$6.00	\$21.60
				Disc %: 10%	
100	O-RING THERMOSTAT	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
101	O-RING VALVE	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
102	PAD, ADJUSTING (1.60)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
103	PAD, ADJUSTING (1.65)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
104	PAD, ADJUSTING (1.75)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
105	PAD, ADJUSTING (1.80)	REPLACE	2	\$6.00	\$10.80
				Disc %: 10%	
106	PIN, PISTON	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
107	PISTON (STD)	REPLACE	1	\$75.00	\$67.50
				Disc %: 10%	
108	PISTON RING SET (STD)	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
109	PLATE DISC BRAKE REAR	REPLACE	1	\$75.00	\$67.50
				Disc %: 10%	
110	PLATE NUMBER REAR (6.5 INCH X 9 INCH)	REPLACE	1	\$27.00	\$24.30
				Disc %: 10%	
111	PROTECTOR EXHAUST	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
112	REAR BLINKER (ORANGE)	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
113	REFLECTOR ASSY REAR	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
114	REFLECTOR, FRONT	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
115	RIM SPORT REAR	REPLACE	1	\$342.00	\$307.80
				Disc %: 10%	
116	RIVET	REPLACE	4	\$2.00	\$7.20
				Disc %: 10%	
117	RIVET	REPLACE	2	\$5.00	\$9.00
				Disc %: 10%	
118	ROTOR SENSOR	REPLACE	1	\$26.00	\$23.40
				Disc %: 10%	
119	SCREW (VISOR)	REPLACE	4	\$5.00	\$18.00
				Disc %: 10%	
120	SCREW PLUG	REPLACE	1	\$2.00	\$1.80
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
121	SEAL	REPLACE	1	\$5.00	\$4.50
				Disc %: 10%	
122	SEAL OIL	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
123	SEAL OIL	REPLACE	1	\$14.00	\$12.60
				Disc %: 10%	
124	SEAL OIL	REPLACE	1	\$9.00	\$8.10
				Disc %: 10%	
125	SEAL OIL PUMP	REPLACE	1	\$45.00	\$40.50
				Disc %: 10%	
126	SEAL VALVE	REPLACE	4	\$7.00	\$25.20
				Disc %: 10%	
127	SEAT DOUBLE ASSY	REPLACE	1	\$444.00	\$399.60
				Disc %: 10%	
128	SEAT PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
129	SEAT UNDER BOX	REPLACE	1	\$194.00	\$174.60
				Disc %: 10%	
130	SHAFT ASSY	REPLACE	1	\$61.00	\$54.90
				Disc %: 10%	
131	SHAFT, PIVOT	REPLACE	1	\$23.00	\$20.70
				Disc %: 10%	
132	STAND MAIN	REPLACE	1	\$135.00	\$121.50
				Disc %: 10%	
133	STAND SIDE	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
134	STARTER ONE-WAY ASSY	REPLACE	1	\$82.00	\$73.80
				Disc %: 10%	
135	STAY 1	REPLACE	1	\$133.00	\$119.70
				Disc %: 10%	
136	STAY WINDSHEILD	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
137	STAY WINDSHEILD 2	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
138	STICKER (ORANGEFORCE) BOX REAR NEW	REPLACE	1	\$28.00	\$28.00
139	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	REPLACE	1	\$19.00	\$19.00
140	STICKER(ORANGEFORCE) COVER SIDE LH/RH NEW	REPLACE	1	\$70.00	\$70.00
141	STICKER(ORANGEFORCE) WINDSHIELD NEW	REPLACE	1	\$28.00	\$28.00
142	TENSIONER ASSY, CAM CHAIN	REPLACE	1	\$97.00	\$87.30
				Disc %: 10%	
143	TYRE 140/70-14 (SHINKO) SR568	REPLACE	1	\$140.00	\$126.00
				Disc %: 10%	
144	UPPER COVER METER	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
145	VALVE RELIEF ASSY	REPLACE	1	\$31.00	\$27.90
				Disc %: 10%	
146	VALVE RIM	REPLACE	1	\$7.00	\$6.30
				Disc %: 10%	
147	WASHER BOLT (MASTER CYLINDER PUMP)	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
148	WINDSHIELD	REPLACE	1	\$299.00	\$269.10
				Disc %: 10%	
149	LABOUR	Supply/Install	1	\$935.00	\$935.00



S/N	Description	Action	Qty	Unit Price	Amount
150	MISCELLANEOUS FEE (CRANKCASE INSPECTION)		1	\$35.00	\$35.00
151	MISCELLANEOUS FEES		1	\$35.00	\$35.00
152	SPRAY PAINT WHOLE BODY	Spray	1	\$532.00	\$532.00
153	SPRAY PAINT REAR GIVI BOX	Spray	1	\$154.00	\$154.00
154	TRANSPORT CHARGES		1	\$56.00	\$56.00
155	NUT (WINDSCREEN)	REPLACE	4	\$5.00	\$18.00
				Disc %: 10%	
156	BALANCER ASSY	Replace	1	\$229.00	\$206.10
				Disc %: 10%	
157	BEARING 6204 (NSK)	Replace	1	\$14.00	\$12.60
				Disc %: 10%	
158	BODY FRONT UNDER 1	Replace	1	\$38.00	\$34.20
				Disc %: 10%	
159	BOLT CONNECTING ROD	Replace	6	\$4.00	\$21.60
				Disc %: 10%	
160	CLIP COVER (PLASTIC)	Replace	2	\$6.00	\$10.80
				Disc %: 10%	
161	COVER LIGHT BOX V56N	Replace	1	\$78.00	\$70.20
				Disc %: 10%	
162	GROMMET	Replace	2	\$6.00	\$10.80
				Disc %: 10%	
163	LEG SHIELD 1	Replace	1	\$45.00	\$40.50
				Disc %: 10%	
164	NUT	Replace	6	\$6.00	\$32.40
				Disc %: 10%	
165	BEARING 6002-2NS (NACHI)	Replace	1	\$13.00	\$11.70
				Disc %: 10%	
166	COOLANT (MOBIL) ANTIFREEZE	Replace	2	\$12.00	\$21.60
				Disc %: 10%	
SUB TOTAL					\$10,901.27
GST @ 7 %					\$763.09
GRAND TOTAL (SGD)					\$11,664.36

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND

bizSAFE₃



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-20-028000

Date of Request: 17/02/2020

Your Ref No:

Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 17/02/2020
Enquiry By Hasrianah Binte Hassan
TP Vehicle No. GBF2488H
Accident Date 09/02/2020

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBF2488H	India International Insurance Pte Ltd	17/08/2019-16/08/2020	63476100

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-20-028000
Date of Request: 17/02/2020

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 17/02/2020
Enquiry By Hasrianah Binte Hassan
TP Vehicle No. GBF2488H
Accident Date 09/02/2020

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque