	*			
FASTE	ECH AUT	O PTE LTD		
1 KAKI BUKIT AVENUE 6				Int Authorial
#01-46/48/50				ALLK
SINGAPORE 417883				1/2 n 7500
				75977
	E NO: GB	A 6543		1 2005.
QTY		PARTICULAR		
1 PCS		TAILGATE 2149.10	, , , , , , ,	Bodly DD \$3410.10
1 PCS		TAILGATE REAR LOGO		\$2,419.10
1 PCS		TAILGATE 'TOYOTA' STICKER		400.10
1 PCS		TAILGATE HIACE STICKER		400.00
1 PCS		TAILGATE GLASS OUTER SEAL		N 7 \$60.35 ★ 888.10 ★
1 PCS		TAILGATE GLASS INNER DAM RUBBER		ser \$55.00
1 PCS		TAILGATE INNER LOCK		80/Jm \$395.60
1 PCS		TAILGATE INNER LOCK ACTUATOR		Shirth \$388.20
1 PCS		TAILGATE LOCK STRICKER		イイ \$60.80 火
1 PCS		TAILGATE WEATHERSRTRIP	,	1~1 \$395.10
1 PCS		TAILGATE OUTER GARNISH		11 \$322.50 X
1 PCS		TAILGATE INNER TRIM BOARD		19 \$480.00,X
1 SET 2 PCS		TAILGATE INNER TRIM BOARD CLIPS		11 \$50.00 €
2 PCS		TAILGATE DAMPERS @\$299.10		1 1 \$598.20 X
2 PCS		TAILLAMPS @\$388.50		scalcra \$777.00_
2 PCS		TAILLAMP LOWER GARNISHS@169.30		3/11/w \$338.60 ipc
1 PCS		TAILLAMP LOWER PANELS @\$399.40		0/5100 \$788.80 IPC
1 PCS		TAILLAMP MAIN RAIL PILLAR PANEL N/S		\$489.60 X
1 SET		REAR BUMPER		0-5 \$681.10
2 PCS		REAR BUMPER CLIPS		\$50.00
4 PCS		REAR BUMPER SIDE BRACKETS @\$115.00	Ce	\$230.00
1 PCS		REAR BUMPER LOWER BRACKETS @\$85.00 REAR BUMPER BEAM	2244-88	340.00
1 PCS		REAR EXHAUST		NS \$197.30 ≪
2 PCS			1	\$971.00
1 PCS		REAR EXHAUST MOUNTINGS @\$35.00 REAR END PANEL OUTER		\$70.00 \$
1 PCS		DEAD ENG THE	- K	30.500 \$788.10
1 PCS		REAR END PANEL INNER REAR END PANEL TOP STEEL PLATE		30.500 \$1,245.10
1 PCS		REAR FLOOR PANEL		\$299.50
1 PCS		REAR FLOOR PANEL TOP board	Marings Marin Color	\$1,280.10 ✓
1 PCS		REAR SPARE TYRE BRACKET		SUC \$850.10 X
1 PCS		REAR FENDER 3 (^	3 (\$399.10)
1 PCS		REAR WINDSCREEN	10034	30.60/Jul \$1,419.70
		The second secon	50%	\$1,015.70
		S.NETT		\$17,676.85
1 SET		REAR BUMPER REVERSE SENSOR		a hatel and
1 PCS		TAILGATE 70KM/H STICKER	e kan de dage i i i i i i i i i i i i i i i i i i i	\$280.00 200
1 PCS		REAR LICENECE PLATE	**	AU \$20.00 /0
1 PCS		REAR WINDSCREEN SEALANT		+=0.00 /-
		and the second s	with this is a second	ner \$50.00 HD

1 SET 1 PCS

REAR REVERSE CAMERA REAR END PANEL SEALANT

11 \$480.00 📉 M \$50.00.

LABOUR CHRAGES:

TO CHECK WIRING

TO DISMANTLE & REPLACING REVERSE SENSOR

TO DISMANTLE & REFIX REAR EXHAUST

TO DISMANTLE & REFIX REAR WINDSCREEN

TO DISMANTLE & REFIX TAILGATE MECHANISM

TO DISMENTLE & REFIX FRONT UNDERCARRIAGE

TO SPRAY RUST PROOFING

TO MOUNT VEHICLE ON CAR O-LINER

LABOUR FOR PANEL BEATING & REPLACING PARTS

TO PUTTY & SPRAY PAINTING

\$50.00 30 \$80.00 \$100.00 60 \$150.00/00 \$150.00 60 \$180.00 × \$200.00/00 \$380.00 🗴 \$2,200.00/20,7

\$1,800.00 900 TOTAL \$23,866.85

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-9773.4 502 P-486.70 S.N-300.00 L-2500.00 L-2500.00