

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Due 2/3/20
1pm 2/3/2020
Smey & repair



GST REG. NO : M2 - 0020081 - X

20 FEB 2020

ESTIMATE

Estimate No. : b1 54539	Page No. : 1 of 5
Date Estimated : 20/02/2020	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Ong Chuan Wei (Wang QuanWei) 122A Sengkang East Way #15-43 Singapore 541122	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV7771A	WBA2F12030V312498	26/02/2016	218iA/2	0

DESCRIPTION	VALUE
Replace front right side fender include remove attachment etc include repair on accident damage area	1700 2,550.00
Spray painting right front door, right front side fender and right lower side skirting	2261.7 2,513.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451 531.00
To replace tyre and wheel rim including balancing. (1x). right front	80 94.00
To carry out body cavity preservation. (Per panel).	100 118.00
To conduct checks on all doors and bootlid central locking system for proper function.	150. 177.00
Sundries.	? 150.00
Total Labour 1:	6,133.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM M DOUBLE SPOKE 461 7.5X18 - <i>Ant.</i>	1	1,024.65	1,024.65
FRT RH FENDER - <i>BMC</i>	1	597.25	597.25
SIDE PANEL BRACKET FRT RH 3 <i>X</i>	1	35.10	35.10
FRT RH 2 SIDE PANEL BRACKET <i>X</i>	1	35.10	35.10
FRT RH 2 SIDE PANEL BRACKET <i>X</i>	1	35.10	35.10
EXPANDING RIVET <i>SAC</i>	10	0.50	5.00
BUMPER RIVET	8	0.50	4.00
EMBLEM (M) - <i>NBC</i>	1	82.35	82.35
RIVET	6	0.50	3.00
COVER WHEEL HOUSING FRT RH ?	1	79.75	79.75
FRT RH WHEEL ARCH COVER FRT SECTION ?	1	105.40	105.40
RH SILL STRIP PRIMED (M) ?	1	334.45	334.45



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 54539	Page No.	: 2 of 5
Date Estimated	: 20/02/2020		
Prepared By	: Chua Kee Sin		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV7771A	WBA2F12030V312498	26/02/2016	218iA/2	0

Total Parts : 2,341.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date&Time _____ Excess S\$ _____
 Surveyor's Name Guo Qiang Sign _____
 Surveyor's Tel 82880282 Authorised Yes / No _____
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
 Surveyor's E-mail GuoQiang@lkkauto.com
 No. of Working Days Recommend 5

before paint photos.

Labour 1	:	6,133.00
Parts	:	2,341.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	593.19
Grand Total	:	9,067.34

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**