

GST REG. NO : M2 - 0020081 - X

20 FEB 2020

ESTIMATE

Estimate No. : b1 54539 Page No. : 1 of 5
 Date Estimated : 20/02/2020
 Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
 Ong Chuan Wei (Wang QuanWei)
 122A Sengkang East Way
 #15-43
 Singapore 541122

- ACCOUNT - 40000
 Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFV7771A	WBA2F12030V312498	26/02/2016	218iA/2	0

DESCRIPTION	VALUE
Replace front right side fender include remove attachment etc include repair on accident damage area	1700 / 2,550.00
Spray painting right front door, right front side fender and right lower side skirting	2261.7 / 2,513.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451 / 531.00
To replace tyre and wheel rim including balancing. (1x). right front	80 / 94.00
To carry out body cavity preservation. (Per panel).	100 / 118.00
To conduct checks on all doors and bootlid central locking system for proper function.	150 / 177.00
Sundries.	7 / 150.00

Total Labour 1: **6,133.00**

supp Hexagon Screw with Nut ✓ NBL

DESCRIPTION

ALLOY RIM M DOUBLE SPOKE 461 7.5X18	1	1,024.65	1,024.65
FRT RH FENDER	1	597.25	597.25
SIDE PANEL BRACKET FRT RH 3	1	35.10	35.10
FRT RH 2 SIDE PANEL BRACKET	1	35.10	35.10
FRT RH 2 SIDE PANEL BRACKET	1	35.10	35.10
EXPANDING RIVET	10	0.50	5.00
BUMPER RIVET	8	0.50	4.00
EMBLEM (M)	1	82.35	82.35
RIVET	6	0.50	3.00
COVER WHEEL HOUSING FRT RH	1	79.75	79.75
FRT RH WHEEL ARCH COVER FRT SECTION	1	105.40	105.40
RH SILL STRIP PRIMED (M)	1	334.45	334.45

QTY	PRIC	VALUE
1	6.85	6.85
1	1,024.65	1,024.65
1	597.25	597.25
1	35.10	35.10
1	35.10	35.10
1	35.10	35.10
10	0.50	5.00
8	0.50	4.00
1	82.35	82.35
6	0.50	3.00
1	79.75	79.75
1	105.40	105.40
1	334.45	334.45

supp supporting ledge RH ✓ DMN.

1 18.95 18.95