



南方摩哆

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

19th February 2020

AXA Insurance Singapore Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore (068811)

Dear Sirs,

RE: Cost of repair to Yamaha X-1R 200 – FBD7658L

1pc of Front Spork Rim ? x R	S\$	250.00
1pc of Front Fork Complete repair x		225.00
1pc of Meter Complete ca		290.00
1pc of Handle Bar ? x SVC		65.00
1pc of Brake Lever sca		20.00
1pc of Handle Grip sca		20.00
1pc of Mirror bro		45.00
1pc of Exhaust Pipe bro		850.00
1pc of Rear Footrest Bracket RH bro		75.00
1pc of Body Cover Complete ca		580.00
1pc of Front Footrest bt		48.00
1pc of Gear Lever bt		35.00
1pc of Brake Lever x repainted		20.00
1pc of Magento Cover sca		145.00
1pc of Front Side Light LH sca		55.00
1pc of Head Lamp Complete ? x SVC		225.00
1pc of Rear Footrest bro		45.00
1pc of Throttle Cable bt		55.00
1pc of Steering Corn na cm		75.00

Rasul
Hp 90010068

4 days

4/8

26/02/2020

@ 1700

Resy after repair

	2338	3,123.00
Less 10%	10%	312.30
	2104.20	

Nett	2,810.70
Transport	30.00
Magneto Gasket na	12.00
Engine Oil na	20.00
IU sca	165.00
GIVI E33 Box sca	140.00
Number Plate sca	15.00
Alignment Front Body	250.00
Labor	250.00

782

200

200

2104.20

782.00

2886.20

20%

2308.96

L/S - 2300.00

AXA MANDATE - \$ 2,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours Faithfully,
Southern Motor