

Mon 02/03 @ 10am
S&R

SMR90344

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 FEB 2020

ESTIMATE

Estimate No. : b1 54540
Date Estimated : 20/02/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Cheong Ing Hun
1 Fort Road
#10-02 One Fort

Singapore 439069

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR9034U	WBA5F32080FH74738	31/01/2020	320i	0

DESCRIPTION

To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident

1700
850 VALUE
2,125.00

To respray rear bumper and tail panel

1603 ✓ 1,781.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

231 ✓ 271.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 ✓ 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 ✓ 177.00

Sundries. New

80.00

Total Labour 1: 4,611.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER / BT	1	479.65	479.65
ADAPTER	1	50.20	50.20
REAR BUMPER LH TRIM PANEL (LUXURY) / CRA	1	77.20	77.20
REAR BUMPER LH SIDE GUIDE	1	58.25	58.25
REAR BUMPER RH SIDE GUIDE	1	58.25	58.25
REAR BUMPER LH TRIM PANEL REAR TOP	1	95.35	95.35
REAR BUMPER LH BOTTOM TRIM PANEL (L) / BT	1	96.00	96.00
REAR BUMPER PANEL PRIMED (BASIS PDC) / CRA	1	1,274.95	1,274.95
SET MOUNTING PDC/PMA SENSOR REAR	1	69.35	69.35
EXPANDING RIVET D=8MM / MBL	15	1.10	16.50
REAR LH REAR REFLECTOR	1	38.85	38.85
DECOUPLING RING	1	5.10	5.10
ULTRASONIC SENSOR MINERAL WHITE WA9	1	381.90	381.90
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 54540
Date Estimated : 20/02/2020
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR9034U	WBA5F32080FH74738	31/01/2020	320i	0

Total Parts : 2,754.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 02/3/2020 Excess S\$ _____
Surveyor's Name Eugene Qiao Sign _____
Surveyor's Tel 82880282 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend 3

before paint photos.



Labour 1	:	4,611.00
Parts	:	2,754.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	515.59
Grand Total	:	<u>7,881.19</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 54540**
Date Estimated : **20/02/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Cheong Ing Hun
1 Fort Road
#10-02 One Fort

Singapore 439069

- ACCOUNT - 121

AIIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR9034U	WBA5F32080FH747	31/01/2020	320i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To pull, straighten, make good left trunk floor panel and knock out dented area caused by the accident	425.00	0.00	425.00
# To respray trunk floor panel.	531.00	0.00	531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	956.00
Total Parts :	
Total Labour & Parts :	956.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54540**
Date Estimated : **20/02/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -

Cheong Ing Hun
1 Fort Road
#10-02 One Fort

Singapore 439069

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR9034U	WBA5F32080FH747	31/01/2020	320i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to make good tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00	0.00	1,700.00
To respray rear bumper and tail end panel.	1,603.00	0.00	1,603.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	231.00	0.00	231.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0.00	150.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00
Sundries.	80.00	0.00	80.00
# To pull, straighten, make good left trunk floor panel and knock out dented area caused by the accident	425.00	0.00	425.00
# To respray trunk floor panel.	531.00	0.00	531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	479.65	1.00	0.00	479.65
REAR BUMPER LH TRIM PANEL (LUXURY)	77.20	1.00	0.00	77.20
REAR BUMPER LH TRIM PANEL REAR TOP	95.35	1.00	0.00	95.35
REAR BUMPER LH BOTTOM TRIM PANEL (L	96.00	1.00	0.00	96.00
REAR BUMPER PANEL PRIMED (BASIS PDC	1,274.95	1.00	0.00	1,274.95
EXPANDING RIVET D=8MM	1.10	15.00	0.00	16.50
REAR LH REAR REFLECTOR	38.85	1.00	0.00	38.85

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



Final Report

Total Labour :	4,870.00
Total Parts :	2,078.50
Total Labour & Parts :	6,948.50
GST @7%:	486.40
<u>Grand Total :</u>	<u>7,434.90</u>

CAR RENTAL = \$214(2 DAYS).
LOSS OF USE = \$120 X 1 DAY
GIA SEARCH FEE = \$2.

GuoQiang
LKR - 18/3/20 3+1