

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 2981702/20

Your Ref: \_\_\_\_\_

Date: 21st FEB 2020

The Claim's Manager  
Motor Claims Dept.  
INDIA INTERNATIONAL INSURANCE PTE. LTD  
64, Cecil Street, #05-00, IOB Bldg.  
Singapore 049711

Name Of Insured : Mr Moi Jin Kun  
Date Of Accident : 11/02/2020 (19:10hrs)  
Policy Number : D18MPC0002103\_01

Cost of repair to PERODUA VIVA ELITE EZ 1.0 (A) 5dr - SJU 1704 S

To supply tail gate door, emblems, rear windscreen glass inner seal, damper, sealant, trim board clips, rear bumper, side bracket, clips & necessary parts.

To remove & refix rear windscreen glass, trim board cover, wiper motor, inner lock, hinge, shock absorber, third brake light & necessary parts, including wiring check up for affected wiring system.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear end panel & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected parts.

Lump Sum Repair : \$ 2,100.00

Less Excess : \$ 600.00

Balance : \$ 1,500.00

=====

Dollars : One Thousand And Five Hundred Only.

**HUP MOTOR TRADING & SERVICE**

Encl : Discharge Voucher