

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 027/IC/TCAC/CCR/2020
DATE : 20-FEB-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MISS CHOW SOOK MUN ELIZABETH
ADDRESS : BLK 684D CHOA CHU KANG CRESCENT
#09-360
S(684684)
TELEPHONE NO : 81888032

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100473529-03
VEHICLE NO : SLD9152Y
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2274537A
CHASSIS NO : SJNFEAJ11U1653595
MILEAGE : 58880 KM
DATE IN : 20/02/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 19/02/2020

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLD9152Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01W	**COMPLETE WAXING OF VEHICLE	71.00	.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00 ✓
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
5	ZZ/001	REPLACE REAR BUMPER REPAIR TAILGATE	840.00	780.00 ✓
6	ZZ/002	RESPRAY REAR BUMPER IN 2 COLORS, TAILGATE	1000.00	600.00 ✓
7	ZZ/003	QC, RETUNE & CONSULT CHECK		
8	ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			2186.00	1435.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLD9152Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	REMARKS
1	ORNAMENT-BACK D (SUPP)	90892-4EA0A	94.40	✓	NEC	OK
2	EMBLEM-REAR (SUPP)	90890-4EA0A	64.90	✓	NEC	OK
3	STAY ASSY-REAR(SUPPLEMENTARY)	H5211-4EAMA	141.00	✓	BT	OK
4	STAY ASSY-REAR(SUPPLEMENTARY)	H5210-4EAMA	141.00	✓	BT	OK
5	REAR UPPER PANEL	G9110-4EAMA	482.60			X
6	RIGHT REFLECTOR	26560-JJ90A	61.90			X
7	REINFORCEMENT (SUPP)	H5030-4EAMA	691.50			OK
8	BUMPER RIGHT BRACKET	85220-4EA0A	38.90			X
9	BUMPER LEFT BRACKET	85221-4EA0A	38.90			X
10	ENERGY ABSORBER (SUPP)	85090-4EA0B	141.40			OK
11	BUMPER RIGHT RETAINER	79184-4EA0A	25.70			X
12	BUMPER LEFT RETAINER	79185-4EA0A	25.70			X
13	CLIP (\$1.30 EA X 4)	01553-05933	5.20			OK
14	TOW HOOK COVER	85071-4EA0A	18.80			X
15	REAR BUMPER	85022-4EA0H	796.70			OK
16	LEFT REFLECTOR	26565-JJ90A	61.90			X
17	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140		BR ✓	360.00	OK
SUB TOTAL			2076.10	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			415.22	0.00	0.00	
GRAND TOTAL			1660.88	0.00	360.00	
OVERALL TOTAL			2020.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLD9152Y

NETT ITEM	2076.10
LESS 20.00%)	-415.22
NETT AMOUNT	1660.88

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	360.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	360.00

TOTAL LABOUR CHARGES	1435.00
TOTAL SPARE PARTS CHARGES	2020.88

TOTAL CHARGES	3455.88
ADD 7 % GST	241.91

GRAND TOTAL	3697.79
-------------	---------