

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5002X**AAD2002-134***Not Authorised**Resurvey B4 paint**2424.16*

Vehicle No.:

Chassis No.:

20 FEB 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5002X

VF1ABL15AUC283470

RENAULT

LATITUDE

16.2.2020

AIG

10/7/2017

PART		LIST		
1	BUMPER COVER REAR	\$	<i>Bu/ln</i> 561.70	✓
1	BUMPER LOWER REAR	\$	<i>nd/ln</i> 411.90	✓
1	BUMPER BRACKET CTR REAR	\$	<i>ln</i> 98.10	X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>ln</i> 82.10	X
1	BUMPER RETAINER RH REAR	\$	<i>ln</i> 59.80	X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>ln</i> 80.80	X
1	BUMPER RETAINER LH REAR	\$	<i>ln</i> 54.20	X
1	BUMPER REFLECTOR LH	\$	<i>ln</i> 16.60	X
1	BUMPER BEAM REAR	\$	<i>R</i> 547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50	} X
1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90	
1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80	
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>ln</i> 404.56	
1	TAILLAMP RH	\$	<i>ln</i> 313.10	
1	TAILLAMP LH	\$	<i>ln</i> 401.40	
1	BOOT REAR	\$	<i>R</i> 1,677.20	
1	BOOT FINISHER	\$	<i>ln</i> 344.70	
1	BOOT WHEATERSTRIP	\$	<i>ln</i> 178.20	
1	BOOT REFLECTOR LAMP LH	\$	<i>ln</i> 277.70	
1	BOOT REFLECTOR LAMP RH	\$	<i>ln</i> 277.70	
1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40	
1	BOOT BADGE	\$	<i>nn</i> 95.80	
1	EXHAUST CAP REAR	\$	<i>ln</i> 125.40	
TOTAL		\$	7,052.36	
10%		\$	705.24	
		\$	6,347.12	

Trans-cab Auto Services Pte Ltd**AAD2002-134**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5002X**Special Nett**

1SET PARKING AID	\$	Shot 700.00	400.00
1SET REAR BUMPER CLIP	\$	nn 66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00	X
1SET BUMPER LOWER REAR RIVET	\$	nn 22.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn 66.00	✓
1 BOOT STICKER "Trans-cab"	\$	nn 30.00	X
1 BOOT STICKER "6555-3333"	\$	nn 30.00	X
1SET BOOT FINISHER CLIP	\$	nn 24.20	X
1 TAILLAMP CLIP LH	\$	nn 5.00	X
1 TAILLAMP CLIP RH	\$	nn 5.00	X
1 Rear Bumper Protector	\$	nn 100.00	X
TOTAL	\$	1,141.20	
TOTAL PARTS	\$	7,488.32	

LABOUR

To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	↪ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5002X**AAD2002-134**

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2201</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
TOTAL	\$	14,170.00	
Over All Total	\$	21,658.32	

PART BY PART (REPAIR DAY)~~**20 DAYS**~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: