



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20002997/Fda3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-04-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8496P	Veh. Inspected	SMP 7237A	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001100MFSH/1	Excess (\$)	0.00	
Assign From	KAREN	Assign Date	20/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GK82100208	Colour	GREY	
Odometer	32858	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2020	Inspection Date	20/02/2020	
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		