FASTECH AUTO PTE LTD

BLK1 KAKI BUKIT AVE 6

#01-46,48,50 AUTOBAY

SINGAPORE 417883

VEHICLE NO:HJA 3132

QTY

PARTICULAR

VEHICLE NO:	HJA 3132			
QTY	PARTICULAR		ile cun	\$922.10
1 PCS	FRONT BUMPER		110 24)	
1 PCS	FRONT BUMPER SIDE RETAINER N/S			\$66.50
1 SET	FORNT BUMPER CLIPS		ALC SOR	
1 PCS	HEADLAMP N/S			\$788.10
1 PCS	FRONT FENDER N/S		17	\$615.00
1 PCS	FRONT DOOR N/S			\$1,450.00
1 PCS	FRONT DOOR INNER RUBBER N/S		17	\$288.00
1 PCS	FRONT DOOR INNER LOCK N/S		11	\$399.00
2 PCS	FRONT DOOR HINGES @\$105.00		11	\$210.00
1 PCS	REAR DOOR N/S			\$1,350.00
1 PCS	REAR DOOR INNER RUBBER N/S		11	\$295.00
1 PCS	REAR DOOR INNER LOCK N/S		11	\$395.00 🗶
2 PCS	REAR DOOR HINGES @\$105.00		,11	\$210.00 \
1 PCS	REAR DOOR INNER TRIM BORAD N/S		Del70-2	\$688.10
1 PCS	REAR DOOR GLASS REGULATOR N/S		Sel	\$299.10
1 PCS	REAR DOOR GLASS REGULATOR MOTOR N/S		In	\$450.00
1 PCS	REAR BUNNER	7 (17)	pe	\$971.00
1 PCS	REAR BUMPER SIDE RETAINER N/S	000/	11	\$66.50 🗶
1 SET	REAR BUMPER CLIPS		iner	\$50.00
1 PCS	FRONT FOG LAMP N/S		NA	\$388.00 🗴
1 PCS	CENTRE PILLAR N/S		r	\$645.10
			\$10,596.50	
	S. NETT			
1 SET	FRONT DOOR STICKER N/S		17	\$280.00
1 PCS	FRONT DOOR VISOR N/S		11	\$100.00
1 SET	REAR DOOR STICKER N/S			\$280.00 /
1 PCS	REAR DOOR VISOR N/S		ne	\$100.00 6
	REAR SPORT RIM N/S		1	\$650.00
1 PCS	REAR SPORT KINI N/S		, _	\$030.00
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 2
	TO SPRAY RUST PROOFING			\$100.00 3
	TO CONDUCT WHEEL ALIGNMENT			\$120.00 6
	TO TRANSFER BOTH N/S DOOR MECHANISM			\$180.00 6
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,080.00	
	TO PUTTY & SPRAY PAINTING			
		Consultants hence not	TOTAL	$^{\$1,500.00}_{15,066.50}6$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7.368.4