

22/03/2002

ASS. REC. BY:

REF: CS/C11 2000999/ Kt f3 12
Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Adeline Chng of C11 Date/Time: 21.2.2020 2.54p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YQ 9191 L Insured: GBD 4370Rat Workshop m/s Kum Chew Motor Workshop Tel: 645 3656of 160 Sin Ming Dr #05-08Policy No: DMCKN15443419044 Claim No: SNM 200 200922 C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/2/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 21.2.2020 3.2p.mPerson Contacted: ndm lim

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>YQ 9191 L - X</u>
	<u>GBD 4370R - X</u>
<u>28/2</u>	<u>L1 Lp & 5 food email (fld: 3681.13, 390%)</u>

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YG 9191L

Yr Regn:

06.1.9

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Hino 300

c.c

4009

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

9632

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH14UCV31H00K03088

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod:

N/S / Rlm / STD A/Rlm or

Tyre Size:

F:

700 R16 X10

R:

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

9

mm

L/Bal.

9

mm

L/Bal.

9

9

mm

D.O.A.

19/2/20

D.O.I.

21/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$

TP

5700/-

Days Of Repair:

4

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Fees

Others

TOTAL

220

Nivitha (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Friday, 21 February 2020 2:54 PM
To: 'assignments'
Cc: kumchew1; Claims Dept of CTI
Subject: RE: OUR REF: SNM20D200922/GBD4370K/ADELINE - RE : ACCIDENT INVOLVING YQ 9191 L & GBD 4370 K ON 19/2/2020.

Without Prejudice

Dear LKK

Please refer to below email and liaise with third party workshop.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6178 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: kumchew1 [mailto:kumchew1@singnet.com.sg]
Sent: Friday, 21 February 2020 2:21 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200922/GBD4370K/ADELINE - RE : ACCIDENT INVOLVING YQ 9191 L & GBD 4370 K ON 19/2/2020.

Hi Ms Adeline,

Kindly arrange Mr Kenneth Kong to pre-repair inspection our insured vehicle.

Thanks & Best Regards,
Mdm Lim

-----Original Message-----

From: Adeline Chng [mailto:adeline.chng@sg.cntaiping.com]
Sent: Thursday, February 20, 2020 6:01 PM
To: Claims Dept of CTI; kumchew1@singnet.com.sg
Subject: RE: OUR REF: SNM20D200922/GBD4370K/ADELINE - RE : ACCIDENT INVOLVING YQ 9191 L & GBD 4370 K ON 19/2/2020.

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached PRS letter for your next action.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6178 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: Claims Dept of CTI
Sent: Thursday, 20 February 2020 5:34 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>; kumchew1@singnet.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D200922/GBD4370K/ADELINE - RE : ACCIDENT INVOLVING YQ 9191 L & GBD 4370 K ON 19/2/2020.

Dear Adeline,

Please conduct PRS for YQ9191L.

Note : officer in charge – Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: kumchew1 <kumchew1@singnet.com.sg>
Sent: Thursday, February 20, 2020 3:05 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: FW: RE : ACCIDENT INVOLVING YQ 9191 L & GBD 4370 K ON 19/2/2020.

Dear Sir/Madam,

We are acting on behalf of M/s Poh Seng Engineering, the owner of YQ 9191 L in the above matter.

Kindly arrange for pre-repair with the following details;

Venue : Kum Chew Motor Workshop
: 160, Sin Ming Drive #05-08
: Sin Ming Autocity
: Singapore 575722.

Contact No. : 64536256

Thanks & Best Regards,

Mdm Lim

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08

SIN MING AUTOCITY, SINGAPORE 575722.

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3, ANSON ROAD #16-00

SPRINGLEAF TOWER, SINGAPORE 079909.

claimsdept@sg.cntaiping.com

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES004763

Date : 21/02/2020

Vehicle Num. : YQ 9191 L

Make/Model : HINO XZU710R-2019

Chassis/Eng# : JHHUCV3H00K030978

Accident Date : 19/02/2020

Claim No. :

Reference : KC/TP9191/2002-07

Policy No. :

*Not Authorized**Resurvey B4 point**4-5 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1. 1 PC
2. 1 PC
3. 1 PC
4. 1 PC
5. 1 PC
6. 2 PCS
7. 1 PC
8. 1 PC
9. 2 PCS
10. 8 PCS
11. 1 PC
12. 2 PCS
13. 1 PC
14. 1 PC
15. 1 PC
16. 1 PC
17. 1 PC

LIST ITEMS :

FRT DOOR - L/H *RA*
 FRT DOOR SIGNAL LAMP - L/H *RA*
 FRT DOOR STEP GARNISH - LH *RA*
 FRT DOOR STICKER '616' - L/H *RA*
 FRT DOOR 'EURO 6' STICKER - L/H *RA*
 FRT DOOR HINGE - L/H *RA*
 FRT BUMPER *Bul/Car*
 FRT BUMPER REINFORCEMENT *?*
 FRT BUMPER BRACKET *RA*
 FRT BUMPER CLIPS *X*
 FRT FOG LAMP - LH *?*
 FRT HEADLAMP *?* *car/mg car*
 FRT GRILLE *?*
 FRT GRILLE EMBLEM *?*
 FRT 'HINO' STICKER *RA*
 FRT '300' STICKER *RA*
 FRT L/H MIRROR BRACKET *RA*

List TotalS\$:

10.00% Discount S\$:

LABOUR :

TO PULL & KNOCK ON FRT ACCIDENT PORTION & CHANGE THE PARTS.

500
850.00

CONTINUE / ...

LKK Auto Consultants (Pte) Ltd. hereby notify the Repairer of the following:

- To resolve a claim after survey printing
- To display survey print, upon survey
- Parts provided on "as is" basis
- Third party liability on "as is" basis
- No claim for consequential damage
- Supplier's responsibility for damaged and
- We are not responsible for any damage to the vehicle

Acknowledged by:

Signature:

Date:

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3, ANSON ROAD #16-00
 SPRINGLEAF TOWER, SINGAPORE 079909.
 claimsdept@sg.cntaiping.com

Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

Estimate : ES004763

Date : 21/02/2020
 Vehicle Num. : YQ 9191 L
 Make/Model : HINO XZU710R-2019
 Chassis/Eng# : JHHUCV3H00K030978
 Accident Date : 19/02/2020
 Claim No. :
 Reference : KC/TP9191/2002-07
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO SPRAY & PAINT ON FRT ACCIDENT PORTION.		550/ 950.00
		TO CHECK WIRING FUNCTIONS.		20/ 85.00
		TO ANTI-RUST AFFECTED AREAS.		30/ 150.00
		Labour Total S\$:		2,035.00

SingDollars : Two Thousand Thirty-Five Only

Total S\$: 2,035.00

KUM CHEW MOTOR WORKSHOP

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3, ANSON ROAD #16-00
 SPRINGLEAF TOWER, SINGAPORE 079909.
 claimsdept@sg.cntaiping.com

Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

Estimate : ES004763

Date : 21/02/2020
 Vehicle Num. : YQ 9191 L
 Make/Model : HINO XZU710R-2019
 Chassis/Eng# : JHHUCV3H00K030978
 Accident Date : 19/02/2020
 Claim No. :
 Reference : KC/TP9191/2002-07
 Policy No. :

Not Authorized
L1 Eng 85700p
Recovery After Paint

4 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | S/N | Quantity | Particular |
|-----|----------|---------------------------------|
| 1. | 1 PC | FRT DOOR - L/H |
| 2. | 1 PC | FRT DOOR SIGNAL LAMP - L/H |
| 3. | 1 PC | FRT DOOR STEP GARNISH - LH |
| 4. | 1 PC | FRT DOOR STICKER '616' - L/H |
| 5. | 1 PC | FRT DOOR 'EURO 6' STICKER - L/H |
| 6. | 2 PCS | FRT DOOR HINGE - L/H |
| 7. | 1 PC | FRT BUMPER |
| 8. | 2 PCS | FRT BUMPER BRACKET |
| 9. | 8 PCS | FRT BUMPER CLIPS |
| 10. | 1 PC | FRT FOG LAMP - LH |
| 11. | 2 PCS | FRT HEADLAMP |
| 12. | 1 PC | FRT GRILLE |
| 13. | 1 PC | FRT GRILLE EMBLEM |
| 14. | 1 PC | FRT 'HINO' STICKER |
| 15. | 1 PC | FRT '300' STICKER |
| 16. | 1 PC | FRT L/H MIRROR BRACKET |
| 17. | 1 PC | FRT FENDER (CORNER) - RH |

LIST ITEMS :

List TotalS\$:
 10.00% Discount S\$:

LABOUR :

RH	1,605.08	✓
mi	97.39	✓
nd/l	488.28	✓
na	163.54	✓
na	114.01	✓
99.87	199.74	X
873.10		✓
369.50	739.00	X
16.70	133.60	X
my cm	318.65	✓
my cm	1,721.64	✓
my cm	684.15	✓
na	109.50	✓
na	82.53	✓
na	86.58	✓
R	270.47	X
my cm	465.11	✓
8,162.37		
816.24		
7,346.13		

To: MR KENNETH
From: Kum Chew
21/2/20

LKK Auto Consultants hereby notify the Repairer of the following: CONTINUE / ...

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
Tel No. : 64536256/64563715 Fax No. : 64557754
E-Mail : kumchew1@singnet.com.sg
GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3, ANSON ROAD #16-00
SPRINGLEAF TOWER, SINGAPORE 079909.
claimsdept@sg.cntaiping.com
Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES004763

Date : 21/02/2020
Vehicle Num. : YQ 9191 L
Make/Model : HINO XZU710R-2019
Chassis/Eng# : JHHUCV3H00K030978
Accident Date : 19/02/2020
Claim No. :
Reference : KC/TP9191/2002-07
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PULL & KNOCK ON FRT ACCIDENT PORTION & CHANGE ABOVE PARTS.		850.00 500l
		TO SPRAY & PAINT ON FRT ACCIDENT PORTION.		950.00 550l
		TO CHECK WIRING FUNCTIONS.		85.00 20l
		TO ANTI-RUST AFFECTED AREAS.		150.00 30l
		Labour Total S\$:		2,035.00

SingDollars : Nine Thousand Three Hundred Eighty-One & Cents Thirteen Only

Total S\$: 9,381.13

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002999/KTF3N2
Date: 04/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN15443419044
Claimant Vehicle No: YQ9191L Insured Vehicle No: GBD4370K
Date of Loss: 19/02/2020 Nature of Claim: TP Claim No: SNM20D200922C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ9191L Engine No: N04CVV10717
Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M) Chassis No: JHHUCV3H00K030978
Reg. Date: 20/06/2019 (Man. Year: 2019) Odometer: 9632 km
Colour: White
Engine Capacity: 4009 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 700R16X10 Rear Tyre Size: 700R16X10 (D)
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9/9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,346.13	6,016.08	1,330.05	18.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,035.00	1,100.00	935.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,381.13	7,116.08	2,265.05	24.14
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	9,381.13	5,700.00	3,681.13	39.24
+ GST 7.00/7.00% (S\$)	656.68	399.00	257.68	39.24
Nett Amount (S\$)	10,037.81	6,099.00	3,938.81	39.24

INSPECTION

Date of Assignment: 21/02/2020
Date Inspected: 21/02/2020 Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ)
160 Sin Ming Drive, #05-08 Sin Ming Autocity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Mar 2020)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ9191L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR-L/H	Bent	1,605.08 FL	*1,605.08 FL
2	1		*FRT DOOR SIGNAL LAMP-L/H	Missing	97.39 FL	*97.39 FL
3	1		*FRT DOOR STEP GARNISH-LH	Dented/Cut	488.28 FL	*380.00 FL
4	1		*FRT DOOR STICKER 616-L/H	Necessary	163.54 FL	*163.54 FL
5	1		*FRT DOOR EURO 6 STICKER-L/H	Necessary	114.01 FL	*114.01 FL
6	2		*FRT DOOR HINGE-L/H	Repair	199.74 FL	*- FL
7	1		*FRT BUMPER	Buckled/Cracked	873.10 FL	*873.10 FL
8	2		*FRT BUMPER BRACKET	Repair	739.00 FL	*- FL
9	8		*FRT BUMPER CLIPS	Not Necessary	133.60 FL	*- FL
10	1		*FRT FOG LAMP-LH	Mtg Cracked	318.65 FL	*291.90 FL
11	2		*FRT HEADLAMP	Mtg Cracked	1,721.64 FL	*1,721.64 FL
12	1		*FRT GRILLE	Mtg Cracked	684.15 FL	*684.15 FL
13	1		*FRT GRILLE EMBLEM	Necessary	109.50 FL	*109.50 FL
14	1		*FRT HINO STICKER	Necessary	82.53 FL	*82.53 FL
15	1		*FRT 300 STICKER	Necessary	96.58 FL	*96.58 FL
16	1		*FRT L/H MIRROR BRACKET	Repair	270.47 FL	*- FL
17	1		*FRT FENDER (CORNER)-RH	Mtg Cracked	465.11 FL	*465.11 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,162.37	6,684.53
- List Item Discount on L Items 10.00/10.00% (S\$)	816.24	668.45
Total Parts (S\$)	7,346.13	6,016.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL & KNOCK ON FRT ACCIDENT PORTION & CHANGE ABOVE PARTS	New	850.00	500.00
2	TO SPRAY & PAINT ON FRT ACCIDENT PORTION	New	950.00	550.00
3	TO CHECK WIRING FUNCTIONS	New	85.00	20.00
4	TO ANTI-RUST AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			2,035.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >