

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SKOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SIM5536C

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES X <i>MAI</i>	NPN		<i>20</i> 100.00
2	CLIP \$1.20 X 10 X <i>MAI</i>	84953-JA00A	12.00	
3	CLIP \$2.50 X06 X <i>MAI</i>	76847-4EA0A	15.00	
4	REAR FENDER WHEEL ARCH PROTECTOR RH X <i>MAI</i>	93828-4EA0A		541.40
5	REAR DOOR LOWER PROTECTOR RH X <i>MAI</i>	82870-4EA0A	253.50	
6	FRONT DOOR LOWER PROTECTOR RH X <i>MAI</i>	80870-4EA0A	309.70	
SUB TOTAL			590.20	541.40 100.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			118.04	162.42 0.00
GRAND TOTAL			472.16	378.98 100.00
OVERALL TOTAL			951.14	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM5536C

TOTAL LABOUR CHARGES	1930.00
TOTAL SPARE PARTS CHARGES	951.14
GRAND TOTAL	2881.14

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Star (LKK) WML PWL

83228813

24/2/20, 11.15am

2 w dys

P/P

My AL sy

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALISED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0368/2017
DATE : 01-JUL-2017

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR ANDI PADENAN
ADDRESS : BLK 440A FERNVALE LINK
#20-183
S(791440)
TELEPHONE NO : 98399773

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SJW1968L
VEHICLE NO : SLM5536C
MODEL CODE : FRLARBEJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2401862A
CHASSIS NO : SJNFEAJ11U1909514
MILEAGE : 1 KM
DATE IN : 01/07/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 21/05/2017

06/07/20

STW (LAW)

Revised

100/day X 02

= # 200 + 41

= # 214 | -

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM5536C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	240.00
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
3 22/001	REPAIR FRONT & REAR DOOR RH, RENEW DOOR LOWER PROTECTOR, REAR WHEEL ARCH PROTECTOR RH	840.00	280.00
4 22/002	SPRAY PAINT FRONT & REAR DOOR RH	750.00	500.00
TOTAL LABOUR CHARGES		1930.00	1020.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/S/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM5536C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REAR FENDER WHEEL ARCH PROTECTOR RH	93828-4EA0A		541.40	X
2	REAR DOOR LOWER PROTECTOR RH	82870-4EA0A	253.50		X
3	CLIP \$2.50 X06	76847-4EA0A	15.00		X
4	SUNDRIES	NPN			100.00 X
5	CLIP \$1.20 X 10	84953-JA00A	12.00		X
6	FRONT DOOR LOWER PROTECTOR RH	80870-4EA0A	309.70		X
SUB TOTAL			0.00	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	0.00
OVERALL TOTAL			0.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLM5536C

NETT ITEM	0.00
LESS 20.00%)	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	1020.00
TOTAL SPARE PARTS CHARGES	0.00
TOTAL CHARGES	1020.00
ADD 7 % GST	71.40
GRAND TOTAL	1091.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2020		21 Feb 2020 18:41 Edit Adj Rpt	S\$1,020.00 Edit Estimates	S\$1,020.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	ANDI FADENAN, ID: S8372779I		
Vehicle Reg. No.:	SLM5536C	Date of Loss:	21/05/2017 19:00 - :59 [1 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM17D03049	Policy/Cover Note No.:	DMHCSN17197717000
Vehicle Reg. No. (Insured):	SJW1968L	Policy No. (Claimant):	2100506178
		Excess:	S\$0.00
Repairer:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road, 589622 Bukit Timah - Tel: 64601694		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/03/2020]		
Adj Asg. Remarks:	Direct Settlement		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM5536C (SNM17D03049)**
[SJW1968L]

TP
ANDI FADENAN
May 21 2017 7:00PM
[-]
Tan Chong Motor Sales

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/02/20 17:49	General View	Load JPG	✓
2	24/02/20 17:49	General View	Load JPG	✓
3	24/02/20 17:49	General View	Load JPG	✓
4	24/02/20 17:49	General View	Load JPG	✓
5	24/02/20 17:49	General View	Load JPG	✓
6	24/02/20 17:49	General View	Load JPG	✓
7	24/02/20 17:49	General View	Load JPG	✓
8	24/02/20 17:49	General View	Load JPG	✓
9	24/02/20 17:49	General View	Load JPG	✓
10	24/02/20 17:49	General View	Load JPG	✓
11	24/02/20 17:49	General View	Load JPG	✓
12	24/02/20 17:49	General View	Load JPG	✓
13	24/02/20 17:49	General View	Load JPG	✓
14	24/02/20 17:49	Odometer Reading	Load JPG	✓
15	24/02/20 17:49	Chassis Number	Load JPG	✓
16	24/02/20 17:49	General View	Load JPG	✓
17	24/02/20 17:49	General View	Load JPG	✓
18	24/02/20 17:49	General View	Load JPG	✓
19	24/02/20 17:49	General View	Load JPG	✓
20	24/02/20 17:49	General View	Load JPG	✓
21	24/02/20 17:49	General View	Load JPG	✓
22	24/02/20 17:49	General View	Load JPG	✓
23	24/02/20 17:49	General View	Load JPG	✓
24	24/02/20 17:49	General View	Load JPG	✓
25	06/03/20 17:28	Reinspection Photo	Load JPG	✓
26	06/03/20 17:28	Reinspection Photo	Load JPG	✓
27	06/03/20 17:28	Reinspection Photo	Load JPG	✓
28	06/03/20 17:28	Reinspection Photo	Load JPG	✓

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	03/09/19 14:31	Accident Statement	Load HTM	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
Photos/Images			3 per page ▼	✓
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	01/07/17 16:40	Accident Photo	 Load JPG	✓
2	01/07/17 16:40	Accident Photo	 Load JPG	✓
3	01/07/17 16:40	Accident Photo	 Load JPG	✓
4	01/07/17 16:40	Accident Photo	 Load JPG	✓
5	01/07/17 16:40	Accident Photo	 Load JPG	✓
6	01/07/17 16:41	Accident Photo	 Load JPG	✓
7	01/07/17 16:41	Accident Photo	 Load JPG	✓
8	01/07/17 16:41	Accident Photo	 Load JPG	✓
9	01/07/17 16:41	Accident Photo	 Load JPG	✓
10	01/07/17 16:41	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Tan Chong Motor Sales Pte Ltd (Bukit Timah)	Thumbnail	Print
1	01/07/17 16:42	Sketch Plan	 Load TIF	
2	01/07/17 16:42	Sketch Plan #2	 Load TIF	
3	01/07/17 16:42	Sketch Plan #3	 Load TIF	
4	01/07/17 16:42	Sketch Plan #4	 Load TIF	
5	01/07/17 16:42	Sketch Plan #5	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003006/EQD3S2
Date: 20/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.
Policy No: DMHCSN17197717000
Claimant Vehicle No: SLM5536C
Insured Vehicle No: SJW1968L
Date of Loss: 21/05/2017
Nature of Claim: TP
Claim No: SNM17D03049

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM5536C
Make & Model: NISSAN QASHQAI, 1.2 (A)
Reg. Date: 31/03/2017 (Man. Year: 2017)
Colour: Red
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price
Engine No: HRA2401862A
Chassis No: SJNFEAJ11U1909514
Odometer: 47946 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	951.14	0.00	951.14	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,020.00	910.00	47.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,881.14	1,020.00	1,861.14	64.60
+ GST 7.00/7.00% (S\$)	201.68	71.40	130.28	64.60
Nett Amount (S\$)	3,082.82	1,091.40	1,991.42	64.60

INSPECTION

Date of Assignment: 21/02/2020
Date Inspected: 24/02/2020 Inspected At: Tan Chong Motor Sales (HQ)
913 Bukit Timah Road
Singapore 589623
Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM5536C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER WHEEL ARCH PROTECTOR RH	Not Necessary	541.40 FL	*- FL
2	10		*CLIP	Not Necessary	12.00 FN	*- FN
3	6		*CLIP	Not Necessary	15.00 FN	*- FN
4	1		*REAR DOOR LOWER PROTECTOR RH	Not Necessary	253.50 FN	*- FN
5	1		*FRONT DOOR LOWER PROTECTOR RH	Not Necessary	309.70 FN	*- FN
6	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$\$)					1,231.60	0.00
- List Item Discount on L Items 30.00/30.00% (\$\$)					162.42	0.00
- Nett Item Discount on N Items 20.00/20.00% (\$\$)					118.04	0.00
Total Parts (\$\$)					951.14	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	New	240.00	240.00
2	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	New	100.00	0.00
3	REPAIR FRONT & REAR DOOR RH, RENEW DOOR LOWER PROTECTOR, REAR WHEEL ARCH PROTECTOR RH.	New	840.00	280.00
4	SPRAY PAINT FRONT & REAR DOOR RH.	New	750.00	500.00
Gross Labour Cost (S\$)			1,930.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >